

ASS. REC. BY:

REF: ~~CS3/LPC21002885/R1ty3~~

Special Instruction:

Surveyor: RASUL KENNY ASSIGNMENT (Office)

03/02/2022

From (Person): ~~ONG LEE~~ of LPC Date/Time: ~~2/3/2021 5.25 PM~~

Estimated Cost: _____ Bill to: _____

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: YP 972P Insured: GBB 6683Eat Workshop m/s Ngee Ngee Motor Tel: 67775382of Blk K, No. 22 Pandan LoopPolicy No: _____ Claim No: 20/21/21/VC05/024289

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 01 MARCH 2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 03-03-2021 4.0P.MPerson Contacted: JESSIEVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	YP 972P- ☒
	GBB 6683E- ☒

ASS. REC. BY:

REF:

CS3/LPC21002885/RH#3-1

2846

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / W'S / TP RES / OD RES / EVA / INV / MIV

To Inspect Vehicle No: 4P 972Pat Workshop n/s NGEE NGEEof BLK K No. 22, Pandan LoopInsured: LPC

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 52K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 4P 972PYr Regn: 2016 JANType: M.Car / M.Cycle / Bus / Van / Corr / Taxi / Prime Mover /

Truck / Traller or _____

Make: MITSUBISHI CANTER Feb 21ER c.c. 2998Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 132676 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Feb 21ER 10706Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NR / S/Rim / STD A/Rim orTyre Size: F: 195/85R15R: 2 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / XOKO or _____

Front

Rear

R/Bal. 7 mm R/Bal. 7/7 mmL/Bal. 7 mm L/Bal. 7/7 mmD.O.A. 01/03/21 D.O.I. 03/03/21Survey held at NGEE NGEEDes. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair limit - 31K</u>
	<u>ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (4K-5K) / 7 days</u>
	<u>submit prs report lump sum \$2950, 7days</u>
	<u>red:4250;59%</u>

Date/Time, File Pass to?



Prell. Report

Days Of Repair: 7

Date/Time, File Return to?



Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL

Rep. Format: _____

Lump Sum / I.B.F. (\$) _____

Annex A : Assesement / Adjustment on Spare Parts

YP 972 P						
Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
List Items						
1	Front bumper	Buckled	1	\$895.00	25%	\$671.25
2	Front bumper side LH	Slack/distorted	1	\$334.00	25%	\$250.50
3	Front bumper side RH xnn	Slack/distorted	1	\$334.00	25%	\$250.50 X
4	Front bumper bracket @54.60	Bent	1 ✓	\$145.60	25%	\$109.20 54.60
5	Front corner panel garnish LH	Deformed/cut	1	\$382.15	25%	\$286.61
6	Front panel	Repair	1	\$3,046.00	100%	\$0.00
7	Front panel FUSO emblem	Necessary	1	\$152.00	25%	\$114.00 105
8	Front grille assy xnn	Cracked	1	\$959.50	25%	\$719.63 X
9	Front grille badge xnn	Necessary	1	\$57.00	25%	\$42.75 X
10	Front grille "Center" emblem xnn	Necessary	1	\$40.00	25%	\$30.00 X
11	Front LH mirror stay repair	Slack/bent	1	\$428.00	25%	\$321.00 X
12	Front LH mirror (round)	Distorted/cracked	1	\$125.00	25%	\$93.75 60
13	Front LH mirror (square) xnn	Slack/distorted	1	\$145.00	25%	\$108.75 X
14	Front signal lamp LH	Grazed/cracked	1	\$325.50	25%	\$244.13
15	Head lamp LH xnn	Grazed/cracked	1	\$648.00	25%	\$486.00 X
16	Head lamp lower rubber LH xnn	Necessary	1	\$38.00	25%	\$28.50 X
17	Side lamp garnish LH xnn	Grazed/slack	1	\$218.80	25%	\$164.10 X
S/Nett Items						
18	Rear bumper assy c/w bracket	Bent/torn	1	\$1,900.00		\$1,900.00 850
19	Rear number plate	Dented/bent	1	\$38.00		\$38.00 35
20	Rear number plate lamp	Cracked/faulty	1	\$68.00		\$68.00 55
21	Tail gate MITSUBISHI lettering	Not necessary	1	\$150.00		\$0.00
22	Tail lamp assy LH	Serviceable	1	\$275.00		\$0.00
23	Tail lamp bracket LH	Serviceable	1	\$120.00		\$0.00
24	Front number plate	Dented/bent	1	\$38.00		\$38.00 35
Total for Spare Parts :						\$10,862.55 \$5,964.66

Annex B : Adjustment on Labour and Spray Painting

YP 972 P

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)	
1	Anti rust treatment	\$100.00	\$60.00	40
2	To check wiring system & lights	\$200.00	\$100.00	40
3	To respray affected areas	\$1,400.00	\$900.00	600
4	To renew damaged parts, straighten/repair front cross member & aligned all parts	\$1,500.00	\$1,400.00	800
TOTAL FOR LABOUR & SPRAY PAINTING :		\$3,200.00	\$2,460.00	1480

Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$10,862.55	\$5,964.66
TOTAL FOR LABOUR & SPRAY PAINTING :	\$3,200.00	\$2,460.00
TOTAL REPAIR COSTS :	\$14,062.55	\$8,424.66

1254.06

975.00

1480.00

3709.06

20%

2967.24

L/S-\$2,950/7 DAYS

[illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21002885/R1ty3e2-1 Date: 10/02/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 6683E	Veh. Inspected	YP 972P	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024289	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	03/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi canter feb21er	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	FEB21EA10706	Colour	WHITE	
Odometer	132676 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R15	YOKOHAMA	7 mm	
L/H Front Tyre	195/85 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	195/85 R15 (D)	YOKOHAMA	7/7 mm	
L/H Rear Tyre	195/85 R15 (D)	YOKOHAMA	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/03/2021	Inspection Date	03/03/2021	
Survey held at	NGEE NGEE MOTOR BLK 1 NO: 22 PANDAN LOOP SINGAPORE 128219			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 972P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	895.00	895.00
1	FRONT BUMPER SIDE LH	SLACK / DISTORTED	334.00	334.00
1	FRONT BUMPER SIDE RH	NOT NECESSARY	334.00	-
2	FRONT BUMPER BRACKET	BENT	145.60	54.60
1	FRONT CORNER PANEL GARNISH LH	DEFORMED / CUT	382.15	382.15
1	FRONT PANEL	TO REPAIR SEE LABOUR	3,046.00	-
1	FRONT PANEL FUSO EMBLEM	NECESSARY	152.00	105.00
1	FRONT GRILLE ASSY	NOT NECESSARY	959.50	-
1	FRONT GRILLE BADGE	NOT NECESSARY	57.00	-
1	FRONT GRILLE "CENTER" EMBLEM	NOT NECESSARY	40.00	-
1	FRONT LH MIRROR STAY	TO REPAIR SEE LABOUR	428.00	-
1	FRONT LH MIRROR (ROUND)	DISTORTED / CRACKED	125.00	60.00
1	FRONT LH MIRROR (SQUARE)	NOT NECESSARY	145.00	-
1	FRONT SIGNAL LAMP LH	GRAZED / CRACKED	325.50	325.50
1	HEAD LAMP LH	NOT NECESSARY	648.00	-
1	HEAD LAMP LOWER RUBBER LH	NOT NECESSARY	38.00	-
1	SIDE LAMP GARNISH LH	NOT NECESSARY	218.80	-
	LESS 25% DISCOUNT		-	-539.06
			8,273.55	1,617.19
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER ASSY C/W BRACKET (SN)	BENT / TORN	1,900.00	850.00
1	REAR NUMBER PLATE (SN)	DENTED / BENT	38.00	35.00
1	REAR NUMBER PLATE LAMP (SN)	CRACKED / FAULTY	68.00	55.00
1	TAIL GATE MITSUBISHI LETTERING (SN)	NOT NECESSARY	150.00	-
1	TAIL LAMP ASSY LH (SN)	SERVICEABLE	275.00	-
1	TAIL LAMP BRACKET LH (SN)	SERVICEABLE	120.00	-

Report Ref No. CS3/LPC21002885/R1ty3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	DENTED / BENT	38.00	35.00
			2,589.00	975.00
	LABOUR			
	ANTI RUST TREATMENT.		100.00	40.00
	TO CHECK WIRING SYSTEM & LIGHTS.		200.00	40.00
	TO RESPRAY AFFECTED AREAS.		1,400.00	600.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN / REPAIR FRONT CROSS MEMBER & ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF FRONT PANEL AND FRONT LH MIRROR STAY.		1,500.00	800.00
			3,200.00	1,480.00
GRAND TOTAL			14,062.55	4,072.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CS3/LPC21002885/R1ty3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.