



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 972P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BUCKLED	895.00	895.00
1	FRONT BUMPER SIDE LH	SLACK / DISTORTED	334.00	334.00
1	FRONT BUMPER SIDE RH	NOT NECESSARY	334.00	-
2	FRONT BUMPER BRACKET	BENT	145.60	54.60
1	FRONT CORNER PANEL GARNISH LH	DEFORMED / CUT	382.15	382.15
1	FRONT PANEL	TO REPAIR SEE LABOUR	3,046.00	-
1	FRONT PANEL FUSO EMBLEM	NECESSARY	152.00	105.00
1	FRONT GRILLE ASSY	NOT NECESSARY	959.50	-
1	FRONT GRILLE BADGE	NOT NECESSARY	57.00	-
1	FRONT GRILLE "CENTER" EMBLEM	NOT NECESSARY	40.00	-
1	FRONT LH MIRROR STAY	TO REPAIR SEE LABOUR	428.00	-
1	FRONT LH MIRROR (ROUND)	DISTORTED / CRACKED	125.00	60.00
1	FRONT LH MIRROR (SQUARE)	NOT NECESSARY	145.00	-
1	FRONT SIGNAL LAMP LH	GRAZED / CRACKED	325.50	325.50
1	HEAD LAMP LH	NOT NECESSARY	648.00	-
1	HEAD LAMP LOWER RUBBER LH	NOT NECESSARY	38.00	-
1	SIDE LAMP GARNISH LH	NOT NECESSARY	218.80	-
	LESS 25% DISCOUNT		-	-539.06
			8,273.55	1,617.19
SPECIAL NETT ITEMS				
1	REAR BUMPER ASSY C/W BRACKET (SN)	BENT / TORN	1,900.00	850.00
1	REAR NUMBER PLATE (SN)	DENTED / BENT	38.00	35.00
1	REAR NUMBER PLATE LAMP (SN)	CRACKED / FAULTY	68.00	55.00
1	TAIL GATE MITSUBISHI LETTERING (SN)	NOT NECESSARY	150.00	-
1	TAIL LAMP ASSY LH (SN)	SERVICEABLE	275.00	-
1	TAIL LAMP BRACKET LH (SN)	SERVICEABLE	120.00	-

Report Ref No. CS3/LPC21002885/R1ty3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	DENTED / BENT	38.00	35.00
	LABOUR		2,589.00	975.00
	ANTI RUST TREATMENT.		100.00	40.00
	TO CHECK WIRING SYSTEM & LIGHTS.		200.00	40.00
	TO RESPRAY AFFECTED AREAS.		1,400.00	600.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN / REPAIR FRONT CROSS MEMBER & ALIGNED ALL PARTS.		1,500.00	800.00
	INCLUSIVE OF THE REPAIR OF FRONT PANEL AND FRONT LH MIRROR STAY.			
	GRAND TOTAL		3,200.00	1,480.00
			14,062.55	4,072.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CS3/LPC21002885/R1ty3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.