



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/ASM21006836/Vqy3-1

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Ref: ~~CS3/ASM21006836/Vqy3-1~~
Date: ~~21/06/2021~~ 04/02/2022
Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHD 3203X	Veh. Inspected	SJE 5196R
Policy No.		Coverage (\$)	0.00
Claim No.	S1M03C2A	Excess (\$)	0.00
Assign From	CHAN KIAN CHUAN	Assign Date	21/06/2021 04/02/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	18/06/2021	Inspection Date	21/06/2021
Survey held at	25 KAKI BUKIT ROAD 4 #08-26 SYNERGY @KB		
Repairer	1 STOP GARAGE PTE. LTD.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

File No: Thuan

REF: CS3/ASm2006826/V9C-1


ASSIGNMENT

29/4/2008

From: _____ Date: _____
 Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: S1M03C2A
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 20k
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 79 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SSE5196R Yr Regn: 2008
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mitsubishi Lancer 706 GTM cc 1998
 Colour: black A/C: Insured / Std / NI / NA
 Sp. Reading: 313910 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ~~CS3/ASm2006826~~ Jm, SNC YL 88000863
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NII / S/Rim / STD A/Rim or
 Tyre Size: F: 225/402R8
 R: 225/402R8
 BS / DUN / EXNOVA / GY FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 18/6/21 D.O.I. 21/6/21 1100
 Survey held at 1 stop car 2 w/s
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	mv: 20k
	NV: 12437
	rebate: 7563
	rc: 6k-7k
	resurvey on 21/6/21 1530
	21/6/21

23/06/21 @2.48pm revised to Chan Kian Chuan via Smart Claims.

23/06/21 Submit PRS.

15/02/22 Submit LS \$7250, 9 days (Red \$7050, 49%)

OverTime, File Pass to? ☐ : Prell. Report

Days Of Repair: 9

15/02 Typist ☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

\$ + PS \$

Printed

Checked

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Visual Insp (\$

Request Formed:

TP

Limit: 7250

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	195C
Vehicle Details	
Vehicle No.:	SJE5196R
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jun 2021
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 2.0L MIVEC GT 5M/T SR
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	4B11BN8580
Chassis No.:	JMYSNCY4A8U000863
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$19,486.00
Original Registration Date:	29 Apr 2008
First Registration Date:	29 Apr 2008
Transfer Count:	4
Actual ARF Paid:	\$21,435.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Apr 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$20,441.00
COE Rebate Amount:	\$7,563.00
Total Rebate Amount:	\$7,563.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Jun 2021

OK

10A 18/6/21
= 14rs 10yr 15 / 22
dp: 10 700
12
= 8912
892 x 22
= 19624 / 20k
~~19624~~ - 70k - 7563
= 12437

HWM + HardwareZone Tech Awards 2021

Catch the video highlights now!



Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

1 Lady Owner, 2014 Model, Low Mileage, Fancy Number.



Fully Maintained By M&L Motor
Lap 1 With Accidents & Road
Turned Car. No Issues
Direct Owner. No Junk

PRIME MOTOR & LEASING
[CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES]
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Sort by Date Posted 20 results/

4 vehicles

LANCER 2.0 GT

Basic Search

Price Any price **Depre** Any depre **Reg Date** Before 2011 **Eng Cap** Any **Veh Type** All types
Fuel Any fuel **Mileage** Any **OMV** Any **Gear** Manual **Past Owners** Any
Category All categories **Scheme** All schemes **Dealer** Any Dealer **Location** Any **Status** Available

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Sta



Mitsubishi Lancer EX 2.0M GT
(COE till 08/2025)

\$44,400

\$10,690 /yr

17-Aug-2010

1,998 cc

125,000 km

Sedan

Av

Excellent Condition. Serviced Regularly At Reputable Workshop. All Wear And Tear Replaced. Get Your Hands On This Beauty Now! Loan Available. Call Now For Viewing.

Posted: 11-Jun-2021 Tags: 2010 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer



Mitsubishi Lancer EX 2.0M GT
(COE till 05/2029)

\$76,800

\$9,670 /yr

09-Jun-2009

1,998 cc

250,000 km

Sedan

Av

Engine Overhauled, Definitely A Car Not For The Faint Heart, New Coat Of Paint & Coating Just Done Recently, Driven Daily And Even Ready To Hit The Tracks When The Borders Open! View To Know More, Flexible Loan Package Available, Viewings By Appointments Onl...

Posted: 08-Jun-2021 Tags: 2009 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer



Mitsubishi Lancer EX 2.0M GT
(COE till 05/2029)

\$69,999

\$8,830 /yr

26-May-2009

1,998 cc

120,000 km

Sedan

Av

Tastefully Done Up! Rarely Driven Ride! Very Well Taken Care Of! Lots Of Wear And Tear Changed, Many Accessories Too Many To List Included! Stock Parts Will Be Given, View To Believe! Trade In And High Loan Welcome! Viewing Strictly Via Appointment!

Posted: 02-Jun-2021 Tags: 2009 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer



Mitsubishi Lancer EX 2.0M GT
(COE till 08/2028)

\$62,800

\$8,790 /yr

13-Aug-2008

1,998 cc

-

Sedan

Av

New Paint Work Will Be Given. Engine & Gearbox Fully Overhauled, Lots Of Wear And Tear Changed, View To Believe! Call Our Experience Sales Executives To Avoid Disappointment. Viewing Strictly Via Appointment Only!

Posted: 16-May-2021 Tags: 2008 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Sta

For old advertisements, view Expired ads

20 result

[Home](#)
[New Cars](#)
[Used Cars](#)
[Rental Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Article](#)
[Forum](#)
[Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or sta SUV, MPV, hatchback, to COE cars & DPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance used LANCER 2.0 GT, LANCER 2.0 GT Singapore, used LANCER 2.0 GT Singapore, used LANCER 2.0 GT, used vehicles Singapore or even buy used LANCER 2.0 GT Singapore. We have dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner in Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

Compare

CARLINK CONSULTANCY


60 Hillside Drive
Singapore 549009

Tel : 62856178

Fax : 62874788

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CL 12311 SJE 5196 R

1 REFERENCE					
Date of request	:	18th June 2021			
Requested by	:	Ong Poh Meng C/o Synergy@KB 25 Kaki Bukit Road 4, #03-65/67/68 Singapore 417800			
Type of claim	:	Third party			
Workshop	:	M/S 1 Stop Carz Pte Ltd C/o Synergy@KB 25 Kaki Bukit Road 4, #03-65/67/68 Singapore 417800			
Accident date	:	18th June 2021			
Date of survey	:	18th June 2021			
2 DETAILS OF VEHICLE					
Registration No.	:	SJE 5196 R			
Make & Model	:	Mitsubishi Lancer 2.0L MIVEC GT 5M/T SR			
Date of registration	:	29th April 2008			
Engine No.	:	4B11BN8580			
Chassis No.	:	JMYSNCY4A8U000863			
Speedometer reading	:	313810 Km			
Transmission	:	Manual			
Colour	:	Black			
3 STATIC CHECK					
Steering	:	see annex(es)	Paintwork	:	Good
Footbrake	:	see annex(es)	Modification	:	Nil
Handbrake	:	see annex(es)	General condition	:	Good
4 TYRE CONDITION					
		<u>Nearside/Make</u>	<u>Offside/Make</u>	<u>Size</u>	
Front tyre	:	6mm/Goodyear	6mm/Goodyear	:	225/40Z R18
Rear tyre	:	6mm/Goodyear	6mm/Goodyear	:	225/40Z R18
5 POINT OF IMPACT					
See Annex(es) and Motor Accident Reports					
6 REMARK					
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.					

Annex A : Assesement / Adjustment on Spare Parts

SJE 5196 R

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
List Items						
1	Front bonnet	Buckled	1	\$877.00	10%	\$609.30
2	Front bonnet cable	Jammed	1	\$38.00	10%	\$34.20
3	Front bonnet hinges L/R	Bent	2	\$110.00	10%	\$99.00
4	Front bonnet insulation mat	Crumpled	1	\$82.00	10%	\$73.80
5	Front bonnet mechanism lock	Distorted/jammed	1	\$53.00	10%	\$47.70
6	Front bonnet nozzle L/R	Distorted/cut	2	\$32.00	10%	\$28.80
7	Front bonnet rubber guide stopper L/R	Cut	4	\$40.00	10%	\$36.00
8	Front bonnet stand holder clips	Necessary	1	\$6.50	10%	\$5.85
9	Front bonnet weatherstrip	Cut	2	\$28.00	10%	\$25.20
10	Front head lamp L/R	Cracked	2	\$1,396.00	10%	\$1,256.40
11	Front head lamp clips L/R	Necessary	2	\$13.00	10%	\$11.70
12	Front head lamp HID ballast 'ORIGINAL' L/R	Faulty	2	\$1,898.00	10%	\$1,708.40
13	Front head lamp HID bulb 'ORIGINAL' L/R	Faulty	2	\$862.00	10%	\$595.80
14	Front grille 'LOGO' emblem	Cracked	1	\$38.00	10%	\$34.20
15	Front grille L/R	Cracked	2	\$80.00	10%	\$72.00
16	Front grille inner air guide L/R	Crumpled/cut	2	\$50.00	10%	\$45.00
17	Front grille chrome moulding	Cracked	1	\$286.00	10%	\$257.40
18	Front bumper	Bent/cut	1	\$810.00	10%	\$729.00
19	Front bumper beam	Bent	1	\$67.00	10%	\$60.30
20	Front bumper foglamp LH	Serviceable	1	\$422.00	100%	\$0.00
21	Front bumper foglamp RH	Cracked/faulty	1	\$422.00	10%	\$379.80
22	Front bumper foglamp garnish L/R	Shifted/cut	2	\$76.00	10%	\$68.40
23	Front bumper foglamp garnish wire harness	Cut	1	\$130.00	10%	\$117.00
24	Front bumper number plate garnish	Bent/cut	1	\$28.00	10%	\$25.20
25	Front bumper reinforcement	Bent	1	\$326.00	10%	\$293.40
26	Front bumper side retainer L/R	Necessary	2	\$40.00	10%	\$36.00
27	Front bumper top rubber seal	Cut	1	\$28.00	10%	\$25.20
28	Front bumper tow hook cover	Slack/cut	1	\$25.00	10%	\$22.50
29	Front bumper lower center grille	Bent/cut	1	\$69.00	10%	\$62.10
30	Front bumper lower center grille cover L/R	Distorted/cut	2	\$20.00	10%	\$18.00
31	Front bumper lower under cover	Serviceable	1	\$145.00	100%	\$0.00
32	Front support panel top garnish	Cut	1	\$63.00	10%	\$56.70
33	Front support panel	Bent	1	\$984.00	10%	\$885.60
34	Aircon condenser	Dented/leaked	1	\$883.00	10%	\$794.70
35	Aircon cooling pipe	Bent	1	\$130.00	10%	\$117.00
36	Aircon discharge pipe	Bent	1	\$176.00	10%	\$158.40
37	Aircon fan blade	Grazed/cut	1	\$53.00	10%	\$47.70
38	Aircon fan cowling	Cracked	1	\$222.00	10%	\$199.80
39	Aircon fan motor	Dented/faulty	1	\$58.00	10%	\$52.20
40	Aircon outside temperature sensor	Faulty	1	\$40.00	10%	\$36.00
41	Aircon suction pipe	Bent	1	\$186.00	10%	\$167.40
42	Horn L/R	Faulty	2	\$180.00	10%	\$162.00
43	Radiator	Dented/cut/leaked	1	\$978.00	10%	\$880.20

702

SJE 5196 R

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)	
44	Radiator by pass hose	Leaked	1	\$18.00	10%	\$18.20	X SVC
45	Radiator fan blade	Grazed	1	\$62.00	10%	\$55.80	X SVC
46	Radiator fan cowling	Cracked	1	\$224.00	10%	\$201.60	X SVC
47	Radiator fan motor	Dented/faulty	1	\$386.00	10%	\$347.40	X SVC
48	Radiator lower hose	Cut	1	\$72.00	10%	\$64.80	X SVC
49	Radiator lower rubber bush L/R	Distorted	2	\$24.00	10%	\$21.60	X SVC
50	Radiator neck	Leaked	1	\$75.00	10%	\$67.50	X SVC
51	Radiator neck hose	Leaked	1	\$80.00	10%	\$72.00	X SVC
52	Radiator spare tank	Leaked	1	\$50.00	10%	\$45.00	X SVC
53	Radiator spare tank hose	Leaked	1	\$10.00	10%	\$9.00	X SVC
54	Radiator top hose	Necessary	1	\$43.00	10%	\$38.70	X SVC
55	Radiator top rubber bush L/R	Necessary	2	\$20.00	10%	\$18.00	X SVC
56	Washer tank	Dented/cut	1	\$81.00	10%	\$72.90	X SVC
57	Washer tank cap	Serviceable	1	\$10.00	100%	\$0.00	
58	Washer tank motor	Faulty	1	\$139.00	10%	\$125.10	X SVC
59	Washer tank neck	Shifted/leaked	1	\$21.00	10%	\$18.90	X SVC
60	Rear bootlid	Dented/bent	1	\$580.00	10%	\$522.00	X SVC
61	Rear bootlid 'LANCER' emblem	Necessary	1	\$41.00	10%	\$36.90	
62	Rear bootlid 'LOGO' emblem	Necessary	1	\$38.00	10%	\$34.20	
63	Rear bootlid damper L/R	Serviceable	2	\$150.00	100%	\$0.00	
64	Rear bootlid hinges L/R	Bent	2	\$164.00	10%	\$147.60	X SVC
65	Rear bootlid inner upholstery trim	Serviceable	1	\$160.00	100%	\$0.00	
66	Rear bootlid mechanism lock	Bent/jammed	1	\$58.00	10%	\$52.20	
67	Rear bootlid mechanism lock garnish	Cut	1	\$10.00	10%	\$9.00	
68	Rear bootlid outer handle switch	Faulty	1	\$76.00	10%	\$68.40	X SVC
69	Rear bootlid rubber guide stopper L/R	Necessary	2	\$20.00	10%	\$18.00	X SVC
70	Rear bootlid weatherstrip	Deformed/cut	1	\$160.00	10%	\$144.00	X SVC
71	Rear bumper	Buckled/cut	1	\$731.00	10%	\$657.90	
72	Rear bumper beam	Bent	1	\$67.00	10%	\$60.30	
73	Rear bumper inner side shield clips L/R	Necessary	15	\$39.00	10%	\$35.10	
74	Rear bumper inner side shield L/R	Distorted/cut	2	\$60.00	10%	\$54.00	X SVC
75	Rear bumper number plate lamp bracket L/R	Bent	2	\$30.00	10%	\$27.00	X SVC
76	Rear bumper number plate lamp L/R	Distorted/cracked	2	\$96.00	10%	\$86.40	X SVC
77	Rear bumper reflector L/R	Grazed/cracked	1	\$46.00	10%	\$41.40	
78	Rear bumper reinforcement	Dented/bent	1	\$188.00	10%	\$169.20	
79	Rear bumper side retainer L/R	Necessary	2	\$40.00	10%	\$36.00	
80	Rear end panel inner top garnish	Bent/cut	1	\$150.00	10%	\$135.00	X SVC
81	Rear end panel lock striker	Bent	1	\$25.00	10%	\$22.50	X SVC
82	Rear end panel bootlid antenna sensor with alarm	Faulty	1	\$140.00	10%	\$126.00	X SVC
83	Rear end panel	Repair	1	\$427.00	100%	\$0.00	
S/Nett Items							
84	Front bonnet insulator mat clips - set	Necessary	1	\$30.00		\$30.00	15
85	Front bumper clips - set	Necessary	1	\$30.00		\$30.00	15
86	Front bumper number plate	Dented/bent	1	\$25.00		\$25.00	
87	Front bumper number plate holder	Bent/cut	1	\$50.00		\$50.00	20
88	Front bumper rivert - set	Necessary	1	\$40.00		\$40.00	20

SJE 5196 R

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)	
89	Front support panel top garnish clips - set	Necessary	1	\$30.00		\$30.00	15
90	Front bootlid inner upholstery trim clips - set	Necessary	1	\$30.00		\$30.00	15
91	Front fender inner upholstery trim clips L/R - set	Necessary	2	\$60.00		\$60.00	XNN
92	Rear bumper clips - set	Necessary	1	\$30.00		\$30.00	15
93	Rear bumper number plate	Betn/cut	1	\$25.00		\$25.00	15
94	Rear bumper number plate holder	Bent/cut	1	\$50.00		\$50.00	20
95	Rear bumper reverse sensor - set	Distorted/cut/faulty	1	\$350.00		\$350.00	200
Total for Spare Parts :				\$17,609.50		\$14,740.95	

Annex B : Adjustment on Labour and Spray Painting

SJE 5196 R

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor	\$140.00	\$100.00 40
2	To remove, reinstall air con parts, vaccum, refill aircon gas	\$160.00	\$120.00 60 + 20
3	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet	\$120.00	\$100.00 50
4	To respray painting on the change bodyparts, repair portion, and where consistent to the accident	\$1,250.00	\$1,200.00 1200 1000
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident	\$1,700.00	\$1,500.00 1000
6	To apply anti-rust chemical on repaired and replaced panel	\$120.00	\$100.00 40
TOTAL FOR LABOUR & SPRAY PAINTING :		\$3,490.00	\$3,120.00

Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$17,609.50	\$14,740.95
TOTAL FOR LABOUR & SPRAY PAINTING :	\$3,490.00	\$3,120.00
TOTAL REPAIR COSTS :	\$21,099.50	\$17,860.95

CARLINK CONSULTANCY

SJE 5196 R

Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S 1 Stop Carz Pte Ltd estimated repair cost is **S\$21,099.50** and we have adjusted it to **S\$17,860.95** on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.

7550
78700

The repairer have agreed to undertake the repairs on a contract lump sum of **S\$14,300.00**, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

7 + 2 = 9

The entire repair of the damaged vehicle should be completed within a reasonable period of **15** working days.

We have advised the repairer that the inspection was conducted strictly on a **WITHOUT PREJUDICE** basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,

CARLINK CONSULTANCY

PATRICK NG

Automotive Engineer Assessor

MIMI, MIRTE, LCGI, I ENG, LAE, CGLI ETC.

Vehicle no.: SLU 9717D

S/N.	PARTS	NETT	S/NETT	LABOUR
1	\$ 677.00		\$ 15.00	\$ 40.00
2	\$ 38.00		\$ 15.00	\$ 80.00
3	\$ 55.00		\$ 25.00	\$ 50.00
4	\$ 82.00		\$ 20.00	\$ 1,000.00
5	\$ 53.00		\$ 20.00	\$ 1,000.00
6	\$ 28.00		\$ 15.00	\$ 40.00
7	\$ 1,396.00		\$ 15.00	
8	\$ 13.00		\$ 15.00	
9	\$ 38.00		\$ 25.00	
10	\$ 80.00		\$ 20.00	
11	\$ 50.00		\$ 200.00	
12	\$ 286.00			
13	\$ 695.00			
14	\$ 67.00			
15	\$ 28.00			
16	\$ 185.00			
17	\$ 40.00			
18	\$ 28.00			
19	\$ 25.00			
20	\$ 69.00			
21	\$ 20.00			
22	\$ 63.00			
23	\$ 418.00			
24	\$ 883.00			
25	\$ 702.00			
26	\$ 41.00			
27	\$ 38.00			
28	\$ 58.00			
29	\$ 10.00			
30	\$ 160.00			
31	\$ 655.00			
32	\$ 67.00			
33	\$ 15.00			
34	\$ 23.00			
35	\$ 188.00			
36	\$ 40.00			
	\$ 7,314.00	\$ -	\$ -	\$ 385.00
		\$ -	\$ -	\$ 2,210.00
		Sub Total:	\$ 7,314.00	10%
		10%	\$ 731.40	\$ -
			\$ 6,582.60	\$ -
			TOTAL:	\$ 9,177.60
			80% Lump Sum:	\$ 7,342.08
			Round Off:	\$ 7,250.00

CHECK:

S/N.	PARTS	NETT	S/NETT	LABOUR
------	-------	------	--------	--------

1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				

\$	-	\$	-	\$	-	\$	-	\$	-	\$	-
		Sub Total:	\$	-		10%					
		10%	\$	-	\$	-					
			\$	-	\$	-					

TOTAL:	\$	-
0% Lump Sum:	\$	-
Round Off:	\$	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 5196R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	BUCKLED	677.00	677.00
1	FRONT BONNET CABLE	JAMMED	38.00	38.00
2	FRONT BONNET HINGES L/R	O/S BENT / N/S SERVICEABLE	110.00	55.00
1	FRONT BONNET INSULATION MAT	CRUMPLED	82.00	82.00
1	FRONT BONNET MECHANISM LOCK	DISTORTED / JAMMED	53.00	53.00
2	FRONT BONNET NOZZLE L/R	NOT NECESSARY	32.00	-
4	FRONT BONNET RUBBER GUIDE STOPPER L/R	NOT NECESSARY	40.00	-
1	FRONT BONNET STAND HOLDER CLIPS	SERVICEABLE	6.50	-
2	FRONT BONNET WEATHERSTRIP	CUT	28.00	28.00
2	FRONT HEAD LAMP L/R	CRACKED	1,396.00	1,396.00
2	FRONT HEAD LAMP CLIPS L/R	NECESSARY	13.00	13.00
2	FRONT HEAD LAMP HID BARLAST 'ORIGINAL' L/R	SERVICEABLE	1,896.00	-
2	FRONT HEAD LAMP HID BULB 'ORIGINAL' L/R	NOT NECESSARY	662.00	-
1	FRONT GRILLE 'LOGO' EMBLEM	CRACKED	38.00	38.00
2	FRONT GRILLE L/R	CRACKED	80.00	80.00
2	FRONT GRILLE INNER AIR GUIDE L/R	CRUMPLED / CUT	50.00	50.00
1	FRONT GRILLE CHROME MOULDING	CRACKED	286.00	286.00
1	FRONT BUMPER	BENT / CUT	810.00	695.00
1	FRONT BUMPER BEAM	BENT	67.00	67.00
1	FRONT BUMPER FOGLAMP LH	SERVICEABLE	422.00	-
1	FRONT BUMPER FOGLAMP RH	SERVICEABLE	422.00	-
2	FRONT BUMPER FOGLAMP GARNISH L/R	SERVICEABLE	76.00	-
1	FRONT BUMPER FOGLAMP GARNISH WIRE HARNESS	SERVICEABLE	130.00	-
1	FRONT BUMPER NUMBER PLATE GARNISH	BENT / CUT	28.00	28.00
1	FRONT BUMPER REINFORCEMENT	BENT	326.00	185.00
2	FRONT BUMPER SIDE RETAINER L/R	NECESSARY	40.00	40.00
1	FRONT BUMPER TOP RUBBER SEAL	CUT	28.00	28.00
1	FRONT BUMPER TOW HOOK COVER	SLACK / CUT	25.00	25.00
1	FRONT BUMPER LOWER CENTER GRILLE	BENT / CUT	69.00	69.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT BUMPER LOWER CENTER GRILLE COVER L/R	DISTORTED / CUT	20.00	20.00
1	FRONT BUMPER LOWER UNDER COVER	SERVICEABLE	145.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	CUT	63.00	63.00
1	FRONT SUPPORT PANEL	BENT	984.00	418.00
1	AIRCON CONDENSER	DENTED / LEAKED	883.00	883.00
1	AIRCON COOLING PIPE	SERVICEABLE	130.00	-
1	AIRCON DISCHARGE PIPE	SERVICEABLE	176.00	-
1	AIRCON FAN BLADE	SERVICEABLE	53.00	-
1	AIRCON FAN COWLING	SERVICEABLE	222.00	-
1	AIRCON FAN MOTOR	SERVICEABLE	58.00	-
1	AIRCON OUTSIDE TEMPERATURE SENSOR	SERVICEABLE	40.00	-
1	AIRCON SUCTION PIPE	SERVICEABLE	186.00	-
2	HORN L/R	SERVICEABLE	180.00	-
1	RADIATOR	DENTED / CUT / LEAKED	978.00	702.00
1	RADIATOR BY PASS HOSE	SERVICEABLE	18.00	-
1	RADIATOR FAN BLADE	SERVICEABLE	62.00	-
1	RADIATOR FAN COWLING	SERVICEABLE	224.00	-
1	RADIATOR FAN MOTOR	SERVICEABLE	386.00	-
1	RADIATOR LOWER HOSE	SERVICEABLE	72.00	-
2	RADIATOR LOWER RUBBER BUSH L/R	SERVICEABLE	24.00	-
1	RADIATOR NECK	SERVICEABLE	75.00	-
1	RADIATOR NECK HOSE	SERVICEABLE	80.00	-
1	RADIATOR SPARE TANK	SERVICEABLE	50.00	-
1	RADIATOR SPARE TANK HOSE	SERVICEABLE	10.00	-
1	RADIATOR TOP HOSE	SERVICEABLE	43.00	-
2	RADIATOR TOP RUBBER BUSH L/R	SERVICEABLE	20.00	-
1	WASHER TANK	SERVICEABLE	81.00	-
1	WASHER TANK CAP	SERVICEABLE	10.00	-
1	WASHER TANK MOTOR	SERVICEABLE	139.00	-
1	WASHER TANK NECK	SERVICEABLE	21.00	-
1	REAR BOOTLID	TO REPAIR SEE LABOUR	580.00	-
1	REAR BOOTLID 'LANCER' EMBLEM	NECESSARY	41.00	41.00

Report Ref No. CS3/ASM21006836/Vqy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOTLID 'LOGO' EMBLEM	NECESSARY	38.00	38.00
2	REAR BOOTLID HINGES L/R	NOT NECESSARY	164.00	-
1	REAR BOOTLID INNER UPHOLSTERY TRIM	SERVICEABLE	160.00	-
1	REAR BOOTLID MECHANISM LOCK	BENT / JAMMED	58.00	58.00
1	REAR BOOTLID MECHANISM LOCK GARNISH	CUT	10.00	10.00
1	REAR BOOTLID OUTER HANDLE SWITCH	SERVICEABLE	76.00	-
2	REAR BOOTLID RUBBER GUIDE STOPPER L/R	SERVICEABLE	20.00	-
1	REAR BOOTLID WEATHERSTRIP	DEFORMED / CUT	160.00	160.00
1	REAR BUMPER	BUCKLED / CUT	731.00	655.00
1	REAR BUMPER BEAM	BENT	67.00	67.00
6	REAR BUMPER INNER SIDE SHIELD CLIPS L/R	NECESSARY	39.00	15.00
2	REAR BUMPER INNER SIDE SHIELD L/R	SERVICEABLE	60.00	-
2	REAR BUMPER NUMBER PLATE LAMP BRACKET L/R	SERVICEABLE	30.00	-
2	REAR BUMPER NUMBER PLATE LAMP L/R	SERVICEABLE	96.00	-
2	REAR BUMPER REFLECTOR L/R	GRAZED / CRACKED (1PC ONLY)	46.00	23.00
1	REAR BUMPER REINFORCEMENT	DENTED / BENT	188.00	188.00
2	REAR BUMPER SIDE RETAINER L/R	NECESSARY	40.00	40.00
1	REAR END PANEL INNER TOP GARNISH	SERVICEABLE	150.00	-
1	REAR END PANEL LOCK STRIKER	TO REPAIR SEE LABOUR	25.00	-
1	REAR END PANEL BOOTLID ANTENNA SENSOR WITH ALARM	SERVICEABLE	140.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	427.00	-
2	REAR BOOTLID DAMPER L/R	SERVICEABLE	150.00	-
	LESS 10% DISCOUNT		-	-731.40
			16,859.50	6,582.60
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BONNET INSULATOR MAT CLIPS (SN)	NECESSARY	30.00	15.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	15.00
1	FRONT BUMPER NUMBER PLATE (SN)	DENTED / BENT	25.00	25.00
1	FRONT BUMPER NUMBER PLATE HOLDER (SN)	BENT / CUT	50.00	20.00
1	SET FRONT BUMPER RIVERT (SN)	NECESSARY	40.00	20.00

Report Ref No. CS3/ASM21006836/Vqy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NECESSARY	30.00	15.00
1	SET FRONT BOOTLID INNER UPHOLSTERY TRIM CLIPS (SN)	NECESSARY	30.00	15.00
2	SET FRONT FENDER INNER UPHOLSTERY TRIM CLIPS L/R (SN)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	15.00
1	REAR BUMPER NUMBER PLATE (SN)	BENT / CUT	25.00	25.00
1	REAR BUMPER NUMBER PLATE HOLDER (SN)	BENT / CUT	50.00	20.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DISTORTED / CUT / FAULTY	350.00	200.00
			750.00	385.00
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.		140.00	40.00
	TO REMOVE, REINSTALL AIRCON PARTS, VACUUM, REFILL AIRCON GAS.		160.00	80.00
	TO REMOVE, REINSTALL TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET.		120.00	50.00
	TO RESPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,250.00	1,000.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR END PANEL LOCK STRIKER AND REAR END PANEL.		1,700.00	1,000.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	40.00
			3,490.00	2,210.00
GRAND TOTAL			21,099.50	9,177.60

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,250.00
---	--	--	-----------------

Report Ref No. CS3/ASM21006836/Vqy3e2-1

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.