

LKK Auto Consultants Pte Ltd

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 950C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR N/S FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	987.10	-
1	REAR N/S FENDER AIR DUCT (CONSISTENT)	DENTED	105.10	105.10
1	REAR N/S SIDE BUMPER (CONSISTENT)	BUCKLED	335.60	195.00
1	REAR N/S FENDER ARCH GARNISH (CONSISTENT)	BUCKLED	205.10	205.10
1	REAR N/S FENDER INNERSHIELD (CONSISTENT)	DEFORMED	197.60	197.60
1	REAR BUMPER (CONSISTENT)	DENTED / CUT	855.60	689.00
1	REAR N/S BUMPER REFLECTOR (CONSISTENT)	SERVICEABLE	137.10	-
1	REAR BUMPER UNDER COVER (CONSISTENT)	CRACKED	195.70	195.70
	LESS 20% DISCOUNT		-603.78	-317.50
			2,415.12	1,270.00
	SPECIAL NETT ITEMS			
1	REAR REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	200.00	-
20	REAR BUMPER CLIP @\$2.00 (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			240.00	40.00
	<u>LABOUR</u>			
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING.INCLUSIVE OF THE REPAIR OF REAR N/S FENDER.		1,200.00	550.00
	TO PUTTY AND SPRAY PAINT.		1,000.00	300.00
	CHECK & RECONNECT WIRING.		30.00	15.00
	TO RESPRAY ANTI-RUST PROOFING TREATMENT.	NOT NECESSARY	100.00	-
	REMOVE/REFIT ROOF LINING TO FACILITATE REPAIR. }		180.00	80.00
	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR. }		100.00	-
			2,610.00	945.00
	GRAND TOTAL		5,265.12	2,255.00

Report Ref No. CS/ASM22001065/Kvy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/ASM22001065/Kvy3e2

KONG SENG CHEONG

Licensed Appraiser