LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd Our File No: CS/III22001066/KVY3E2 64 Cecil Street, #04-00 IOB Building

Date: 25/03/2022 Singapore 049711

REFERENCE

COMFORTDELGRO CORPORATION LTD & ALL ITS

Policy Insured/Claimant: SUBSIDIARIES FOR THIER RESPECTIVE RIGHTS AND D18MFL0001360 03 No:

INTERESTS

Nature

Claim MFL2022D0000584 25/01/2022 OD Date of Loss: of No:

Claim:

DESCRIPTION & IDENTIFICATION OF VEHICLE

YN8749B Reg No:

Make & Model: ISUZU NJR85AUE6W, 3.0 D (M) 4JJ11Z1683 Engine No:

Chassis No: Reg. Date: JAANJR85EF7100034 21/08/2015 (Man. Year: 2015)

Colour: Multi-colour Odometer: 189825 km

Engine Capacity: 2999 cc Market Value/New Car Price: S\$31.000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes **Engine Modification:** No

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8 (D) Front Left Side: Rear Left Side: **DURATURN 8 mm** DURATURN 9/9 mm Front Right Side: **DURATURN 8 mm** Rear Right Side: DURATURN 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		870.50	850.50	20.00	2.30
Miscellaneous Items		11.00	11.00	0.00	0.00
Labour		2,030.00	1,080.00	950.00	46.80
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	2,911.50	1,941.50	970.00	33.32
	Approved Total (Overridden) (S\$)		1,500.00		
	- Excess (S\$)	0.00	750.00	-750.00	
	(S\$)	2,911.50	750.00	2,161.50	74.24
	+ GST 7.00/7.00% (S\$)	203.81	52.50	151.31	74.24
	Nett Amount (S\$)	3,115.31	802.50	2,312.81	74.24

INSPECTION

ComfortDelGro Engineering Pte Ltd (Braddell) Date of Assignment: 04/02/2022 Present Location:

ComfortDelGro Engineering Pte Ltd (Braddell)

205 Braddell Road Date Inspected: 04/02/2022 Inspected At:

Singapore 579701

Estimated Period of Repair: 4.0 days

KENNETH KONG **VERON CHEN** Adjuster: Manager:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 25 Mar 2022)

Parts: N/A ISUZU NJR85AUE6W 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YN8749B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH TAILLAMP	Cracked	130.00 FL	*130.00 FL
2	1		*REAR NUMBER PLATE	Bent	45.00 FS	*25.00 FS
3	1		*REAR 60KM/H STICKER	Necessary	20.00 FS	*20.00 FS
4	1		*REAR ADDVERTISEMENT STICKER	Necessary	250.00 FS	*250.00 FS
5	1		*REAR CRASH BAR	Bent	500.00 FL	*500.00 FL
6	1		*REAR 6 PAX STICKER	Necessary	20.00 FS	*20.00 FS
F=Fra	nchise	part. S=SpcNe	ett. L=ListItemDisc.			
				Sub Total (S\$)	965.00	945.00
			- List Item Discount on L I	tems 15.00/15.00% (S\$)	94.50	94.50
				Total Parts (S\$)	870.50	850.50
			Report was unsubmitted dur	ing this print-out		

Recommended Miscellaneous Items

No Qt	y Particulars		Repairer's	Amount
Miscella	ineous Items			
1 1	OD/TP Case (Insurer)		11.00	11.00
		Sub Total (S\$)	11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO PANEL BEAT ON REAR TAILGATE ,REAR FLOOR PANEL ,NUMBER PLATE LAMP BRACKET ,REPLACE DAMAGE ITEM AND REALIGN AFFECTED AREAS	New	1,000.00	500.00
2	TO PUTTY,RESPRAY ON REAR TAILGATE ,REAR FLOOR PANEL,CRACSH BAR,CHASSIS FRAME ,BRACKET AND AFFECET AREAS	New D	900.00	500.00
3	CHECK LIGHTING AND WIRING	New	30.00	20.00
4	TO INSTALL REAR ADVERTISEMENT STICKER check)	New	100.00	60.00
	Gross Lab	our Cost (S\$)	2,030.00	1,080.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.