

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EV 988A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR SLIDING DOOR N/S	TO REPAIR SEE LABOUR	2,455.10	-
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	1,855.30	-
1	FUEL LID	TO REPAIR SEE LABOUR	195.00	-
			4,505.40	-
	<u>LABOUR</u>			
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO DISMANTLE & REFIX FUEL TANK.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	80.00	-
	TO TRANSFER REAR SLIDING DOOR MECHANISM.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR SLIDING DOOR N/S, REAR FENDER N/S AND FUEL LID.		680.00	300.00
	TO PUTTY & SPRAY PAINTING.		900.00	500.00
			1,910.00	800.00
	GRAND TOTAL		6,415.40	800.00

RECOMMENDED COST OF REPAIRS

Report Ref No. CS/UOI22001081/Uvy3e2

CHUA KANG SENG

Licensed Appraiser