

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 342Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	SEALANT (SN)	NECESSARY	200.00	100.00
1	PANEL SUB-ASSY, FR (SN)	TO REPAIR SEE LABOUR	1,377.90	-
1	STRIPE, FR DOOR (SN)	NOT NECESSARY	14.10	-
1	STRIPE, FR DOOR (SN)	NOT NECESSARY	46.20	-
1	STRIPE, FR DOOR (SN)	NOT NECESSARY	27.90	-
1	PANEL SUB-ASSY, RR (SN)	BENT	1,371.80	1,371.80
1	STRIPE, RR DOOR (SN)	NECESSARY	23.20	23.20
1	STRIPE, RR DOOR (SN)	NECESSARY	37.00	37.00
1	STRIPE, RR DOOR (SN)	NECESSARY	16.30	16.30
1	PANEL SUB-ASSY (SN)	TO REPAIR SEE LABOUR	925.90	-
1	MIRROR ASSY, OUTER (SN)	TO REPAIR SEE LABOUR	1,422.00	-
10	RIVET (SN) (ADDITIONAL)	NECESSARY	21.00	21.00
			5,583.30	1,599.30
	<u>LABOUR</u>			
	CHECK WIRING & CONDUCT LEAK TEST.	NOT NECESSARY	180.00	-
	CHECK WIRING & CONDUCT LEAK TEST.		180.00	180.00
	RESET ECU UPON COMPLETION OF REPAIR.		180.00	180.00
	TRANSFER DOOR MACH.		720.00	360.00
	REPL ACC AFF AREA. STRAIGHTEN & PANEL ACC AFF AREA. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, FR, PANEL SUB-ASSY AND MIRROR ASSY, OUTER.		3,600.00	1,440.00
	RESPRAY ACC AFF AREA.		2,950.00	2,065.00
			7,810.00	4,225.00
	GRAND TOTAL		13,393.30	5,824.30



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 5,824.30

Report Ref No. CS/FCI22001084/Rty3e2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser