



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4661H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LH REFLECTOR RR BUMPER (N)	SERVICEABLE	61.90	-
1	RH REFLECTOR RR BUMPER (N)	SERVICEABLE	61.90	-
1	LH RR HATCHBACK DOOR LAMP (N)	SERVICEABLE	231.30	-
1	RH RR HATCHBACK DOOR LAMP (N)	CRACKED	231.30	231.30
1	LH RR COMB LAMP (N)	SERVICEABLE	346.90	-
1	RH RR COMB LAMP (N)	SERVICEABLE	346.90	-
1	ORNAMENT - BACK DOOR QASHQAI (N)	NECESSARY	94.40	94.40
1	EMBLEM - REAR NISSAN (N)	NECESSARY	64.90	64.90
1	PLATE - LUGGAGE REAR GARNISH (N)	SERVICEABLE	68.80	-
1	STRIKER HATCHBACK DOOR (N)	BENT	34.80	34.80
1	HATCHBACK DOOR LOCK (N)	DISTORTED	173.20	173.20
1	RUBBER DUM (N)	NECESSARY	63.80	63.80
1	GLASS - TAILGATE (N)	NECESSARY	990.00	990.00
1	WEATHER STRIP HATCHBACK DOOR (N)	SERVICEABLE	167.00	-
1	HATCHBACK DOOR CENTER MOULDING (N)	SCRATCHED	352.00	352.00
1	HATCHBACK DOOR (N)	DENTED	3,062.60	3,062.60
1	LH SIDE BRACKET RR BUMPER (N)	NECESSARY	38.90	38.90
1	RH SIDE BRACKET RR BUMPER (N)	NECESSARY	38.90	38.90
1	LH STAY RR BUMPER (N)	SERVICEABLE	141.00	-
1	RH STAY RR BUMPER (N)	SERVICEABLE	141.00	-
1	REINFORCEMENT RR BUMPER (N)	DENTED	691.50	691.50
1	ENERGY ABSORBER RR BUMPER (N)	SERVICEABLE	141.40	-
1	TOW HOOK COVER RR BUMPER (N)	SCRATCHED	18.80	18.80
10	CLIP RR BUMPER @ \$1.30 (N)	NECESSARY	13.00	13.00
1	REAR BUMPER (N)	CUT	796.70	796.70
1	RR END PANEL (N)	TO REPAIR SEE LABOUR	482.60	-
	NETT 20% DISCOUNT		-1,771.10	-1,332.96
			7,084.40	5,331.84
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SENSOR REVERSE (SN)	CUT	250.00	250.00

Report Ref No. CS/FCI22001086/Vqy3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR W/SCREEN SEALANT (SN)	NECESSARY	80.00	80.00
1	SUNDRIES (SN)	NOT WORKING	50.00	-
1	REAR LICENSE PLATE (NPA) (SN)	NOT NECESSARY	-	-
			380.00	330.00
	<b>LABOUR</b>			
	LABOUR CHARGES TO RENEW RR END PANEL, HATCHBACK DOOR & RR BUMPER, REPAIR BOTH RR FENDER. INCLUSIVE OF THE REPAIR OF RR END PANEL.		1,950.00	1,170.00
	CHARGES TO SPRAY PAINTING, RR END PANEL, RR BUMPER HATCHBACK DOOR AND BOTH RR FENDER.		1,250.00	750.00
	RENEW REAR WINDSCREEN GLASS.		180.00	180.00
	RENEW REAR WINDSCREEN GLASS SEALANT FILM.		150.00	150.00
	REMOVE AND INSTALL REVERSE CAMERA.		120.00	120.00
	REMOVE AND TRANSFER HATCHBACK DOOR MECHANISM.		80.00	80.00
	APPLY SEALANT TO RR END PANEL AND HATCHBACK DOOR.		200.00	100.00
	RENEW BOTH RR COMB LAMP AND CHECK RR WIRING SYSTEM.		48.00	48.00
	COMPUTER CHECK DIAGNOSIS.		120.00	120.00
	RENEW REVERSE SENSOR.		110.00	110.00
			4,208.00	2,828.00
<b>GRAND TOTAL</b>			<b>11,672.40</b>	<b>8,489.84</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>8,489.84</b>

Report Ref No. CS/FCI22001086/Vqy3s2

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.