

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI22001092/VQY3E2

**Date:** 17/03/2022

### REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MX003851		
<b>Claimant Vehicle No :</b>	SHC3107X	<b>Insured Vehicle No :</b>	SGG5580P		
Date of Loss:	30/01/2022	Nature of Claim:	TP	Claim No:	M2200562

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3107X	Engine No:	2ZR2G11034
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Chassis No:	JTDKB3FU103090420
Reg. Date:	20/12/2019 (Man. Year: 2019)	Odometer:	180473 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,623.57	2,322.62	5,300.95	69.53
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,450.00	1,290.00	1,160.00	47.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,084.57</b>	<b>3,623.62</b>	<b>6,460.95</b>	<b>64.07</b>
<b>+ GST 7.00/7.00% (S\$)</b>	705.92	253.65	452.27	64.07
<b>Nett Amount (S\$)</b>	<b>10,790.49</b>	<b>3,877.27</b>	<b>6,913.22</b>	<b>64.07</b>

### INSPECTION

Date of Assignment:	03/02/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	03/02/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 2 cents -Finalise confirm amount: \$3623.60

# REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2022)
<b>Parts:</b>	144	TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC3107X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*GARNISH SUB -ASSY BACK DOOR	Dented	889.70 FL	-	*889.70 FL
2	1		*REAR TRUNK	Serviceable	1,126.60 FL	-	*- FL
3	1		*REAR TRUNK COVER TRIM	Serviceable	254.40 FL	-	*- FL
4	1		*REAR TRUNK LID LOCK	Serviceable	457.90 FL	-	*- FL
5	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	52.90 FL	-	*52.90 FL
6	1		*REAR TRUNK LID LOGO (HYBIRD)	Necessary	52.40 FL	-	*52.40 FL
7	1		*REAR TRUNK LID LOGO (TOYOTA)	Necessary	60.80 FL	-	*60.80 FL
8	1		*REAR TRUNK LID GLASS W/MOULDING UPPER	Not Necessary	1,778.30 FL	-	*- FL
9	1		*REAR TRUNK LID GLASS W/MOULDING LOWER	Not Necessary	1,569.70 FL	-	*- FL
10	1		*REAR BUMPER	Dented	458.60 FL	-	*458.60 FL
11	1		*REAR BUMPER UNDER COVER	Dented	552.60 FL	-	*552.60 FL
12	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
13	2		*REAR BUMPER SIDE RETAINER LH/ RH	Necessary	225.40 FL	-	*225.40 FL
14	1		*REAR BUMPER UNDER COVER CENTRE	Serviceable	252.00 FL	-	*- FL
15	1		*TAIL LAMP UPPER RH	Serviceable	548.40 FL	-	*- FL
16	1		*TAIL LAMP LOWER RH	Serviceable	602.10 FL	-	*- FL
17	1		*REAR SMART KEY ANTENNA	Serviceable	447.10 FL	-	*- FL
18	1		*REAR BUMPER TOWING COVER	Missing	82.70 FL	-	*82.70 FL
19	1		*REAR BUMPER REINFORCEMENT	Dented	318.80 FL	-	*318.80 FL
20	1		*REAR BUMPER REVERSE SENSOR	Cut	135.70 FL	-	*135.70 FS
21	1		*REAR TRUNK LID COMFORT APP	Necessary	40.00 FL	-	*40.00 FS
22	2		*REAR TRUNK LID COMFORT /TEL NO STICKER	Necessary	120.00 FL	-	*60.00 FS
23	1		*REAR NUMBER PLATE W/HOLDER	Serviceable	50.00 FL	-	*- FL
<b>Supplementary #1</b>							
24	1		*REAR BUMPER MAT	Necessary	50.00 FS	-	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,148.10</b>	<b>3,001.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,524.53	678.98
<b>Total Parts (\$\$)</b>	<b>7,623.57</b>	<b>2,322.62</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,090.00	700.00
2	SPRAY PAINTING	New	1,000.00	500.00
3	CHECK WIRING & LIGHTING	New	90.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
5	TUFF COATING	New	90.00	30.00
6	REMOV/REPLACE REAR WINDSCREEN	New	120.00	0.00
Gross Labour Cost (\$\$)			2,450.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >