

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001096/KTY3S2**Date:** 24/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00119112101

**Claimant Vehicle No :** XE4693M **Insured Vehicle No :** YP3288L

Date of Loss: 25/01/2022 Nature of Claim: TP Claim No: SNM22D200682/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **XE4693M**

Make & Model: SCANIA P410A4X2NZ, 12.7 D (M) Engine No: HIDDEN

Reg. Date: 01/01/2019 (Man. Year: 2019) Chassis No: YS2P4X20005529140

Colour: White Odometer: 115754 km

Engine Capacity: 12742 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 315/80 R22.5 Rear Tyre Size: 315/80 R22.5 (D)

Front Left Side: OTANI 9 mm Rear Left Side: OTANI 9/9 mm

Front Right Side: OTANI 9 mm Rear Right Side: OTANI 9/9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	20,983.00	5,302.80	15,680.20	74.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,030.00	2,190.00	3,840.00	63.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>27,013.00</b>	<b>7,492.80</b>	<b>19,520.20</b>	<b>72.26</b>

**INSPECTION**

Date of Assignment: 07/02/2022

Date Inspected: 04/02/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)  
205 Braddell Road  
Singapore 579701

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 24 May 2022)	
<b>Parts:</b>	N/A	SCANIA P410A4X2NZ 12.7 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for XE4693M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH TAILLAMP ASSY	Cracked	945.00 F	*945.00 FL
2	1		*REAR RH MUD GUARD (REAR)	Buckled	592.00 F	*592.00 FL
3	1		*REAR RH MUD FLAP	Cracked	139.00 F	*139.00 FL
4	1		*REAR RH GUARD SCANIA BADGE	Scratched	139.00 F	*139.00 FL
5	1		*REAR RH MUD GUARD (CENTRE) TOP	Buckled	398.00 F	*398.00 FL
6	1		*REAR RH MUD GUARD RH RUBBER HOOK	Distorted	28.00 F	*28.00 FL
7	1		*REAR RH MUD GUARD SUPPORT BAR	Not Necessary	300.00 F	*- FL
8	1		*REAR RH MUD GUARD SUPPORT BAR BRACKET RR	Buckled	1,411.00 F	*1,411.00 FL
9	4		*REAR RH MUD GUARD SUPPORT BAR BRACKET BUSH	Serviceable	30.00 F	*- FL
10	1		*REAR RH TOP LEAF SPRING }	Repair	0.00 F	*- FL
11	10		*RR RH LEAF SPRING (1-10) }	Serviceable	5,186.00 F	*- FL
12	1		*REAR RH TOP LEAF SPRING BUSH	Serviceable	60.00 F	*- FL
13	1		*REAR RH TOP LEAF SPRING BUSH GREASE NIPPER	Serviceable	9.00 F	*- FL
14	1		*RR RH TOP LEAF SPRING BRACKET	Repair	300.00 F	*- FL
15	1		*RR RH TOP LEAF SPRING BRACKET HOUSING	Serviceable	450.00 F	*- FL
16	1		*RR RH TOP LEAF SPRING BRACKET BUSH	Serviceable	60.00 F	*- FL
17	1		*RR RH TOP LEAF SPRING BRACKET BUST GREASE NIPPER	Serviceable	9.00 F	*9.00 FL
18	1		*RR LH TOP LEAF SPRING (NPA)	Serviceable	0.00 F	*- FL
19	10		*RR LH LEAF SPRING (1-10)	Serviceable	5,186.00 F	*- FL
20	1		*REAR END CHASSIS CENTER PANEL	Repair	3,342.00 F	*- FL
21	1		*REAR AIR TANK	Dented	735.00 F	*735.00 FL
22	1		*REAR AIR TANK SUPPORT BRACKET	Bent	1,318.00 F	*1,318.00 FL
23	1		*REAR AIR TANK HOSE CONNETOR (SINGLE)	Serviceable	59.00 F	*- FL
24	1		*REAR AIR TANK HOSE CONNSTOR (DOUBLE)	Serviceable	50.00 F	*- FL
25	1		*AIR RETAINER STRIP	Missing	170.00 F	*170.00 FL
26	1		*AIR RETAINER STRIP RUBBER	Missing	8.00 F	*8.00 FL
27	2		*AIR TANK CONNECTOR RING	Serviceable	22.00 F	*- FL
28	1		*AIR TANK HOSE INSERT UNION	Serviceable	37.00 F	*- FL

F=Franchise part. L=ListItemDisc.

**Sub Total (\$\$)** 20,983.00 5,892.00  
**- List Item Discount on L Items 0.00/10.00% (\$\$)** 0.00 589.20

**Total Parts (\$\$)** 20,983.00 5,302.80

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO JACK, STRAIGHTEN REAR CHASSIS MEMBER, CROSS MEMBER, REPLACE DAMAGE PARTS AND REALIGNMENT.	New	2,800.00	2,000.00
2	TO REMOVE REAR AXLE, BOTH MULTI LEAF SPRING TO ASSIST REPAIR AND REPLACE DAMAGE PARTS.	New	2,200.00	0.00
3	TO REMOVE AND REPLACE AIR TANK AND CHECK SYSTEM.	New	100.00	80.00
4	TO CHECK LIGHTING AND WIRING.	New	60.00	20.00
5	CHECK AND ADJUST WHEEL ALIGNMENT.	New	120.00	60.00
6	TO TUFF KOTE ON REAR AFFECTED AREAS.	New	150.00	30.00
7	TO RESPRAY ON REAR AFFECTED AREA.	New	600.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>6,030.00</b>	<b>2,190.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >