



Your Ref : S2M03S77

Date: 25th Feb 2022

Our Ref : CS/ASM22001102/Vty3e2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Teo Kitty

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKW 5013D
INSURED VEHICLE: SHA 4669U
ACCIDENT ON 26/01/2022

Instruction was received to inspect the vehicle Reg. No. SKW 5013D. The inspection was conducted on 26/01/2022 at the premises of M/s Garage 13 Pte Ltd, 8 Kaki Bukit Ave 4 #03-46 Premier, Singapore 415875.

The following vehicle information was recorded:

Registration Number	: SKW 5013D
Make/Model	: Volkswagen Golf A7 1.4 TSI AT 5G13GZ SR HID
Year of Registration	: 2015
Body Colour	: Black
Chassis Number	: WVVZZZAUF356438
Engine Capacity	: 1395 cc
Speedometer Reading	: Not Available

The vehicle sustained damages at the n/s, o/s body, front portion and rooftop. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 54,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 30,099.00)
Nett Liability	<u>S\$ 23,901.00</u> =====

Vehicle Inspected By:



Thevan Thomas Karthikesavan
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.