

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



| NTUC INCOME INSURANCE CO-OPERATIVE LTD | | | Ref: | : NS/INC22001105/Rqy3n2 | | |
|--|---|--------------------|--------|-------------------------|------------|--|
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 1 189556 | | | | 17-02-2022 INC4 | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| | Insured Veh. | SKP 2686T | 1 | nspected | SHB 1217E | |
| | Policy No. | | Cover | age (\$) | 0.00 | |
| | Claim No. | MT/1159869-002 | Exces | s (\$) | 0.00 | |
| | Assign From | | Assign | n Date | 28/01/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | MG MG5 EV EXCITE T | c.c | | 0 | |
| | Engine No. | HIDDEN | Year o | f Reg. | 2021 | |
| | Chassis No. | LSJE2403XMG051373 | Colou | r | GREEN | |
| | Odometer | 24064 | Steeri | ng | IN ORDER | |
| | Brakes | IN ORDER | Modifi | cation | SPORTS RIM | |
| | General | FAIR | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 205/60 R16 | | ESTONE | 6 mm | |
| | L/H Front Tyre | 205/60 R16 | BRIDG | ESTONE | 6 mm | |
| | R/H Rear Tyre | 205/60 R16 | BRIDG | ESTONE | 6 mm | |
| | L/H Rear Tyre | 205/60 R16 | BRIDG | ESTONE | 6 mm | |
| 4. Description of Damages | | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 26/01/2022 | Inspec | tion Date | 28/01/2022 | |
| | Survey held at | • | | | | |
| | 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 | | | | | |
| 5a. Remarks | | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. Estimate Days of Repair | | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | | |