

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22001106/DQF3Q2**Date:** 12/08/2022REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC21B00027000
Claimant Vehicle No : SHC3795J **Insured Vehicle No :** SKQ8259Z
 Date of Loss: 04/02/2022 Nature of Claim: TP Claim No: DMPC2200051H.02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC3795J**
 Make & Model: HYUNDAI IONIQ EV FL SR, 1.6 (A) Engine No: G4LEKU416354
 Reg. Date: 08/01/2021 (Man. Year: 2019) Chassis No: KMHC851CVLU191816
 Colour: Blue Odometer: 152532 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,190.15	10,868.44	7,321.71	40.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,490.00	2,050.00	4,440.00	68.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,680.15	12,918.44	11,761.71	47.66
+ GST 7.00/7.00% (S\$)	1,727.61	904.29	823.32	47.66
Nett Amount (S\$)	26,407.76	13,822.73	12,585.03	47.66

INSPECTION

Date of Assignment: 07/02/2022
 Date Inspected: 07/02/2022 Inspected At: Bifrost Auto Pte Ltd (HQ)
 176 Sin Ming Drive, #03-09
 Singapore 575721
 Estimated Period of Repair: 9.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Aug 2022)
Parts:	192	HYUNDAI IONIQ EV FL SR 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC3795J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR (LH)	Bent / Dented	1,797.20 FL	*1,797.20 FL
2	1		*FRT DOOR RUBBER	Serviceable	250.00 FL	*- FL
3	1		*FRONT DOOR REGULATOR (LH)	Not Necessary	750.40 FL	*- FL
4	1		*FRONT DOOR POWER MOTOR ,LH	Not Necessary	689.20 FL	*- FL
5	1		*FRONT DOOR OUTER HANDLE (LH)	Not Necessary	234.80 FL	*- FL
6	1		*FRONT DOOR TRIM BOARD (LH)	Not Necessary	796.80 FL	*- FL
7	1		*FRONT DOOR PROTECTOR (LH)	Cut	186.20 FL	*186.20 FL
8	1		*REAR DOOR (LH)	Bent / Dented	1,789.90 FL	*1,789.90 FL
9	1		*REAR DOOR RUBBER (LH)	Not Necessary	280.00 FL	*- FL
10	1		*REAR DOOR OUTER HANDLE (LH)	Not Necessary	124.80 FL	*- FL
11	1		*REAR DOOR GEAR /REGULATOR (LH)	Not Necessary	367.84 FL	*- FL
12	1		*REAR DOOR POWER MOTOR (LH)	Not Necessary	256.80 FL	*- FL
13	1		*REAR DOOR LOCK ASSY	Not Necessary	306.40 FL	*- FL
14	1		*REAR DOOR TRIM BOARD (LH)	Not Necessary	613.60 FL	*- FL
15	1		*REAR DOOR PROTECTOR (LH)	Cut	166.20 FL	*166.20 FL
16	1		*ROCKER PANEL OUTER GARNISH	Repair	715.60 FL	*- FL
17	1		*ROCKER PANEL OUTER GARNISH CLIP	Not Necessary	65.00 FL	*- FL
18	1		*REAR BUMPER	Repair	459.40 FL	*- FL
19	1		*REAR BUMPER SIDE RETAINER (LH)	Not Necessary	85.80 FL	*- FL
20	1		*REAR BUMPER COVER CLIPS	Not Necessary	22.00 FL	*- FL
21	1		*REAR FENDER (LH)	Dented	1,768.30 FL	*1,768.30 FL
22	1		*REAR FENDER SHIELD REAR PIECE (LH)	Not Necessary	173.60 FL	*- FL
23	1		*REAR FENDER SHIELD FRT PIECE (LH)	Not Necessary	165.50 FL	*- FL
24	1		*REAR TYRE RIM (LH)	Distorted	1,124.20 FL	*1,124.20 FL
25	1		*REAR WHEEL HUP-CAP (LH)	Cut	346.40 FL	*346.40 FL
26	1		*REAR WHEELBEARING & HUB ASSY	Damaged	554.00 FL	*554.00 FL
27	1		*REAR TRAILING ARM (LH)	Distorted	265.40 FL	*265.40 FL
28	1		*REAR ASSIST (LH)	Distorted	227.90 FL	*227.90 FL
29	1		*REAR SHOCK ABSORBER (LH)	Distorted	230.50 FL	*230.50 FL
30	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	133.10 FL	*- FL
31	1		*REAR ABSORBER STOPPER (LH)	Not Necessary	137.60 FL	*- FL
32	1		*REAR ABSORBER COVER (LH)	Not Necessary	175.60 FL	*- FL
33	1		*REAR CROSSMEMBER	Not Necessary	1,468.70 FL	*- FL
34	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
35	1		*STABILIZER LINK (LH)	Not Necessary	147.30 FL	*- FL
36	1		*REAR UPPER ARM (LH)	Distorted	239.50 FL	*239.50 FL
37	1		*REAR LOWER ARM (LH)	Distorted	393.10 FL	*393.10 FL
38	1		*REAR KNUCKLE ARM (LH)	Distorted	538.10 FL	*538.10 FL
39	1		*FRONT DOOR COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
40	1		*REAR DOOR TEL NO.STICKER (LH)	Not fitted	10.00 FS	*- FS
41	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
42	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS
43	1		*REAR TYRE (LH)	Not Necessary	216.00 FS	*- FS
44	1		*DOOR CENTRE PILLAR OUTER (LH)	Dented	3,764.90 FL	*3,764.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)22,629.9413,546.80

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					4,439.79	2,678.36
Total Parts (S\$)					18,190.15	10,868.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	800.00
2	SPRAY PAINTING CHARGE	New	1,600.00	800.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
8	RE-SET REAR ABS SYSTEM	New	400.00	0.00
9	REMOVE/REFIX FUEL TANK	New	80.00	0.00
10	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
11	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
12	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
13	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
14	FOUR WHEEL ALIGNMENT	New	120.00	60.00
15	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
16	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR	New	550.00	0.00
Gross Labour Cost (\$\$)			6,490.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >