

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001109/GNY3Q2**Date:** 28/12/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00027502200

**Claimant Vehicle
No :** SMS312X**Insured Vehicle
No :** SND5508H

Date of Loss: 28/01/2022

Nature of Claim: TP

Claim
No: SNM22D200756/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMS312X**

Make & Model: HONDA SHUTTLE, 1.5 (A)

Engine No: LEB7102890

Reg. Date: 06/02/2020 (Man. Year: 2018)

Chassis No: GP72002123

Colour: White

Odometer: 0 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,686.48	4,011.60	9,674.88	70.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	2,170.00	2,100.00	49.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,956.48	6,181.60	11,774.88	65.57
Approved Total (Overridden) (\$\$)		4,900.00		
Nett Amount (\$\$)	17,956.48	4,900.00	13,056.48	72.71

INSPECTION

Date of Assignment: 18/02/2022

Date Inspected: 09/02/2022 Inspected At:

JEW Motors (HQ)

60 Jalan Lam Huat Carros Centre #03-72

Singapore 737869

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Dec 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS312X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Buckled	1,550.50 FL	*1,193.00 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	179.80 FL	*120.00 FL
3	1		*REAR TAILGATE EMBLEM	Necessary	47.40 FL	*47.40 FL
4	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	51.90 FL	*51.90 FL
5	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	52.90 FL	*52.90 FL
6	1		*REAR TAILGATE OUTER CHROME GARNISH	Not Necessary	398.80 FL	*- FL
7	2		*REAR TAILGATE REFLECTOR LAMP RH & LH	Not Necessary	984.60 FL	*- FL
8	1		*REAR TAILGATE OUTER LOCK HANDLE SWITCH	Not Necessary	299.80 FL	*- FL
9	2		*REAR TAILGATE HINGE LH & RH	Not Necessary	111.00 FL	*- FL
10	2		*REAR TAILGATE DAMPER RH & LH	Not Necessary	420.60 FL	*- FL
11	1		*REAR TAILGATE INNER HANDLE	Crumpled	30.30 FL	*30.30 FL
12	1		*REAR TAILGATE INNER TRIM BOARD	Crumpled	363.50 FL	*320.00 FL
13	1		*REAR TAILGATE LOCK ASSEMBLY	Bent	296.80 FL	*178.00 FL
14	1		*REAR TAILGATE WEATHERSTRIP	Twisted	206.30 FL	*206.30 FL
15	2		*REAR TAILLAMP ASSEMBLY RH & LH	Not Necessary	1,379.00 FL	*- FL
16	2		*REAR TAILLAMP PANEL RH & LH	Not Necessary	377.20 FL	*- FL
17	1		*REAR BUMPER	Deformed	1,150.60 FL	*936.00 FL
18	2		*REAR BUMPER REFLECTOR LH & RH	Not Necessary	156.60 FL	*- FL
19	2		*REAR BUMPER REFLECTOR GARNISH RH & LH	Not Necessary	240.00 FL	*- FL
20	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	28.80 FL	*- FL
21	2		*REAR BUMPER SIDE RETAINER RH & LH	Not Necessary	78.80 FL	*- FL
22	2		*REAR BUMPER INNER SPONGE RH & LH	Not Necessary	193.80 FL	*- FL
23	1		*REAR BUMPER EXHAUST GARNISH RH	Not Necessary	39.70 FL	*- FL
24	1		*REAR END PANEL	Dented	688.00 FL	*601.00 FL
25	2		*REAR SIDE END PANEL RH & LH	Not Necessary	840.00 FL	*- FL
26	1		*REAR END PANEL ANTENNA SENSOR	Broken	192.00 FL	*125.00 FL
27	1		*REAR END PANEL BUZZER	Not Necessary	189.10 FL	*- FL
28	1		*REAR END PANEL TOP GARNISH	Deformed	298.40 FL	*155.00 FL
29	1		*REAR FLOOR PANEL INNER TOP TOOL SPONGE	Not Necessary	253.10 FL	*- FL
30	1		*REAR FLOOR PANEL TOP TOOL TRAY	Broken	289.00 FL	*289.00 FL
31	1		*REAR FLOOR PANEL TOP JACK TOOL COVER	Broken	283.70 FL	*283.70 FL
32	1		*REAR FLOOR PANEL TOP UPHOLSTERY BOARD FRONT	Not Necessary	585.50 FL	*- FL
33	2		*REAR FENDER INNER TRIM BOARD RH & LH	Not Necessary	1,179.20 FL	*- FL
34	2		*REAR FENDER INNER SHIELD RH & LH	Not Necessary	415.60 FL	*- FL
35	2		*REAR FENDER INNER AIR VENT RH & LH	Not Necessary	130.60 FL	*- FL
36	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	198.70 FL	*- FL
37	3		*REAR EXHAUST MOUNTING	Not Necessary	118.80 FL	*- FL
38	1		*REAR EXHAUST PIPE	Not Necessary	845.20 FL	*- FL
39	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
40	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	120.00 FS	*40.00 FS
41	1		*SET REAR TAILGATE OUTER CHROME GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*REAR TAILGATE REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
43	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*20.00 FS
44	1		*SET REAR TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
46	1		*REAR BUMPER REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

12/28/22, 2:44 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*30.00 FS
48	1		*REAR TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
49	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
50	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	16,715.60
					4,929.50	
					- List Item Discount on L Items 20.00/20.00% (\$)	3,029.12
						917.90
					Total Parts (\$)	13,686.48
						4,011.60
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE & REFIX PARTS	New	1,600.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,600.00	800.00
3	WIRING & BULB CHECK	New	80.00	30.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	120.00	40.00
6	TO SEND OF DIAGNOSTIC AND RESET CONTROL UNIT	New	150.00	0.00
7	TO APPLY ANTI RUST ON AFFECTED PARTS	New	100.00	60.00
8	TO REMOVE & REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	60.00
9	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
10	TO REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS	New	150.00	120.00
11	TO REMOVE & REFIX REAR EXHAUST PIPE	New	120.00	0.00
Gross Labour Cost (\$\$)			4,270.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >