

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 3327B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER	BENT	1,439.70	1,439.70
1	SIDE DOOR ROLLER SUPPORT	DENTED / CUT	167.80	167.80
1	SIDE DOOR ROLLER SUPPORT CATCH	DENTED	65.00	65.00
1	REAR BUMPER ASSY	CRACKED	485.90	485.90
1	REAR LAMP	CRACKED	252.00	252.00
1	BRAKE DRUM	SERVICEABLE	166.60	-
1	BEARING HUB	BENT	381.50	381.50
1	LOWER SHAFT	SERVICEABLE	389.50	-
1	SIDE DOOR WINDSCREEN LH	CUT	580.00	520.00
	LESS 10% DISCOUNT		-	-331.19
			3,928.00	2,980.71
	SPECIAL NETT ITEMS			
1	SET WINDSCREEN SEALANT (SN)	NECESSARY	120.00	40.00
1	REAR BODY PANEL SEALANT (SN)	NECESSARY	60.00	30.00
1	REAR RIM (SN)	DENTED	350.00	50.00
			530.00	120.00
	<u>LABOUR</u>			
	REMOVE SIDE DOOR AND REAR FENDER WINDSCREEN.		360.00	120.00
	REMOVE INTERIOR FLOOR MATTING AND SIDE PANEL FITTING REPAIR, REFIX.		360.00	80.00
	REMOVE UNDERCARRIAFE AND RE-FIX.		350.00	60.00
	WIRINGS.		50.00	20.00
	PANEL BEATING.		1,800.00	800.00
	SPRAY PAINTING.		1,200.00	500.00
	RUSTPROOFING.		180.00	30.00
	WHEEL ALIGNMENT.		120.00	60.00
			4,420.00	1,670.00
	GRAND TOTAL		8,878.00	4,770.71

Report Ref No. CS/FCI22001119/Kqy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,800.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/FCI22001119/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser