

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22001120/RQF3E2

Date: 03/03/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00222822100
Claimant Vehicle No: SG3036R Insured Vehicle No: SND2228K
Date of Loss: 01/02/2022 Nature of Claim: TP Claim No: SNM22D200789/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SG3036R
Make & Model: VOLVO B5LH, 5.1 D (A) Engine No: D5330237
Reg. Date: 14/01/2019 (Man. Year: 2018) Chassis No: YV3T1U22XKA193076
Colour: Green Odometer: 125790 km
Engine Capacity: 5132 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Firenza 8 mm Rear Left Side: Firenza 8/8 mm
Front Right Side: Firenza 8 mm Rear Right Side: Firenza 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	322.00	322.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,100.00	2,580.00	4,520.00	63.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,422.00	2,902.00	4,520.00	60.90
+ GST 7.00/7.00% (S\$)	519.54	203.14	316.40	60.90
Nett Amount (S\$)	7,941.54	3,105.14	4,836.40	60.90

INSPECTION

Date of Assignment: 25/02/2022

Date Inspected: 08/02/2022 Inspected At:

Estimated Period of Repair: 3.0 days

TOWER TRANSIT SINGAPORE PTE LTD
(MANDAI DEPOT) (HQ)
310 Mandai Rd
Singapore 779404

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Mar 2022)	
Parts:	N/A	VOLVO B5LH 5.1 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG3036R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SOUTHCO SEALED LEVER LATCH	Scratched	80.00 F	*80.00 F
2	1		*SET REPAIR KITS / MATERIAL	Necessary	242.00 F	*242.00 F
F=Franchise part.						
Total Parts (S\$)					322.00	322.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS : - OS REAR CORNER BUMPER - SIDE PANEL - EXHAUST FLAP - PANEL ASSY - LOWER SKIRT PANEL	New	3,900.00	1,300.00
2	SPRAY PAINTING: - OS REAR CORNER BUMPER - SIDE PANEL - EXHAUST FLAP - PANEL ASSY - LOWER SKIRT PANEL	New	3,200.00	1,280.00
Gross Labour Cost (\$\$)			7,100.00	2,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >