

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 965R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED / MTG CRACKED	618.00	618.00
1	FRONT HEADLAMP RH	CUT	1,450.00	1,450.00
1	FRONT HEADLAMP LOWER BRACKET RH	SERVICEABLE	21.60	-
1	FRONT FENDER RH	BENT	384.00	384.00
1	FRONT FENDER INNER COWLING	CRACKED	68.00	68.00
1	FRONT RIM RH	DENTED	650.00	650.00
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	14.00	14.00
	LESS 10% DISCOUNT		-	-318.40
			3,205.60	2,865.60
	SPECIAL NETT ITEMS			
6	FRONT BUMPER CLIPS @\$5.00 (SN)	NECESSARY	30.00	30.00
5	FRONT FENDER INNER COWLING CLIPS @\$5.00 (SN)	NECESSARY	25.00	25.00
			55.00	55.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, FRONT BUMPER, FRONT FENDER RH, AND DAMAGE AREA.		600.00	400.00
	TO CHECK AND ADJUST HEADLAMP LH / RH FOCUS. }		120.00	20.00
	TO CHECK ALL WIRING FOR OPERATION. }		120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		120.00	30.00
	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	TO REMOVE AND REFIX FRONT TYRE TO NEW RIM.		120.00	20.00
	TO RESPRAY FRONT PORTION, FRONT BUMPER, FRONT FENDER RH AND POLISH DAMAGE AREAS.		800.00	440.00
			2,000.00	970.00
	GRAND TOTAL		5,260.60	3,890.60

Report Ref No. CS/FCI22001123/Kqf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,100.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/FCI22001123/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser