

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22001130/APA3 Q2**Date:** 02/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826_01

Claimant Vehicle No : SMW9745A **Insured Vehicle No :** SMZ452M

Date of Loss: 21/01/2022 Nature of Claim: TP Claim No: MFL2022D0000563

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW9745A**

Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B1461248

Reg. Date: 21/12/2020 (Man. Year: 2019) Chassis No: GK31351205

Colour: Blue Odometer: 51613 km

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	41,323.92	15,034.96	26,288.96	63.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,520.00	4,310.00	7,210.00	62.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,843.92	19,344.96	33,498.96	63.39
Approved Total (Overridden) (S\$)		15,500.00		
Nett Amount (S\$)	52,843.92	15,500.00	37,343.92	70.67
+ Car Rental (17.0 x S\$50.00/day) (S\$)		850.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		200.00		
Nett Liability (S\$)		16,557.45		
Global Sum Settlement (S\$)		16,500.00		

INSPECTION

Date of Assignment: 07/02/2022

Date Inspected: 08/02/2022 Inspected At:

PROVI AUTOWORKS PTE LTD (HQ)
8 Kaki Bukit Avenue 4, #02-24 Premier @ Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 15.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2022)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW9745A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Distorted	712.00 FL	*712.00 FL
2	1		*BONNET CENTER RUBBER SEAL	Not Necessary	68.00 FL	*- FL
3	1		*BONNET CENTER GARNISH	Not Necessary	169.20 FL	*- FL
4	2		*BONNET SIDE GARNISG	Not Necessary	248.00 FL	*- FL
5	2		*BONNET REBBER SEAL	Not Necessary	82.00 FL	*- FL
6	2		*BONNET STOPPER	Not Necessary	36.00 FL	*- FL
7	1		*BONNET LOCK	Not Necessary	198.20 FL	*- FL
8	2		*BONNET HINGES	Bent	224.00 FL	*224.00 FL
9	1		*BONNET INSULATOR	Not Necessary	198.00 FL	*- FL
10	1		*FRONT BUMPER	Distorted	625.20 FL	*525.00 FL
11	1		*FRONT BUMPER TOW COVER	Not Necessary	16.40 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	395.20 FL	*- FL
13	1		*FRONT BUMPER SIDE RETAINER	N/S Damaged	70.40 FL	*35.20 FL
14	1		*FRONT BUMPER LOWER GRILLE	Torn	257.00 FL	*257.00 FL
15	1		*FRONT BUMPER LOWER SIDE GRILLE	N/S Missing	272.00 FL	*136.00 FL
16	1		*FRONT BUMPER LOWER SIDE GRILLE CHROME	N/S Missing	196.00 FL	*98.00 FL
17	1		*FRONT BUMPER UNDER COVER	Not Necessary	154.00 FL	*- FL
18	1		*FRONT GRILLE	Cracked	425.00 FL	*425.00 FL
19	1		*FRONT GRILLE LOGO	Necessary	49.00 FL	*49.00 FL
20	1		*FRONT GRILLE LOGO CENTER BRACKET	Not Necessary	45.00 FL	*- FL
21	1		*FRONT GRILLE BASE	Not Necessary	458.00 FL	*- FL
22	1		*FRONT GRILLE CHROME TOP	Not Necessary	154.00 FL	*- FL
23	2		*FRONT GRILLE SIDE CHROME	Not Necessary	228.00 FL	*- FL
24	2		*FRONT FOG LAMP	Not Necessary	512.00 FL	*- FL
25	2		*FRONT FOG LAMP CHROME RING	Not Necessary	112.00 FL	*- FL
26	1		*HEADLAMP	N/S Smashed	1,794.00 FL	*897.00 FL
27	1		*HEADLAMP LOWER BRACKET	N/S Smashed	228.00 FL	*114.00 FL
28	2		*HORN	Not Necessary	159.20 FL	*- FL
29	1		*WIPER WASHER C/W MOTOR	Not Necessary	498.00 FL	*- FL
30	2		*FRONT WINDSCREEN SIDE MOULDING	Not Necessary	424.00 FL	*- FL
31	1		*FRONT FENDER	N/S Distorted	1,030.00 FL	*515.00 FL
32	1		*FRONT FENDER INNER PANEL LH	Repair	398.00 FL	*- FL
33	1		*FRONT FENDER INNER COWLING	N/S Torn	248.00 FL	*124.00 FL
34	1		*FRONT FENDER QUARTER GLASS MOULDING	N/S Necessary	374.00 FL	*187.00 FL
35	1		*FRONT EXTENTION PANEL INNER LH	Distorted	176.00 FL	*176.00 FL
36	1		*FRONT EXTENTION PANEL OUTER LH	Distorted	169.30 FL	*169.30 FL
37	1		*FRONT EXTENTION PANEL BRACKET LH	Bent	217.00 FL	*217.00 FL
38	1		*FRONT CHASSIS FRAME MEMBER LH	Repair	674.30 FL	*- FL
39	2		*AIR BAG IMPACT SENSOR	Activated	466.00 FL	*466.00 FL
40	1		*FRONT ABSORBER LH	Bent	410.20 FL	*410.20 FL
41	1		*FRONT LOWER ARM LH	Bent	269.90 FL	*269.90 FL
42	1		*FRONT KNUCKLE ARM LH	Damaged	330.40 FL	*330.40 FL
43	1		*FRONT WHEEL BEARING LH	Damaged	236.40 FL	*236.40 FL
44	1		*FRONT ORIGINAL WHEEL RIM LH	Not Necessary	985.00 FL	*- FL
45	1		*FRONT SUPPORT PANEL	Repair	698.60 FL	*- FL
46	1		*FRONT SUPPORT PANEL TOP GARNISG	Not Necessary	110.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*AIR CON CONDENSER	Not Necessary	762.80 FL	*- FL
48	2		*AIR CON CONDENSER MOUNTING RUBBER	Not Necessary	36.00 FL	*- FL
49	2		*AIR CON CONDENSER BRACKET	Not Necessary	72.00 FL	*- FL
50	1		*AIR CON SUCTION PIPE	Not Necessary	321.00 FL	*- FL
51	1		*AIR CON DISCHARGE PIPE	Not Necessary	325.00 FL	*- FL
52	1		*RADIATOR	Not Necessary	1,382.60 FL	*- FL
53	2		*RADIATOR AIR ARCH TOP	Not Necessary	90.00 FL	*- FL
54	2		*RADIATOR AIR ARCH LOWER	Not Necessary	90.00 FL	*- FL
55	2		*RADIATOR RUBBER MOUNTING	Not Necessary	50.00 FL	*- FL
56	1		*RADIATOR SPARE TANK	Not Necessary	155.60 FL	*- FL
57	1		*RADIATOR FAN MOTOR	Not Necessary	369.80 FL	*- FL
58	1		*RADIATOR FAN COWLING	Not Necessary	142.30 FL	*- FL
59	1		*RADIATOR FAN BLADE	Not Necessary	156.00 FL	*- FL
60	1		*AIR DUCT	Not Necessary	152.00 FL	*- FL
61	1		*AIR DUCT HOSE	Not Necessary	98.40 FL	*- FL
62	1		*AIR DUCT BASE LOWER	Not Necessary	65.00 FL	*- FL
63	1		*BATTERY TRAY	Cracked	166.30 FL	*166.30 FL
64	1		*BATTERY TOP BRACKET	Bent	142.10 FL	*142.10 FL
65	1		*FUSE BOX	Cut	453.20 FL	*453.20 FL
66	1		*ECU	Not Necessary	1,127.40 FL	*- FL
67	1		*DASH BOARD	Torn	1,076.30 FL	*1,076.30 FL
68	1		*FRONT PASSENGER AIR BAG	Activated	2,192.10 FL	*2,192.10 FL
69	1		*FRONT DRIVE AIR BAG	Activated	1,887.40 FL	*1,887.40 FL
70	1		*STEERING COLUMN SENSOR	Not Necessary	544.00 FL	*- FL
71	2		*FRONT SEAT BELT	Activated	1,576.40 FL	*1,576.40 FL
72	2		*FRONT SEAT BELT BUCKLE	Not Necessary	684.00 FL	*- FL
73	2		*CETER PILLAR INNER LOWER TRIM	Not Necessary	622.00 FL	*- FL
74	2		*CETER PILLAR INNER TOP TRIM	Not Necessary	494.40 FL	*- FL
75	1		*TAIL GATE	Repair	998.00 FL	*- FL
76	1		*TAIL GATE STOPPER	Not Necessary	28.50 FL	*- FL
77	1		*TAIL GATE INNER LOCK	Not Necessary	289.00 FL	*- FL
78	1		*TAIL GATE DETECTOR	Not Necessary	154.00 FL	*- FL
79	1		*TAIL GATE WEATHER STRIP	Not Necessary	154.00 FL	*- FL
80	1		*TAIL GATE INNER TRIM	Not Necessary	258.00 FL	*- FL
81	1		*TAIL GATE WINDSCREEN MOULDING	Not Necessary	110.00 FL	*- FL
82	1		*TAIL GATE REFLECTOR LH	Not Necessary	311.00 FL	*- FL
83	1		*TAIL GATE EMBLEM (FIT)	Necessary	35.00 FL	*35.00 FL
84	1		*REVERSE CAMERA	Not Necessary	854.00 FL	*- FL
85	1		*REAR BUMPER	Distorted	659.00 FL	*545.00 FL
86	1		*REAR BUMPER SIDE RETAINER	N/S Damaged	90.00 FL	*45.00 FL
87	1		*REAR BUMPER TOW COVER	Missing	42.00 FL	*42.00 FL
88	1		*REAR BUMPER SIDE GARNISH LH	Missing	121.00 FL	*121.00 FL
89	1		*REAR BUMPER REFLECTOR LH	Not Necessary	144.20 FL	*- FL
90	1		*REAR BUMPER CENTER GARNISH	Not Necessary	124.00 FL	*- FL
91	1		*TAIL LAMP LH	Cracked	489.00 FL	*489.00 FL
92	1		*TAIL LAMP PANEL LH	Buckled	315.00 FL	*315.00 FL
93	1		*ALARM BUZZER	Not Necessary	121.00 FL	*- FL
94	1		*REAR FENDER LH	Distorted	689.00 FL	*689.00 FL
95	2		*REAR FENDER INNER TOP TRIM	Not Necessary	510.00 FL	*- FL
96	1		*REAR FENDER INNER LOWER TRIM	N/S Deformed	824.00 FL	*315.00 FL
97	1		*REAR FENDER INNER SHIELD LH	Torn	89.60 FL	*89.60 FL
98	1		*REAR FENDER COWLING LH	Repeated	165.00 FL	*- FL
99	1		*REAR AIE VENT LH	Cracked	85.00 FL	*85.00 FL
100	1		*REAR QUARTER GLASS WITH MOULDING LH	Necessary	412.00 FL	*85.00 FL
101	1		*REAR END PANEL	Distorted	542.00 FL	*542.00 FL
102	1		*REAR END PANEL TOP GARNISH	Deformed	101.00 FL	*101.00 FL
103	1		*REAR FLOOR PANEL	Repair	985.00 FL	*- FL
104	1		*REAR FLOOR TOP BOARD	Not Necessary	415.00 FL	*- FL
105	1		*REAR TOOLS TOOLS BOX COMPARTMENT	Not Necessary	421.00 FL	*- FL
106	1		*REAR EXHAUST TAIL PIPE	Not Necessary	898.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	2		*REAR EXHAUST MOUNTING	Not Necessary	76.00 FL	*- FL
108	1		*REAR ABSORBER LH	Not Necessary	339.50 FL	*- FL
109	1		*REAR WHEEL BEARING LH	Damaged	452.90 FL	*452.90 FL
110	1		*REAR AXLE BEAM	Not Necessary	1,188.70 FL	*- FL
111	1		*REAR ORIGINAL WHEEL RIM LH	Not Necessary	985.00 FL	*- FL
112	1		*REAR DOOR LH	Repair	899.20 FL	*- FL
113	2		*REAR DOOR BLACK STICKER LH	Not Necessary	90.00 FL	*- FL
114	1		*REAR DOOR OUTER MOULDING LH	Not Necessary	180.80 FL	*- FL
115	1		*REAR DOOR INNER LOCK LH	Not Necessary	354.00 FL	*- FL
116	1		*REAR DOOR LOCK CATCH RH	Not Necessary	46.00 FL	*- FL
117	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	154.00 FL	*- FL
118	1		*REAR DOOR LOWER SEAL LH	Not Necessary	65.00 FL	*- FL
119	1		*REAR DOOR INNER TRIM	Not Necessary	568.00 FL	*- FL
120	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
121	1		*BONNET SEALANT	Not Necessary	60.00 FS	*- FS
122	1		*BONNET INSULATOR CLIP	Not Necessary	60.00 FS	*- FS
123	1		*FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
124	1		*FRONT BUMPER LOWER GRILLE CLIP	Not Necessary	30.00 FS	*- FS
125	1		*FRONT GRILLE CLIP	Necessary	50.00 FS	*20.00 FS
126	1		*FRONT EXTENSION PANEL INNER SEALANT	Not Necessary	70.00 FS	*- FS
127	1		*FRONT EXTENSION PANEL OUTER SEALANT	Not Necessary	70.00 FS	*- FS
128	1		*FRONT EXTENSION PANEL BRACKET SEALANT	Not Necessary	70.00 FS	*- FS
129	1		*SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
130	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
131	1		*BATTERY	Not Necessary	200.00 FS	*- FS
132	1		*CENTER PILLAR INNER LOWER TRIM CLIP	Not Necessary	40.00 FS	*- FS
133	1		*CENTER PILLAR INNER TOP TRIM CLIP	Not Necessary	40.00 FS	*- FS
134	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
135	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
136	1		*TAIL LAMP CLIP	Not Necessary	50.00 FS	*- FS
137	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
138	1		*TAIL GATE SEALANT	Not Necessary	80.00 FS	*- FS
139	1		*TAIL GATE INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
140	1		*TAIL GATE WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
141	1		*TAIL GATE WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
142	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*40.00 FS
143	1		*REAR FENDER INNER SHIELD CLIP	Necessary	60.00 FS	*20.00 FS
144	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
145	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
146	1		*FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
147	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
148	1		*REAR DOOR SEALANT	Not Necessary	80.00 FS	*- FS
149	1		*TYRE	Rear Punctured	800.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	50,897.40	18,638.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	9,573.48	3,603.74
Total Parts (\$\$)	41,323.92	15,034.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	WIRING CHECK	New	100.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSER AND REFILL AIRCON GAS	New	150.00	0.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	150.00	0.00
6	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE	New	500.00	220.00
7	REFOCUS HEADLAMP BEAM	New	200.00	0.00
8	TO JACK AND REALIGN CHASSIS MEMBER	New	400.00	0.00
9	PANEL BEATING REMOVAL AND REPLACING PARTS	New	1,800.00	1,000.00
10	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	900.00
11	TUFF COAT	New	250.00	120.00
12	WIRING CHECK	New	100.00	30.00
13	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	600.00	120.00
14	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
15	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	300.00	0.00
16	REMOVE AND REFIX TAILGATE WINDSCREEN	New	150.00	0.00
17	TRANSFER TAILGATE MECHANISM	New	150.00	0.00
18	REMOVE AND INSTALL REAR FENDER GLASS	New	150.00	60.00
19	REMOVE AND INSTALL REAR EXHAUST	New	250.00	0.00
20	TO REMOVE AND INSTALL REAR UNDERCARRIAGE	New	500.00	100.00
21	TO CHECK FOUR WHEEL ALIGNMENT	New	150.00	80.00
22	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			11,520.00	4,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >