



PHOTOCOPY

## INVOICE

TO : CHEW CHING KHUAN, BENJAMIN  
C/O: AH KOON MOTOR (1960) PTE LTD  
BLK 1001, #01-69,  
BUKIT MERAH LANE 3  
SINGAPORE 159718

Invoice No.: 1221/AK1140  
Date: 15-Jan-2022

### PARTICULARS

Vehicle Registration No.: SJX 8935 E  
Date of Loss: 23-Dec-2021  
Date of Assessment: 28-Dec-2021

### SERVICES

### FEES

1. Assessment with report Photographs -  
Including films, developing, storage and Transport.

\$450.00

**TOTAL** **\$450.00**

**SINGAPORE DOLLARS FOUR HUNDRED FIFTY ONLY**

We would appreciate your cheque crossed and made payable to:  
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

**AEON AUTO CONSULTANTS LLP**



### **AEON AUTO CONSULTANTS LLP**

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874  
Tel: +65 97687958 Fax +65 68264112 Email amas@aeonac.com.sg/amasopm@gmail.com  
Reg. No. T07LL1273E (registered with limited liability)

## AUTOMOBILE ASSESSMENT REPORT

TO: CHEW CHING KHUAN, BENJAMIN  
C/O: AH KOON MOTOR (1960) PTE LTD  
BLK 1001, #01-69,  
BUKIT MERAH LANE 3  
SINGAPORE 159718

Our Reference: 1221/AK1140  
Date: 15-Jan-2022

### ASSESSMENT OF VEHICLE NO. SJX 8935 E

DATE OF LOSS: 23-Dec-2021

We have carried out a physical assessment at **AH KOON MOTOR (1960) PTE LTD**,  
Blk 1001, #01-69, Bukit Merah Lane 3, Singapore 159718, according to your instruction  
on 28-Dec-2021 and are pleased to submit our report herewith.

### 1. VEHICLE PARTICULARS

Registration No.: SJX 8935 E  
Make & Model: MITSUBISHI LANCER 1.5 MIVEC SPORTS AT ABS D/AB  
Year of Registration: 2010  
Engine Capacity: 1499  
Chassis No.: JMYSRCY2AAU001852  
Engine No.: 4A910170866  
Colour: WHITE  
Mileage (km): 137636

### 2. VEHICLE CONDITION

Body Paint: GOOD  
Steering: SERVICEABLE  
Foot Brake: SERVICEABLE  
Parking Brake: SERVICEABLE  
Modification: NIL

### 3. TYRE PARTICULARS & CONDITION

#### Front

RH Make/Size/Thread: MICHELIN 205/55 R16 – 70%  
LH Make/Size/Thread: MICHELIN 205/55 R16 – 70%

#### Rear

RH Make/Size/Thread: MICHELIN 205/55 R16 – 70%  
LH Make/Size/Thread: MICHELIN 205/55 R16 – 70%


#### 4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the LHS portion.

#### 5. REMARKS

Market Value: Na  
Salvage Value: Na  
Repair Limit: Na

Estimated Amount: \$17,190.65  
Adjusted Amount: \$12,713.75  
Total Sum: \$10,100.00  
Estimated Repair Days: 10 days  
Date of Completion : 11-Jan-2022



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the insured vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

**ASSESSMENT REPORT FOR VEHICLE NO. SJX 8935 E**

**PARTS (LIST ITEMS)**

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT BONNET	Repair	586.00	-
1	FRONT GRILLE	Repair	257.00	-
1	FRONT LH HEADLAMP	Cracked	671.00	671.00
2	FRONT LH HEADLAMP CLIPS	Necessary	13.00	13.00
1	FRONT LH HEADLAMP LOWER BRACKET	Bent	20.00	20.00
1	FRONT BUMPER	Cracked	810.00	810.00
1	FRONT BUMPER LH FOGLAMP	Cracked	422.00	422.00
1	FRONT BUMPER LH FOGLAMP CHROME RIM	Cracked	38.00	38.00
1	FRONT BUMPER LH FOGLAMP GARNISH	Cracked	28.00	28.00
2	FRONT BUMPER INNER TOP AIR GUIDE L/R	Bent	60.00	30
2	FRONT BUMPER SIDE RETAINER L/R	Bent	40.00	40.00
1	FRONT BUMPER REINFORCEMENT	Repair	326.00	-
1	FRONT BUMPER LOWER CENTER GRILLE	Bent	73.00	73.00
1	FRONT BUMPER TOW HOOK COVER	Necessary	20.00	20.00
1	FRONT BUMPER LOWER LIP	Cracked	434.00	434.00
1	FRONT BUMPER LOWER UNDER COVER	Cracked	146.00	146.00
1	FRONT SUPPORT PANEL TOP GARNISH	Repair	50.00	-
10	FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	65.00	65.00
1	FRONT LH FENDER	Bent	486.00	486.00
1	FRONT LH FENDER INNER SHIELD	Cracked	101.00	101.00
1	FRONT LH FENDER SIGNAL LAMP	Cracked	32.00	32.00
1	FRONT LH ABS SENSOR	Faulty	415.00	415.00
1	FRONT LH DRIVE SHAFT ASSY	Repair	1,159.00	-
1	FRONT LH KNUCKLE ARM	Bent	321.00	321.00
1	FRONT LH KNUCKLE ARM BEARING	Jammed	143.00	143.00
1	FRONT LH LOWER ARM	Bent	304.00	304.00
1	FRONT LH TIE ROD	Bent	125.00	125.00
1	FRONT LH STABILIZER BAR LINK	Bent	123.00	00
1	FRONT LH DOOR	Repair	865.00	-
1	FRONT LH DOOR MIRROR ASSY	Cracked	443.50	443.50
1	FRONT LH DOOR CHECKER	Bent	28.00	28.00
2	FRONT LH DOOR HINGES (UPPER/LOWER)	Bent	76.00	76.00
1	FRONT LH DOOR MECHANISM LOCK	Repair	255.00	-
1	REAR LH DOOR	Bent	1,008.00	1,008.00
1	REAR LH DOOR FRAME BLACK STICKER	Necessary	38.00	38.00
1	REAR LH DOOR INNER TRIM BOARD	Repair	618.00	-
1	REAR LH DOOR MECHANISM LOCK	Bent	284.00	284.00
1	REAR LH DOOR WEATHER STRIP	Cut	127.00	127.00
1	LH SIDE SKIRT GARNISH	Cracked	844.00	844.00
1	REAR LH FENDER	Bent	898.00	898.00
1	REAR BUMPER	Cut	731.00	731.00
2	REAR BUMPER SIDE RETAINER L/R	Bent	40.00	40.00
1	REAR BUMPER INNER LH SIDE SHIELD	Bent	30.00	30.00
1	REAR BUMPER LOWER LH SIDE LIP	Repair	325.00	-
			13,878.50	9,437.50
Less 10% discount			1,387.85	943.75
Parts Total:			12,490.65	8,493.75

### ASSESSMENT REPORT FOR VEHICLE NO. SJX 8935 E

#### SPECIAL NETT ITEMS

1	FRONT BUMPER CLIPS - SET	Necessary	30.00	30.00
1	FRONT BUMPER RIVERT - SET	Necessary	40.00	40.00
1	FRONT LH FENDER INNER SHIELD CLIPS - SET	Necessary	30.00	30.00
1	FRONT LH 16" SPORT RIM	Bent	350.00	350.00
1	FRONT LH 205/55 R16 TYRE	Cut	180.00	180.00
1	FRONT LH DOOR INNER TRIM BOARD CLIPS - SET	Necessary	30.00	30.00
1	REAR LH DOOR INNER TRIM BOARD CLIPS - SET	Necessary	30.00	30.00
1	LH SIDE SKIRT CLIPS - SET	Necessary	30.00	30.00
1	REAR LH 16" SPORT RIM	Bent	350.00	350.00
1	REAR BUMPER CLIPS - SET	Necessary	30.00	30.00
Special Nett Total :			<u>1,100.00</u>	<u>1,100.00</u>

#### LABOUR


S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing.	120.00	100.00
2	To remove, reinstall top trim upholstery, trim garnish, trim liner.	100.00	80.00
3	To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	400.00	350.00
4	To road test driving, check and resetting wheel alignments system.	160.00	140.00
5	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00	1,000.00
6	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,500.00	1,350.00
	To apply anti-rust chemical on repaired and replaced panel.	120.00	100.00
Labour Total :		<u>3,600.00</u>	<u>3,120.00</u>
<b>TOTAL (PARTS &amp; LABOUR) \$</b>		<u>17,190.65</u>	<u>12,713.75</u>

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

**\$10,100.00**

**(SINGAPORE DOLLARS TEN THOUSAND ONE HUNDRED ONLY)**



Amas Ong  
Automobile Assessor