



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 9660R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HEADLAMP RH (WCP)	CRACKED	275.00	275.00
1	CENTER GRILLE ASSY (WCP)	CRACKED	280.00	280.00
1	CENTER GRILLE LOGO BADGE (WCP)	NECESSARY	65.00	65.00
1	FRONT BUMPER (WCP)	CUT	380.00	380.00
2	HEADLAMP LOWER PANEL GARNISH LH/RH @\$195.00 (WCP)	N/S CUT / O/S CRACKED	390.00	390.00
	COST PLUS 10%		139.00	139.00
			1,529.00	1,529.00
SPECIAL NETT ITEMS				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	35.00	30.00
1	CENTER GRILLE CLIPS (SN)	NECESSARY	30.00	20.00
1	FRONT CARPLATE WITH HOLDER (SN)	BENT	35.00	35.00
			100.00	85.00
LABOUR				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.		600.00	300.00
	TO SUPPLY PAINTS MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		400.00	200.00
	TO REMOVE AND REPAIR/REFIT WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION.		30.00	30.00
			1,030.00	530.00
GRAND TOTAL			2,659.00	2,144.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00
LESS EXCESS			-500.00
NETT LIABILITY			1,200.00

Report Ref No. CS/LPC22001133/Rvf3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.