

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001135/KTF3E2**Date:** 04/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00104772102

Claimant Vehicle No : SNC7331S **Insured Vehicle No :** SJR2012P

Date of Loss: 31/01/2022 Nature of Claim: TP Claim No: SNM22D200845/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC7331S**

Make & Model: TOYOTA COROLLA, 1.5 (A) Engine No: 2ZR2L64155

Reg. Date: 12/11/2021 (Man. Year: 2021) Chassis No: ZWE2116068868

Colour: Metallic Silver Odometer: 15506 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Toyo 9 mm Rear Left Side: Toyo 9 mm

Front Right Side: Toyo 9 mm Rear Right Side: Toyo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,544.55	3,808.72	6,735.83	63.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,830.00	1,090.00	37.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,464.55	5,638.72	7,825.83	58.12
Approved Total (Overridden) (\$\$)		4,500.00		
(\$\$)	13,464.55	4,500.00	8,964.55	66.58
+ GST 7.00/7.00% (\$\$)	942.52	315.00	627.52	66.58
Nett Amount (\$\$)	14,407.07	4,815.00	9,592.07	66.58

INSPECTION

Date of Assignment: 07/02/2022

Date Inspected: 14/02/2022 Inspected At: Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2022)
Parts:	143	TOYOTA COROLLA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC7331S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,280.40 FL	*839.50 FL
2	1		*REAR BOOTLID LOGO EMBLEM	Necessary	100.10 FL	*85.10 FL
3	1		*REAR BOOTLID COROLLA EMBLEM	Necessary	95.80 FL	*95.80 FL
4	1		*REAR BOOTLID HYBRID EMBLEM	Necessary	96.40 FL	*96.40 FL
5	1		*REAR BOOTLID OUTER GARNISH	Serviceable	516.20 FL	*- FL
6	1		*REAR BOOTLID TAILLAMP LH	Serviceable	297.30 FL	*- FL
7	1		*REAR BOOTLID TAILLAMP RH	Serviceable	297.30 FL	*- FL
8	1		*REAR BOOTLID MECHANISM LOCK	Repair	613.40 FL	*- FL
9	1		*REAR BOOTLID INNER TRIM BOARD	Serviceable	272.60 FL	*- FL
10	1		*REAR BOOTLID HINGE LH	Repair	116.10 FL	*- FL
11	1		*REAR BOOTLID HINGE RH	Repair	116.10 FL	*- FL
12	1		*REAR BOOTLID WEATHERSTRIP	Dented	307.40 FL	*307.40 FL
13	1		*REAR TAILLAMP OUTER LH	Serviceable	456.80 FL	*- FL
14	1		*REAR TAILLAMP OUTER RH	Serviceable	456.80 FL	*- FL
15	1		*REAR TAILLAMP OUTER LOWER BRACKET LH	Repair	145.70 FL	*- FL
16	1		*REAR TAILLAMP OUTER LOWER BRACKET RH	Repair	145.70 FL	*- FL
17	1		*REAR BUMPER	Buckled	1,854.60 FL	*1,218.30 FL
18	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	172.60 FL	*- FL
19	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	172.60 FL	*- FL
20	1		*REAR BUMPER LOWER	Dented	375.80 FL	*375.80 FL
21	1		*REAR BUMPER TOW HOOK COVER	Serviceable	36.30 FL	*- FL
22	1		*REAR BUMPER REFLECTOR LH	Serviceable	79.80 FL	*- FL
23	1		*REAR BUMPER REFLECTOR RH	Serviceable	79.80 FL	*- FL
24	1		*REAR END PANEL	Bent	896.10 FL	*896.10 FL
25	1		*REAR END PANEL INNER TOP GARNISH	Dented	371.20 FL	*371.20 FL
26	1		*REAR END PANEL LOCK STRIKER	Repair	47.90 FL	*- FL
27	1		*REAR SPARE TYRE PANEL	Repair	1,081.70 FL	*- FL
28	1		*REAR SPARE TYRE PANEL INNER TOP TOOLS SPONGE	Cracked	372.70 FL	*372.70 FL
29	1		*REAR SPARE TYRE PANEL INNER TOP CARD BOARD	Serviceable	609.10 FL	*- FL
30	1		*REAR EXHAUST SILENCER BOX	Repair	1,595.20 FL	*- FL
31	1		*REAR EXHAUST TOP RUBBER MOUNTING	Serviceable	75.40 FL	*- FL
32	1		*REAR EXHAUST TOP HEAT SHIELD	Serviceable	304.50 FL	*- FL
33	1		*REAR NUMBER PLATE WITH HOLDER	Dented	65.00 FS	*45.00 FS
34	1		*REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
35	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
36	1		*REAR BUMPER REVERSE SENSOR	Dented	300.00 FS	*200.00 FS
37	1		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,904.40	4,973.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,359.85	1,164.58
Total Parts (\$\$)	10,544.55	3,808.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREA	New	1,200.00	900.00
2	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA	New	1,200.00	800.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
4	TO DIAGNOSE FAULT CODE & RESET MEMORY	New	120.00	0.00
5	TO TUFF KOTE & UNDERSEAL MATERIALS	New	200.00	60.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM ETC	New	100.00	20.00
Gross Labour Cost (\$\$)			2,920.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >