

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22001136/AQF3N2**Date:** 06/05/2022**REFERENCE**

Insured/Claimant:	OH KAH LEE	Policy No:	MPC21P00120600	Claim No:	DMPC2200048H
Date of Loss:	03/02/2022	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML2396C	Engine No:	Z6759396
Make & Model:	MAZDA 3, 1.6 (A)	Chassis No:	JM6BK106280448948
Reg. Date:	27/05/2009 (Man. Year: 2008)	Odometer:	246210 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$17,500.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,224.00	7,409.60	8,814.40	54.33
Miscellaneous Items	590.00	160.00	430.00	72.88
Labour	3,100.00	1,970.00	1,130.00	36.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,914.00	9,539.60	10,374.40	52.10
Approved Total (Overridden) (S\$)		7,600.00		
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	19,914.00	6,850.00	13,064.00	65.60
+ GST 7.00/7.00% (S\$)	1,393.98	479.50	914.48	65.60
Nett Amount (S\$)	21,307.98	7,329.50	13,978.48	65.60

INSPECTION

Date of Assignment:	07/02/2022 Present Location:	Automobile Integrated Management Pte Ltd (HQ) Automobile Integrated Management Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing) Singapore 415933
Date Inspected:	08/02/2022 Inspected At:	
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2022)
Parts:	144	MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML2396C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*front bonnet (WCP)	Distorted	550.00 F	*550.00 F
2	1		*front bonnet lock (WCP)	Jammed	85.00 F	*85.00 F
3	1		*front bonnet lock bracket (WCP)	Distorted	45.00 F	*45.00 F
4	1		*front bonnet lock cable (WCP)	Jammed	68.00 F	*68.00 F
5	1		*front bonnet insulator (WCP)	Not Necessary	110.00 F	*- F
6	1		*front bonnet insulator clips @ 5.50 x 10pcs (WCP)	Not Necessary	55.00 F	*- F
7	1		*front bonnet hinges @ - L/R @ 45 x 2 pcs90 (WCP)	Bent	90.00 F	*90.00 F
8	1		*front bumper rubber - Inner (WCP)	Not Necessary	36.00 F	*- F
9	1		*front bumper rubber - Outer (WCP)	Not Necessary	48.00 F	*- F
10	1		*front bumper (WCP)	Distorted	480.00 F	*480.00 F
11	1		*front bumper tow cover (WCP)	Missing	18.00 F	*18.00 F
12	1		*front bumper grille - CTR (WCP)	Deformed	115.00 F	*115.00 F
13	1		*front bumper lower spoiler (WCP)	Cracked	550.00 F	*550.00 F
14	1		*front bumper fog lamp grille (WCP)	Not Necessary	85.00 F	*- F
15	1		*front bumper fog lamp grille base (WCP)	Not Necessary	90.00 F	*- F
16	1		*front bumper brackets - L/R @ 65 x 2pcs (WCP)	O/s Cracked	130.00 F	*65.00 F
17	1		*front bumper side retainers - L/R @ 35 x 2pcs (WCP)	Damaged	70.00 F	*70.00 F
18	1		*front bumper reinforcement (WCP)	Dented	380.00 F	*380.00 F
19	1		*front bumper chassis frame member - RH (WCP)	Repair	850.00 F	*- F
20	1		*front fender - RH (WCP)	Distorted	260.00 F	*260.00 F
21	1		*front fender bracket (WCP)	Bent	65.00 F	*65.00 F
22	1		*front fender inner shield (WCP)	Torn	115.00 F	*115.00 F
23	1		*front fender wheel housing - RH (WCP)	Repair	455.00 F	*- F
24	1		*front grille assy (WCP)	Cracked	485.00 F	*200.00 F
25	1		*front headlamps - L/R @ 650 x 2 pcs (WCP)	Cracked	1,300.00 F	*1,300.00 F
26	1		*front headlamp lower brackets - L/R @ 75 x 2 pcs (WCP)	Smashed (1 Pc only)	150.00 F	*75.00 F
27	1		*front support panel (WCP)	Cracked	420.00 F	*420.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*Air con condenser (WCP)	Bent	480.00 F	*480.00 F
29	1		*Air con discharge pipe (WCP)	Not Necessary	280.00 F	*- F
30	1		*Air con suction pipe (WCP)	Not Necessary	260.00 F	*- F
31	1		*Air con liquid pipe (WCP)	Not Necessary	220.00 F	*- F
32	1		*Air con compressor (WCP)	Not Necessary	850.00 F	*- F
33	1		*Air con compressor belt (WCP)	Not Necessary	110.00 F	*- F
34	1		*Air cleaner intake duct (WCP)	Not Necessary	95.00 F	*- F
35	1		*Air cleaner box (WCP)	Not Necessary	285.00 F	*- F
36	1		*TX oil cooler (WCP)	Not Necessary	380.00 F	*- F
37	1		*Power steering pump (WCP)	Not Necessary	680.00 F	*- F
38	1		*Power steering pump (WCP)	Not Necessary	85.00 F	*- F
39	1		*Power steering pipe - Pump to rack (WCP)	Not Necessary	320.00 F	*- F
40	1		*Power steering pipe - Oil tank (WCP)	Not Necessary	65.00 F	*- F
41	1		*Engine mounting - RH (WCP)	Damaged	240.00 F	*240.00 F
42	1		*Engine mounting - LH (WCP)	Not Necessary	220.00 F	*- F
43	1		*Engine mounting - Rear (WCP)	Not Necessary	220.00 F	*- F
44	1		*Engine undercover (WCP)	Not Necessary	135.00 F	*- F
45	1		*Radiator assy (WCP)	Cracked	480.00 F	*480.00 F
46	1		*Radiator auxiliary fan assy (WCP)	Cracked	650.00 F	*400.00 F
47	1		*Radiator top hose (WCP)	Not Necessary	45.00 F	*- F
48	1		*Radiator bottom hose (WCP)	Not Necessary	45.00 F	*- F
49	1		*Washer tank (WCP)	Deformed	120.00 F	*120.00 F
50	1		*Washer tank motor (WCP)	Not Necessary	85.00 F	*- F
51	1		*No. plate garnish (WCP)	Missing	65.00 F	*65.00 F

F=Franchise part.

Sub Total (S\$)	13,520.00	6,736.00
+ Margin on L,N Items 20.00/10.00% (S\$)	2,704.00	673.60
Total Parts (S\$)	16,224.00	7,409.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Air con oil (Bol) Necessary	60.00	30.00
2	1	front bumper clip (Set) Necessary	45.00	30.00
3	1	front fender inner shield clip (Set) Necessary	45.00	20.00
4	1	front no. plate Missing	40.00	40.00
5	1	front tyre - RH Not Necessary	280.00	0.00
6	1	Power steering fluid (Bol) Not Necessary	60.00	0.00
7	1	Radiator coolant (Bol) Necessary	60.00	40.00
Sub Total (\$\$)			590.00	160.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To check front electrical wiring	New	50.00	30.00
2	Towing charges	New	100.00	60.00
3	To remove, refix engine parts	New	200.00	80.00
4	To remove, refix front A/C condenser & refill A/C gas	New	120.00	100.00
5	To diagnos, erase fault memory after repair	New	350.00	0.00
6	To respray painting and etc	New	1,080.00	800.00
7	Panel beating, cut, weld remove & replacing above parts	New	1,200.00	900.00
Gross Labour Cost (\$\$)			3,100.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >