

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001141/BTF3N2**Date:** 05/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00071742102
Claimant Vehicle No :	SCA3353X	Insured Vehicle No :	GBJ8878E
Date of Loss:	29/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200834/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCA3353X	Engine No:	1ZRX375735
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104500773
Reg. Date:	22/01/2014 (Man. Year: 2013)	Odometer:	203183 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,250.16	7,513.92	10,736.24	58.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,750.00	2,940.00	3,810.00	56.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,000.16	10,453.92	14,546.24	58.18
Approved Total (Overridden) (\$\$)		8,350.00		
(\$\$)	25,000.16	8,350.00	16,650.16	66.60
+ GST 7.00/7.00% (\$\$)	1,750.01	584.50	1,165.51	66.60
Nett Amount (\$\$)	26,750.17	8,934.50	17,815.67	66.60

INSPECTION

Date of Assignment:	07/02/2022	
Date Inspected:	09/02/2022 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	8.0 days	

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCA3353X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Dented	867.20 FL	*781.10 FL
2	1	*BOOTLID CENTRE EMBLEM	Necessary	60.90 FL	*60.90 FL
3	1	*BOOTLID COROLLA EMBLEM	Necessary	48.20 FL	*48.20 FL
4	1	*BOOTLID ALTIS EMBLEM	Necessary	48.80 FL	*48.80 FL
5	1	*BOOTLID LOCK	Jammed	210.30 FL	*210.30 FL
6	1	*BOOTLID LOCK CATCH	Not Damaged	28.70 FL	*- FL
7	1	*BOOTLID LH LAMP	Broken	223.70 FL	*223.70 FL
8	1	*BOOTLID RH LAMP	Not Damaged	223.70 FL	*- FL
9	1	*BOOTLID RH HINGE	Not Damaged	68.90 FL	*- FL
10	1	*BOOTLID LH HINGE	Not Damaged	68.90 FL	*- FL
11	1	*BOOTLID WEATHERSTRIP	Torn	190.70 FL	*190.70 FL
12	1	*REAR BUMPER	Broken	545.10 FL	*545.10 FL
13	1	*REAR BUMPER LH REFLECTOR	Broken	40.90 FL	*40.90 FL
14	1	*REAR BUMPER LH SIDE RETAINER	Necessary	70.80 FL	*70.80 FL
15	1	*REAR BUMPER RH SIDE RETAINER	Necessary	70.80 FL	*70.80 FL
16	1	*REAR BUMPER LH CORNER BRACKET	No such part	60.30 FL	*- FL
17	1	*REAR BUMPER RH CORNER BRACKET	No such part	60.30 FL	*- FL
18	1	*REAR BUMPER INNER SPONGE	Broken	125.50 FL	*125.50 FL
19	1	*REAR BUMPER REINFORCEMENT	Bent	398.70 FL	*398.70 FL
20	1	*REAR WINDSCREEN GLASS RUBBER SEAL	Necessary	67.30 FL	*67.30 FL
21	1	*REAR LH FENDER	Dented	986.40 FL	*845.10 FL
22	1	*REAR LH FENDER SPLASH SHIELD	Torn	59.40 FL	*59.40 FL
23	1	*REAR LH FENDER PETROL COVER	Dented	103.60 FL	*85.00 FL
24	1	*REAR LH FENDER PETROL COVER LOCK	Broken	94.50 FL	*85.80 FL
25	1	*REAR LH FENDER PETROL FILLER NECK	Not Damaged	252.40 FL	*- FL
26	2	*REAR LH FENDER PETROL COVER RIVETS	Necessary	19.00 FL	*19.00 FL
27	1	*REAR LH FENDER INNER LOWER AIR VENT	Broken	140.90 FL	*125.00 FL
28	1	*REAR LH FENDER INNER TRIM BOARD	Broken	335.50 FL	*335.50 FL
29	1	*REAR LH FENDER INNER WHEEL HOUSING	Dented	299.00 FL	*189.90 FL
30	1	*REAR LH FENDER INNER PANEL	Dented	487.00 FL	*225.80 FL
31	1	*REAR LH SUB CHASSIS FRAME	Not Damaged	2,468.00 FL	*- FL
32	1	*RH TAILLAMP	Not Damaged	395.40 FL	*- FL
33	1	*RH TAILLAMP SPONGE GASKET	Not Damaged	28.40 FL	*- FL
34	1	*RH TAILLAMP PANEL	Not Damaged	374.45 FL	*- FL
35	1	*RH TAILLAMP LOWER BRACKET	Not Damaged	59.30 FL	*- FL
36	1	*END PANEL	Dented	595.80 FL	*595.80 FL
37	1	*END PANEL INNER GARNISH	Broken	210.30 FL	*210.30 FL
38	1	*SPARE TYRE LH SIDE PANEL	Not Damaged	145.00 FL	*- FL
39	1	*SPARE TYRE TOP COVER	No such part	485.10 FL	*- FL
40	1	*LH REAR DOOR	Bent	1,079.40 FL	*1,079.40 FL
41	1	*LH REAR DOOR FRAME BLACK TAPE	Necessary	73.00 FL	*40.00 FL
42	1	*LH REAR DOOR OUTER CHROME MOULDING	Necessary	144.50 FL	*109.50 FL
43	1	*LH REAR DOOR OUTER HANDLE	Not Damaged	155.00 FL	*- FL
44	1	*LH REAR DOOR OUTER HANDLE SIDE COVER	Not Damaged	52.00 FL	*- FL
45	1	*LH REAR DOOR OUTER HANDLE INNER BRACKET	Not Damaged	155.60 FL	*- FL
46	1	*LH REAR DOOR INNER TRIM BOARD	Broken	940.30 FL	*672.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*LH REAR DOOR GLASS REGULATPR GEAR	Not Damaged	265.70 FL	*- FL
48	1		*LH REAR DOOR GLASS REGULATPR GEAR MOTOR	Not Damaged	585.00 FL	*- FL
49	1		*LH REAR DOOR WEATHERSTRIP	Torn	178.40 FL	*178.40 FL
50	1		*LH REAR DOOR LOCK	Jammed	371.20 FL	*371.20 FL
51	1		*REAR LH SPORT RIM	Cut	1,044.10 FL	*450.00 FL
52	1		*REAR AXLE BEAM	Not Damaged	3,440.00 FL	*- FL
53	1		*REAR LH WHEEL BEARING	Jammed	967.00 FL	*562.00 FL
54	1		*REAR LH SHOCK ABSORBER	Bent	231.10 FL	*150.00 FL
55	1		*LH FRONT DOOR	Repair	1,102.30 FL	*- FL
56	1		*LH FRONT DOOR FRAME BLACK TAPE	Necessary	45.60 FL	*40.00 FL
57	1		*LH FRONT DOOR OUTER CHROME MOULDING	Not Necessary	133.00 FL	*- FL
58	1		*LH FRONT DOOR LOCK	Not Necessary	371.20 FL	*- FL
59	1		*SET BOOTLID INNER TRIM CLIPS	No such part	70.00 FS	*- FS
60	1		*SET BOOTLID CHROME MOULDING CLIPS	Necessary	40.00 FS	*20.00 FS
61	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
62	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
63	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
64	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
65	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
66	1		*REAR LH FENDER JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
67	1		*REAR LH FENDER INNER WHEEL HOUSING JOINT SEALANT	Necessary	50.00 FS	*20.00 FS
68	1		*REAR LH FENDER INNER PANEL JOINT SEALANT	Necessary	50.00 FS	*20.00 FS
69	1		*SET REAR LH FENDER INNER TRIM CLIPS	Necessary	70.00 FS	*30.00 FS
70	1		*SET LH TAILLAMP LOCK CLIPS	Necessary	45.00 FS	*10.00 FS
71	1		*SPARE TYRE LH SIDE PANEL JOINT SEALANT	Necessary	40.00 FS	*20.00 FS
72	1		*SET LH REAR DOOR INNER TRIM BOARD CLIPS	Necessary	70.00 FS	*30.00 FS
73	1		*SET LH FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	70.00 FS	*- FS
74	1		*LH REAR TYRE	Not Damaged	320.00 FS	*- FS
75	1		*SET REAR BUMPER REVERSE SENSOR	Short Circuit	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,838.55	9,841.90
-------------------------	------------------	-----------------

- List Item Discount on L Items 25.00/25.00% (\$\$)	5,588.39	2,327.98
--	----------	----------

Total Parts (\$\$)	18,250.16	7,513.92
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	2,400.00	1,200.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,800.00	1,200.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	120.00	50.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	180.00	0.00
5	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	120.00
6	REMOVE AND REPLACE BOOTLID INNER MECHANISM TO NEW BOOTLID	New	100.00	70.00
7	REMOVE AND REINSTALL BOOTLID REVERSE CAMERA TO ASSIST REPAIR	New	100.00	0.00
8	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS	New	100.00	60.00
9	REMOVE AND REPLACE REAR INNER TRIM,GARNISH AND BOARDS TO ASSIST REPAIR	New	240.00	80.00
10	REMOVE,REINSTALL AND REPLACE FUEL TANK,PIPES,SENSOR AND COVER TO ASSIST REPAIR	New	150.00	80.00
11	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	450.00	0.00
12	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
13	REMOVE AND REPLACE LH REAR DOOR INNER MECHANISM TO NEW DOOR	New	120.00	80.00
14	REMOVE AND REPLACE LH FRONT DOOR INNER MECHANISM TO NEW DOOR	New	120.00	0.00
15	REMOVE AND REINSTALL ROOF LINING,SEATS,CARPET AND SEAT BELTS TO ASSIST REPAIR	New	550.00	0.00
Gross Labour Cost (\$\$)			6,750.00	2,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >