



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JRD 6189

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID	DENTED	987.10	890.00
1	REAR BOOT LID TOYOTA LOGO	NECESSARY	58.90	58.90
1	REAR BOOT LID 'VIOS' EMBLEM	NECESSARY	64.20	64.20
1	REAR BOOT LID 'G' EMBLEM	NECESSARY	49.60	49.60
1	REAR BOOT LID CHROME TRIM MOULDING	DENTED	436.70	213.00
1	REAR NO. PLATE LAMP	CRACKED	83.60	83.60
1	REAR BOOT LID MECHANISM LOCK	JAMMED	438.80	220.00
2	REAR BOOT HINGE L/R @\$97.10	SERVICEABLE	194.20	-
2	REAR LAMP ASSY L/R @\$423.10	SCRATCHED	846.20	846.20
1	REAR BOOT LID WEATHERSTRIP	CUT	258.40	180.00
1	REAR BUMPER ASSY	DENTED	731.50	638.00
10	REAR BUMPER CLIPS @\$5.79	NECESSARY	57.90	30.00
2	REAR BUMPER SIDE HOLDER L/R @\$254.90	SERVICEABLE	509.80	-
2	REAR BUMPER BRACKET L/R @\$97.60	NECESSARY	195.20	195.20
1	REAR END PANEL	DENTED	915.60	719.00
1	REAR END PANEL INNER TOP GARNISH	BENT	180.70	180.70
1	REAR FLOOR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	698.70	-
1	SET REVERSE SENSOR	CUT	380.70	200.00
2	REAR BUMPER REFLECTOR L/R @\$116.80 (ADDITIONAL)	CRACKED	233.60	233.60
	LESS 25% DISCOUNT		-1,830.35	-1,200.50
			5,491.05	3,601.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR NO. PLATE (SN)	CRACKED	50.00	40.00
			50.00	40.00
<u>LABOUR</u>				
	TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTING.		120.00	40.00
	TO REMOVE, REINSTALL UPHOLSTRY, INNER TRIM GARNISHES.		250.00	50.00

Report Ref No. CS/SMR22001144/Vvf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR FLOOR SPARE TYRE PANEL.		1,600.00	800.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA.		1,200.00	800.00
			3,170.00	1,690.00
GRAND TOTAL			8,711.05	5,331.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CS/SMR22001144/Vvf3e2

THEVAN THOMAS KARTHIKESAVAN

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.