

PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Alice Low

Assign Date:	14/08/2020	Survey Date:	14/08/2020	Adjustment Date:	03/03/2021
Accident Date:	12/08/2020	TP Policy No:	NA	Our Ref:	AVS2020-24190/ID
Place of Survey:	Hiap Lek Automobile Trading 160 Sin Ming Drive #05-17 Sin Ming AutoCity Singapore 575722			Your Ref:	MT/1099793-002
				Claim Type:	Third Party
				Claimant:	Tan Shen Ching (Chen Xianjun)

Description of Vehicle:

Veh. No:	SLH5812G	Make/Model:	Honda Vezel
Colour:	White	Engine No:	NA
Engine Capacity:	NA	Chassis No:	RU31218255
Odometer:	93240	Reg. Date:	10/11/2016

Condition of Vehicle:

General:	Fair	Modification:	No	Steering:	Serviceable
Handbrake:	Serviceable	Footbrake:	Serviceable	Paint work:	Fair
Tyre Make:	Dunlop				
Front Tyre Size:	215/60R16	Front Left Side:	6mm	Front Right Side:	6mm
Rear Tyre Size:	215/60R16	Rear Left Side:	6mm	Rear Right Side:	6mm

Description of Damage:

The vehicle sustained damage on the front left portion.

Remarks:

Our recommended amount for the cost of contract lumpsum repair is S\$6,500.00 with approximately six (6) working days to complete. However, no finalisation was agreed with the repairer.



COMPLETED 05 MAR 2021

Adjuster: Idram
Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:			SLH5812G	Our Ref: AVS2020-24190/ID	
No.	Qty	Description of Parts	Condition	Third Party Surveyor's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Front bonnet	Deformed	1,020.00	1,020.00
2	2	Front bonnet side moulding RH/LH	Necessary	75.00	75.00
3	1	Front bonnet centre moulding	Necessary	85.00	85.00
4	10	Front bonnet insulator clips	Necessary	35.00	35.00
5	2	Front bonnet hinge	Bent	100.00	100.00
6	1	Front bonnet lock	Bent	128.00	128.00
7	1	Front bonnet lock bracket	Necessary	76.00	76.00
8	1	Front radiator grille	Cracked	270.00	270.00
9	1	Front radiator grille garnish	Cracked	285.00	285.00
10	1	Front radiator grille emblem 'H' logo	Necessary	28.20	28.20
11	1	Front radiator grille support bracket	Necessary	52.00	52.00
12	2	Front headlamp (HID) RH/LH	Cracked	3,718.80	1,859.00
13	2	Front headlamp lower bracket RH/LH	Bent	70.00	35.00
14	6	Front headlamp clip RH/LH	Necessary	23.40	23.40
15	1	Front bumper	Deformed	927.50	927.50
16	1	Front bumper tow cover	Deformed	20.00	20.00
17	1	Front bumper LED daylight LH	Damaged	587.10	587.10
18	1	Front bumper fog lamp cover LH	Damaged	45.00	45.00
19	1	Front bumper fog lamp LH	Damaged	327.70	327.70
20	1	Front bumper lower grille	Damaged	150.00	150.00
21	1	Front bumper lower moulding	Damaged	146.30	146.30
22	1	Front bumper lower diffuser	Damaged	195.50	195.50
23	2	Front bumper side retainer RH/LH	Necessary	46.00	23.00
24	1	Front bumper inner garnish	Deformed	70.00	70.00
25	1	Front bumper reinforcement	Bent	321.00	321.00
26	1	Front fender LH	Deformed	580.00	580.00
27	1	Front fender emblem 'Hybrid' RH	Necessary	42.50	42.50
28	1	Front fender wheel arch garnish LH	Damaged	153.00	153.00
29	1	Front support panel	Repair	520.00	--
30	1	Horn	Malfunction	110.00	110.00
31	1	Radar sensor	Not necessary	2,887.00	--
32	1	Radar sensor bracket	Not necessary	45.60	--
33	1	Air intake duct	Not necessary	65.00	--

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:				SLH5812G	Our Ref: AVS2020-24190/ID	
No.	Qty	Description of Parts	Condition	Third Party Surveyor's Estimate S\$	Our Recommendation S\$	
34	1	Air con condenser	Not necessary	750.00	--	
35	2	Air con condenser side air guide RH/LH	Not necessary	50.00	--	
36	1	Air con fan blade	Not necessary	58.00	--	
37	1	Air con fan motor	Not necessary	298.00	--	
38	1	Radiator assy	Not necessary	1,250.00	--	
39	2	Radiator top mounting	Not necessary	18.00	--	
40	1	Radiator fan cowl	Not necessary	125.00	--	
41	1	Radiator fan blade	Not necessary	60.00	--	
42	1	Radiator fan motor	Not necessary	298.00	--	
43	1	Radiator spare tank	Not necessary	60.00	--	
44	1	Front chassis LH	Not necessary	--	--	
Sub Total:				16,172.60	7,770.20	
Discount (less 20%):				3,234.52	1,554.04	
				12,938.08	6,216.16	

Special Nett Items					
1	1	Front bumper chrome cover trim set	Damaged	250.00	200.00
2	1	Front bumper clip set	Necessary	35.00	30.00
3	1	Front tyre LH	Re-use	350.00	--
Sub Total:				635.00	230.00
Total Parts Price:				13,573.08	6,446.16

Labour Cost			
1	To straighten and panel beating LH front fender inner panel, LH front door pillar and front frame members. To cut/weld front support panel. To remove and refit above parts.	1,250.00	800.00
2	To putty, re-spray painting and refit above parts.	1,000.00	800.00
3	To check and rectify wiring system.	50.00	30.00
4	To rust proof affected areas.	60.00	30.00
5	To remove, refit air-con condenser and recharge air con gas.	120.00	--
6	To remove, refit front LH tyre/ sport rim and balancing.	40.00	--
7	To conduct electircal wheel alignment test.	150.00	--
Sub Total:		2,670.00	1,660.00
Grand Total:		16,243.08	8,106.16

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2020-24190/ID

Your Ref: MT/1099793-002

Pre-repair survey - 14/08/2020



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2020-24190/ID

Your Ref: MT/1099793-002

Pre-repair survey



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2020-24190/ID

Your Ref: MT/1099793-002

Pre-repair survey



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd




120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2020-24190/ID

Your Ref: MT/1099793-002

Re-survey items - 17/08/2020



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd


120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2020-24190/ID

Your Ref: MT/1099793-002

Re-survey items



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd



120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2020-24190/ID

Your Ref: MT/1099793-002

Re-survey items



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155


Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Our Ref: AVS2020-24190/ID

Your Ref: MT/1099793-002

Re-survey items

Post repair survey - 25/08/2020



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R