



Auto Consultants

Co.Reg no: 53439395X

TAX INVOICE

Our Ref: INV/21/11/001

Date: 26/11/2021

To: Mr Muhammad Juwaidi Bin Norizan
Repairer Company: SERVE YOU MOTOR PTE LTD
Address: 5033 Ang Mo Kio Industrial Park 2 #01-265
Postal Code: 569536

Assignment Date: 23/11/2021
Inspected Vehicle No.: SMK3280B
Date of accident: 29/09/2021

DESCRIPTION	AMOUNT (\$)
PAPER SURVEY	\$ 350.00

TOTAL \$ 350.00

(DOLLARS: THREE HUNDRED AND FIFTY ONLY)

Notes:

- 1) Payment to be made via Cash Cheque or Cash
- 2) For enquiries on this invoice. Please feel free to contact us.



Official Stamp

Computer generated, Signature not required

SL Auto Consultants
Accident Claims . Survey Services . Professional Advice
Add: 129 Lorong Ah Soo #05-352 Singapore 530129
Email: slautoconsultants@gmail.com / Mobile No: 90067276



Auto Consultants

Co.Reg no: 53439395X

VEHICLE INSPECTION REPORT

Our Ref: SLVDIR/21/11/001

Date: 23/11/2021

To: Mr Muhammad Juwaidi Bin Norizan
Repairer Company: SERVE YOU MOTOR PTE LTD
Address: 5033 Ang Mo Kio Industrial Park 2 #01-265
Postal Code: 569536

REFERENCES

Claim Type:	PAPER SURVEY	Date of Accident:	29/09/2021
Third party vehicle:	SMK3280B	Date of Inspection:	23/11/2021
Insured Vehicle:	NIL		

DAMAGED VEHICLE PARTICULARS

Registration Plate No:	SMK3280B	Engine Modification:	NIL
Model/ Make:	Toyota Corolla Axio	Pre-accident damage:	NIL
Date of Registration:	27/8/2009	General Condition:	NIL
Chassis No:	NZE1416105165	General Paint Colour:	Blue
Engine No:	1NZD272819	Steering:	
Engine Capacity:	1496cc	Handbrake:	
Odometer No:	NIL	Footbrake:	

TYRES CONDITION

Front Right

Make:

Size:

Front Left

Make:

Size:

Rear Right

Make:

Size:

Rear Left

Make:

Size:

The above percentages represent the remaining life of tyre treads

SL Auto Consultants

Accident Claims . Survey Services . Professional Advice

Add: 129 Lorong Ah Soo #05-352 Singapore 530129

Email: slautoconsultants@gmail.com / Mobile No: 90067276

VEHICLE REPAIR COST

Descriptions	Repairer SGD	Adjuster SGD
Parts	\$ 10,163.50	\$ 3,838.10
Labour	\$ 3,490.00	\$ 1,840.00
Calculated Cost SGD	<u>\$ 13,653.50</u>	<u>\$ 5,678.10</u>

Recommended Lump Sum Repair Cost SGD	\$ 4,550.00
Estimate Repair Duration	4 Working Days
Survey Inspection Location	NIL
Survey Inspection Address	NIL

DESCRIPTION OF DAMAGE

The vehicle sustained damage at the front portions.

REMARKS

We have inspected the actual damages found on the vehicle and recommended the replacement of parts and repairs accordingly. The estimated repair cost is \$5678.10. The repairer has to agree to undertake the repairs at our adjusted lump sum amount of \$4550.

We have not authorized the repair. Under normal circumstances, estimated 4 working days are required.

We are pleased to advise that the inspection work was carried out accordingly and hereby submit our Inspection Report.

The inspection was conducted on a "WITHOUT PREJUDICE" basis.



Automotive Appraiser: Samuel Phun

SL Auto Consultants
Accident Claims . Survey Services . Professional Advice
Add: 129 Lorong Ah Soo #05-352 Singapore 530129
Email: slautoconsultants@gmail.com / Mobile No: 90067276

ASSESSMENT REPORT FOR VEHICLE NO: SMK3280B

LIST ITEMS

No	Qty	Description	CONDITION	REPAIRER Amount SGD	ADJUSTER Amount SGD
1	1	Front Bonnet	Dented	\$ 820.00	\$ 780.00
2	1	Front Bonnet Rubber	Necessary	\$ 48.00	\$ 48.00
3	1	Front Bonnet Hinges x 2	Serviceable	\$ 120.00	\$ -
4	1	Front Bonnet Lock	Serviceable	\$ 128.00	\$ -
5	1	Front Bonnet Insulator	Serviceable	\$ 188.80	\$ -
6	1	Front Grille 'Sport'	Cracked	\$ 500.00	\$ 450.00
7	1	Front Grille 'TRD' Emblem	Necessary	\$ 150.00	\$ 130.00
8	1	Front LHS Head Lamp HID	Serviceable	\$ 2,388.00	\$ -
9	1	Front RHS Head Lamp HID	Cracked	\$ 2,388.00	\$ 2,388.00
10	1	Front Bumper	Deformed	\$ 688.00	\$ 688.00
11	2	Front Bumper Side Retainer	Necessary	\$ 98.00	\$ 98.00
12	2	Front Bumper Fog Lamp Cover	Serviceable	\$ 120.00	\$ -
13	1	Front Bumper Sponge	Serviceable	\$ 138.00	\$ -
14	1	Front Bumper Reinforcement	Serviceable	\$ 360.00	\$ -
15	2	Front Bumper Reinforcement Stay	Serviceable	\$ 180.00	\$ -
16	1	Front Fender RHS	Buckled	\$ 388.80	\$ 388.80
17	1	Front Brace Panel	Repair	\$ 101.80	\$ -
18	1	Front Support Panel	Repair	\$ 655.00	\$ -
19	1	Condenser Assy	Serviceable	\$ 1,288.80	\$ -
20	1	Radiator Assy	Serviceable	\$ 1,388.80	\$ -
Sub-total				\$ 12,138.00	\$ 4,970.80
Less 25%				\$ 3,034.50	\$ 1,242.70
Total				\$ 9,103.50	\$ 3,728.10

SPECIAL NETT

1	1	Front Bonnet Insulator Clip Set	Necessary	\$ 30.00	\$ 30.00
2	1	Front Grille Clip Set	Necessary	\$ 40.00	\$ 20.00
3	1	Front Bumper Clip Set	Necessary	\$ 50.00	\$ 30.00
4	1	Coolant	Not Necessary	\$ 80.00	\$ -
5	1	Fender Inner Shield Clip Set	Necessary	\$ 60.00	\$ 30.00
6	1	Front Bumper Lower Spoiler	Repair	\$ 800.00	\$ -
Sub-total				\$ 1,060.00	\$ 110.00

SL Auto Consultants
Accident Claims . Survey Services . Professional Advice
Add: 129 Lorong Ah Soo #05-352 Singapore 530129
Email: slautoconsultants@gmail.com / Mobile No: 90067276

LABOUR

1	To check wiring and lighting	\$	60.00	\$	30.00
2	To remove and replace air con condensor and refill aircon gas	\$	150.00	\$	-
3	To remove and replace radiator assy and test for leakage	\$	100.00	\$	-
4	To apply under coating on repair and replace panel	\$	180.00	\$	60.00
5	To panel beat and replace damaged parts on affected areas	\$	1,500.00	\$	750.00
6	To putty and spray painting on affected areas	\$	1,500.00	\$	1,000.00
Sub-total		\$	3,490.00	\$	1,840.00
Total cost		\$	13,653.50	\$	5,678.10

