

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001156/EVY3E2

Date: 23/05/2022

REFERENCE

Insured/Claimant:	ENG KWANG CHIANG	Policy No:	7210023697		
Date of Loss:	01/02/2022	Nature of Claim:	OD	Claim No:	8316760637SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ3280Y	Engine No:	CHZC34586
Make & Model:	AUDI A3, 999cc TFSI S-TRONIC (A)	Chassis No:	WAUZZZ8V5LA007331
Reg. Date:	08/03/2021 (Man. Year: 2019)	Odometer:	24308 km
Colour:	Black		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$122,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,350.00	18,661.44	18,688.56	50.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,024.00	8,974.00	6,050.00	40.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,374.00	27,635.44	24,738.56	47.23
- Excess (S\$)	3,600.00	3,600.00	0.00	0.00
(S\$)	48,774.00	24,035.44	24,738.56	50.72
+ GST 7.00/7.00% (S\$)	3,414.18	1,682.48	1,731.70	50.72
Nett Amount (S\$)	52,188.18	25,717.92	26,470.26	50.72

INSPECTION

Date of Assignment:	08/02/2022		
Date Inspected:	07/02/2022	Inspected At:	24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	10.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	86.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	179.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	571.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	636.00 FS	*- FS
7	2		*FRONT BUMPER TRIM COVER - LH / RH	Not Necessary	364.00 FS	*- FS
8	2		*FRONT BUMPER ADAPTER - LH / RH	Not Necessary	84.00 FS	*- FS
9	1		*RADIATOR GRILLE	Broken	1,406.00 FS	*1,124.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Broken	210.00 FS	*168.00 FS
11	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
12	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
13	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	420.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	847.00 FS	*677.20 FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	211.00 FS	*- FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Broken	136.00 FS	*108.80 FS
17	2		*HORN - LH / RH	Not Necessary	426.00 FS	*- FS
18	1		*FRONT FENDER - LH / RH	N/S Dented	1,908.00 FS	*763.20 FS
19	10		*POP RIVET	Necessary	38.00 FS	*30.40 FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
21	1		*FRONT FENDER BRACKET - LH / RH	N/S Bent	92.00 FS	*36.40 FS
22	1		*FRONT FENDER BRACE - LH / RH	N/S Bent	214.00 FS	*85.60 FS
23	2		*FRONT FENDER END BRACKET - LH / RH	Not Necessary	62.00 FS	*- FS
24	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	366.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	93.00 FS	*- FS
26	1		*BONNET	Dented	3,134.00 FS	*2,507.20 FS
27	1		*BONNET ATTACHMENT PARTS	Not Necessary	172.00 FS	*- FS
28	2		*BONNET HINGE - LH / RH	Bent	136.00 FS	*108.48 FS
29	1		*BONNET EDGE PROTECTION	Necessary	31.00 FS	*24.72 FS
30	1		*BONNET STRIKER - LH / RH	O/S Bent	246.00 FS	*98.00 FS
31	1		*BONNET CATCH HOOK - UPPER	Not Necessary	100.00 FS	*- FS
32	1		*BONNET MICRO SWITCH	N/S Bent	455.00 FS	*182.00 FS
33	1		*BONNET CATCH HOOK - LOWER	Bent	71.00 FS	*56.32 FS
34	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
35	1		*BONNET BOWDEN CABLE COVER CAP	Not Necessary	11.00 FS	*- FS
36	1		*PLENUM CHAMBER	Cut	199.00 FS	*159.20 FS
37	1		*GAS FILLED STRUT	Not Necessary	110.00 FS	*- FS
38	2		*HEADLIGHT - LH / RH	Broken	10,910.00 FS	*8,728.00 FS
39	1		*HEADLIGHT POWER MODULE - LH	Not Necessary	850.00 FS	*- FS
40	1		*HEADLIGHT HEAT SINK - LH	Not Necessary	818.00 FS	*- FS
41	1		*HEADLIGHT CONTROL UNIT	Not Necessary	625.00 FS	*- FS
42	1		*HEADLIGHT HOSE - LH	Not Necessary	46.00 FS	*- FS
43	2		*LIFT CYLINDER - LH / RH	Not Necessary	312.00 FS	*- FS
44	1		*LIFT CYLINDER HOSE	Not Necessary	78.00 FS	*- FS
45	1		*WASH WATER RESERVOIR	Not Necessary	225.00 FS	*- FS
46	1		*LOCK CARRIER	Broken	806.00 FS	*644.80 FS
47	1		*A/C CONDENSER	Not Necessary	569.00 FS	*- FS
48	1		*REFRIGERANT LINE	Not Necessary	499.00 FS	*- FS
49	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
50	1		*ADDITIONAL RADIATOR	Not Necessary	959.00 FS	*- FS
51	1		*RADIATOR	Not Necessary	1,061.00 FS	*- FS
52	6		*RADIATOR COOLANT	Necessary	282.00 FS	*225.60 FS
53	1		*RADIATOR FAN RING	Not Necessary	1,464.00 FS	*- FS
54	1		*RADIATOR AIR GUIDE - LH / RH	N/S Broken	56.00 FS	*22.16 FS
55	1		*RADIATOR SEAL - RH OUTER	Not Necessary	9.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*RADIATOR AIR GUIDE - UPPER CENTER	Broken	14.00 FS	*10.88 FS
57	1		*AIR INTAKE - LOWER COVER	Broken	59.00 FS	*46.48 FS
58	1		*AIR INTAKE - UPPER COVER	Not Necessary	30.00 FS	*- FS
59	1		*AIR INTAKE HOSE	Not Necessary	69.00 FS	*- FS
60	1		*AIR INTAKE AIR GUIDE	Not Necessary	21.00 FS	*- FS
61	1		*FRONT WINDSCREEN	Broken	1,072.00 FS	*857.60 FS
62	1		*FRONT RAIN SENSOR GEL FOIL	Necessary	130.00 FS	*104.00 FS
63	1		*SPRING CLIP	Not Necessary	23.00 FS	*- FS
64	1		*PRIMER	Necessary	22.00 FS	*17.36 FS
65	2		*WINDSCREEN WATER DEFLECTOR STRIP - LH / RH	Not Necessary	208.00 FS	*- FS
66	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
67	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
68	1		*SUNDRIES	Necessary	400.00 FS	*5.60 FS
69	2		*FRONT FENDER INNER COVER - LH / RH	Not Necessary	92.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 37,350.00 18,661.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL AND FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
5	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	400.00	400.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	3,000.00
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH UPPER A-PILLARS	New	5,500.00	2,300.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
9	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	New	200.00	150.00
Gross Labour Cost (\$\$)			15,024.00	8,974.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >