

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001158/KNY3M4**Date:** 15/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00032912100

**Claimant Vehicle No :** SLE431X **Insured Vehicle No :** SKF5563Y

Date of Loss: 27/01/2022 Nature of Claim: TP Claim No: SNM22D200847/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLE431X**

Make & Model: MERCEDES-BENZ E250, 1.8 CGI (A) Engine No: 27186030011642

Reg. Date: 18/12/2009 (Man. Year: 2009) Chassis No: WDD2120472A107250

Colour: Metallic Black Odometer: 154727 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18

Front Left Side: Goodyear 8 mm Rear Left Side: Goodyear 8 mm

Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,187.95	3,522.60	1,665.35	32.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	730.00	550.00	42.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,467.95</b>	<b>4,252.60</b>	<b>2,215.35</b>	<b>34.25</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,400.00</b>		
<b>(\$\$)</b>	6,467.95	3,400.00	3,067.95	47.43
<b>+ GST 7.00/7.00% (\$\$)</b>	452.76	238.00	214.76	47.43
<b>Nett Amount (\$\$)</b>	<b>6,920.71</b>	<b>3,638.00</b>	<b>3,282.71</b>	<b>47.43</b>

**INSPECTION**

Date of Assignment: 14/02/2022

Date Inspected: 08/02/2022 Inspected At: Chew Goon Motor (AMK)  
Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2022)
<b>Parts:</b>	143	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLE431X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	1,810.00 FL	*1,680.00 FL
2	12		*REAR BUMPER CLIPS (14PCS)	Necessary	126.00 FL	*72.00 FL
3	1		*REAR BUMPER SPONGE	No such part	265.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Bent / Buckled	860.00 FL	*765.00 FL
5	2		*REAR BUMPER CENTER RETAINER (PLASTIC)	Serviceable	170.00 FL	*- FL
6	1		*REAR BUMPER CENTER CORE	Cracked	315.00 FL	*215.00 FL
7	1		*REAR BUMPER CENTER MOULDING (BLACK EDITION)	Necessary	295.00 FL	*125.00 FL
8	2		*REAR BUMPER SIDE MOULDINGS (BLACK EDITION) (@\$92.00)	Necessary	370.00 FL	*184.00 FL
9	2		*REAR BUMPER SENSORS (@\$234.00)	Shorted	570.00 FL	*468.00 FL
10	4		*REAR BUMPER SENSOR HOLDERS	Necessary	140.00 FL	*140.00 FL
11	1		*REAR BUMPER SENSOR WIRE HARNESS	Serviceable	275.00 FL	*- FL
12	2		*REAR BUMPER LOWER RETAINERS	Missing	96.00 FL	*96.00 FL
13	1		*BOOT EMBLEM (BLACK EDITION)	Necessary	85.00 FL	*85.00 FL
14	1		*BOOT BADGE E250	Necessary	84.00 FL	*84.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,461.00</b>	<b>3,914.00</b>
<b>- List Item Discount on L Items 5.00/10.00% (S\$)</b>	273.05	391.40
<b>Total Parts (S\$)</b>	<b>5,187.95</b>	<b>3,522.60</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT ELECTRICAL CHECK, REPLACE REVERSE SENSORS ETC	New	100.00	60.00
2	LABOUR CHARGE - PANEL BEATING, REPAIRING OF BOOT, END PANEL AND PART REPLACEMENT	New	580.00	220.00
3	TO RESPRAY AFFECTED AREAS	New	600.00	450.00
Gross Labour Cost (\$\$)			1,280.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >