

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22001165/KTF3E2

Date: 16/04/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001959854		
Claimant Vehicle No :	SML3684P	Insured Vehicle No :	SLH4025T		
Date of Loss:	28/01/2022	Nature of Claim:	TP	Claim No:	269270

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML3684P	Engine No:	M16A1496040
Make & Model:	SUZUKI SWIFT, 1.6 (A)	Chassis No:	JSAEZC31S00205055
Reg. Date:	16/12/2009 (Man. Year: 2009)	Odometer:	138899 km
Colour:	White		
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Falken 9 mm	Rear Left Side:	Falken 9 mm
Front Right Side:	Falken 9 mm	Rear Right Side:	Falken 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,094.15	12,508.13	4,586.02	26.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,460.00	5,415.00	3,045.00	35.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,554.15	17,923.13	7,631.02	29.86
Approved Total (Overridden) (S\$)		12,600.00		
Nett Amount (S\$)	25,554.15	12,600.00	12,954.15	50.69

INSPECTION

Date of Assignment:	07/02/2022		
Date Inspected:	08/02/2022	Inspected At:	At Auto Consultant (HQ) 113 Teck Whye Lane #05-650 Singapore 680113
Estimated Period of Repair:	22.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2022)
Parts:	144	SUZUKI SWIFT 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML3684P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	865.00 FL	*620.00 FL
2	2		*FRONT BUMPER RETAINER	Distorted	112.00 FL	*112.00 FL
3	1		*FRONT BUMPER GRILLE TOP	Distorted	156.00 FL	*156.00 FL
4	1		*FRONT BUMPER GRILLE LOWER	Distorted / Cracked	135.00 FL	*135.00 FL
5	1		*FRONT GRILLE EMBLEM SUZUKI	Necessary	65.00 FL	*65.00 FL
6	2		*FRONT BUMPER FOG LAMP GARNISH LH / RH	Cracked	284.00 FL	*284.00 FL
7	2		*HEAD LAMP LH / RH	Mtg Cracked	1,072.00 FL	*1,072.00 FL
8	1		*FRONT FENDER LH	Buckled	420.00 FL	*420.00 FL
9	1		*FRONT FENDER EMBLEM VVT	Necessary	56.00 FL	*56.00 FL
10	1		*BONNET	Bent	702.00 FL	*702.00 FL
11	1		*BONNET LOCK	Distorted	136.00 FL	*136.00 FL
12	1		*FRONT REINFORCEMENT	Bent	312.00 FL	*230.00 FL
13	1		*FRONT REINFORCEMENT GARNISH	Cracked	223.00 FL	*155.50 FL
14	1		*FRONT SUPPORT PANEL	Buckled	657.00 FL	*494.30 FL
15	1		*FRONT CHASSIS EXTENDER LH	Bent	85.00 FL	*85.00 FL
16	1		*CONDENSER	Bent	698.00 FL	*628.00 FL
17	1		*RADIATOR	Bent	789.00 FL	*789.00 FL
18	4		*RADIATOR MOUNTING RUBBER	Distorted	72.00 FL	*72.00 FL
19	2		*RADIATOR SIDE COVER LH / RH	Cracked	130.00 FL	*130.00 FL
20	2		*FRONT MUDFLAP LH / RH	Serviceable	202.00 FL	*- FL
21	1		*BOOTLID	Bent	903.00 FL	*868.00 FL
22	1		*BOOTLID EMBLEM SUZUKI	Necessary	65.00 FL	*65.00 FL
23	1		*BOOTLID EMBLEM SWIFT	Necessary	65.00 FL	*65.00 FL
24	1		*BOOTLID EMBLEM SPORT	Necessary	65.00 FL	*65.00 FL
25	1		*BOOTLID LOCK	Jammed	156.00 FL	*156.00 FL
26	1		*BOOTLID WEATHERSTRIP (\$165.00) (50%)	Cut	140.25 FS	*82.50 FS
27	1		*BOOTLID INNER TRIM	Serviceable	289.00 FL	*- FL
28	1		*REAR BUMPER	Torn	863.00 FL	*605.00 FL
29	1		*REAR BUMPER LOWER DIFUSER	Missing	278.00 FL	*278.00 FL
30	1		*REAR BUMPER LOWER DIFUSER CENTER COVER	Missing	65.00 FL	*65.00 FL
31	2		*REAR BUMPER SIDE BRACKETS LH / RH	Distorted / Cracked	112.00 FL	*112.00 FL
32	1		*REAR BUMPER SUPPLY CABLE	Serviceable	169.00 FL	*- FL
33	1		*REAR FENDER RH	Repair	735.00 FL	*- FL
34	2		*REAR FENDER INNER TRIM LH / RH	Deformed	1,126.00 FL	*442.40 FL
35	1		*TAIL LAMP LH / RH	O/S Cracked	602.00 FL	*301.00 FL
36	2		*TAIL LAMP POCKET PANEL LH / RH	Serviceable	270.00 FL	*- FL
37	1		*KEY REMOTE SENSOR	Serviceable	103.00 FL	*- FL
38	1		*REAR END PANEL	Bent	455.00 FL	*395.60 FL
39	1		*REAR END PANEL TOP GARNISH	Cracked	169.00 FL	*169.00 FL
40	1		*REAR FLOOR PANEL	Bent	689.00 FL	*689.00 FL
41	1		*REAR FLOOR PANEL TOW PIN PANEL	Repair	123.00 FL	*- FL
42	1		*REAR FLOOR SIDE PANEL LH	Repair	135.00 FL	*- FL
43	2		*REAR CHASSIS EXTENDER LH / RH	Repair	178.00 FL	*- FL
44	4		*REAR EXHAUST HOOK RUBBER	Distorted	80.00 FL	*80.00 FL
45	1		*REAR FLOOR PANEL TOP CUSHION COVER	Deformed	369.00 FL	*369.00 FL
46	1		*REAR FLOOR PANEL TOOL BOX GARNISH	Dented	198.00 FL	*198.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*EXHAUST MUFFLER	Bent	982.00 FL	*653.00 FL
48	1		*EXHAUST CATALYTIC CONVENTER MID PIPE	Bent	1,356.00 FL	*1,128.00 FL
49	1		*REAR AXLE	Bent	1,563.00 FL	*1,102.00 FL
50	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
51	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
52	2		*SET REAR FENDER INNER TRIM CLIPS	Necessary	80.00 FS	*80.00 FS
53	1		*SET REAR REVERSE SENSOR	Torn	320.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,994.25	14,630.30
- List Item Discount on L Items 15.00/15.00% (\$\$)	2,900.10	2,122.17
Total Parts (\$\$)	17,094.15	12,508.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	3,600.00	2,400.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	2,200.00	2,000.00
3	WIRING CHARGES	New	100.00	40.00
4	RE-ALIGNMENT OF FRONT CHASSIS	New	300.00	0.00
5	RE-ALIGNMENT OF REAR CHASSIS }	New	300.00	250.00
6	REPAIR OF REAR CHASSIS FRAME LH / RH }	New	300.00	0.00
7	R/R REAR WINDSCREEN	New	200.00	120.00
8	AIRCON GAS	New	80.00	80.00
9	RADIATOR FLUID	New	80.00	25.00
10	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	New	300.00	180.00
11	R/R REAR PASSENGER SEAT & AFFECTED AREA TO FACILIATE HOT WORK	New	500.00	120.00
12	R/R REAR AXLE	New	500.00	200.00
Gross Labour Cost (\$\$)			8,460.00	5,415.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >