6/27/22, 10:10 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22001166/KTY3N2

27/06/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00135932101

Claimant Vehicle

GBD7963E

Insured Vehicle YP7922M

No:

No:

Date of Loss:

27/01/2022 Nature of Claim: TP

Claim No:

Odometer:

SNM22D200668/C02/IRENE

160988 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBD7963E Reg No:

MERCEDES-BENZ CITAN, 1.2 112 6G-DCT (A) K9KB608D366199 Make & Model: Engine No: Reg. Date: 30/04/2015 (Man. Year: 2014) Chassis No: WDF4156052U149903

Colour: Metallic Grey

Engine Capacity: 1461 cc N/A Market Value/New Car Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: West Lake 8 mm Champiro 9 mm Champiro 9 mm Front Right Side: Rear Right Side: West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,764.70	3,456.00	308.70	8.20
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,730.00	1,230.00	1,500.00	54.95
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,494.70	4,686.00	1,808.70	27.85
	Approved Total (Overridden) (S\$)		3,700.00		
	Nett Amount (S\$)	6.494.70	3.700.00	2.794.70	43.03

INSPECTION

Date of Assignment: 07/02/2022

BLK 1 SIN MING INDUSTRIAL SECTOR C

Date Inspected: 14/03/2022 Inspected At: #01-135

REPAIRER: AT AUTO CONSULTANT

Estimated Period of Repair: 5.0 days

DENISE TAY KWEE CHENG Adjuster: KENNETH KONG Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/27/22, 10:10 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 27 Jun 2022)

Parts: N/A MERCEDES-BENZ CITAN 1.2 112 6G-DCT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBD7963E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Dented	1,070.00 FL	*1,070.00 FL
2	1		*REAR BUMPER REFLECTOR RH	Cracked	132.00 FL	*132.00 FL
3	1		*REAR BUMPER LID RH	Mtg Cracked	243.00 FL	*243.00 FL
4	1		*REAR BUMPER RETAINER RH	Serviceable	189.00 FL	*- FL
5	1		*TAIL LAMP RH	Broken	235.00 FL	*235.00 FL
6	1		*TAIL LAMP TOP PANEL RH	Repair	154.00 FL	*- FL
7	1		*REAR FENDER	Bent	2,160.00 FL	*2,160.00 FL
F=Fra	nchise	part. L=ListIte	mDisc.	_		
				Sub Total (S\$)	4,183.00	3,840.00
			- List Item Discount	418.30	384.00	
				Total Parts (S\$)	3,764.70	3,456.00

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	1,500.00	700.00
2	SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	450.00
3	APPLY PUTTY AND ANTO-CORROSION TO AFFECTED PARTS	New	150.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	50.00
	Gross Labour Cost (S\$)		2,730.00	1,230.00
	Report was unsubmitted during the	is print-out.		

< END OF ESTIMATES >