



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 23A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT COVER	BENT	1,583.00	1,583.00
1	REAR BUMPER	BENT	910.00	910.00
1	REAR TAIL LAMP R/H	CRACKED	585.00	585.00
1	REAR PANEL	BENT	790.00	790.00
2	REAR BUMPER REVERSE SENSOR @\$145.00	SHORTED	290.00	290.00
1	REAR BUMPER LOWER PROTECTOR	DENTED	178.00	178.00
1	REAR R/H EXHAUST SILENCER BOX	BENT	1,058.00	1,058.00
1	REAR R/H EXHAUST CHROME TIP	DENTED	280.00	280.00
1	REAR BUMPER CHROME PROTECTOR	SERVICEABLE	115.00	-
1	REAR BUMPER REINFORCEMENT	BENT	480.00	480.00
1	REAR NUMBER PLATE BRACKET	SERVICEABLE	39.00	-
	LESS 10% DISCOUNT		-	-615.40
			6,308.00	5,538.60
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN) }	DENTED	88.00	45.00
1	REAR NUMBER PLATE HOUSING (SN) }		45.00	-
			133.00	45.00
	<u>LABOUR</u>			
	FOR PUTTY & RESPRAY PAINTING : REAR BOOT COVER INNER SPARE TYRE HOUSING		900.00	660.00
	WORKMANSHIP FOR REPLACE DAMAGED PARTS & RESTRAIGHTEN BODY WORK.		1,800.00	600.00
			2,700.00	1,260.00
	GRAND TOTAL		9,141.00	6,843.60



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,450.00
---	--	--	----------

Report Ref No. CS/FCI22001167/Ktf3e2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.