

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref:	CS/FCI22001167/Ktf3e2
36 ROBINSON ROAD		Date:	25/02/2022
#16-01 CITY HOUSESINGAPORE 068877		Code:	FCI2
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 7018D	Veh. Inspected	SLH 23A
Policy No.		Coverage (\$)	0.00
Claim No.	D22000354MFCV	Excess (\$)	0.00
Assign From	RACHELWU LIMEI	Assign Date	08/02/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ CLA180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD1173422N137831	Colour	METALLIC SILVER
Odometer	110811 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	CONTINENTAL	7 mm
L/H Front Tyre	225/40 R18	CONTINENTAL	7 mm
R/H Rear Tyre	225/40 R18	CONTINENTAL	7 mm
L/H Rear Tyre	225/40 R18	CONTINENTAL	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/02/2022	Inspection Date	10/02/2022
Survey held at	TENG MENG MOTOR SERVICE 176 SIN MING DRIVE SIN MING AUTOCARE #04-01 & #04-10 SINGAPORE 575721		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	