

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001169/RTY3N2**Date:** 06/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00103812100

Claimant Vehicle No : SMN4044U **Insured Vehicle No :** SMT8698A

Date of Loss: 02/02/2022 Nature of Claim: TP Claim No: SNM22D200897/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN4044U**

Make & Model: HYUNDAI AD AVANTE, 1.6 GLS S (A) Engine No: G4FGKU190791

Reg. Date: 07/08/2019 (Man. Year: 2019) Chassis No: KMHD841CMLU964227

Colour: White Odometer: 26907 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm

Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,528.24	430.00	2,098.24	82.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	590.00	1,560.00	72.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,678.24	1,020.00	3,658.24	78.20
Approved Total (Overridden) (\$\$)		800.00		
Nett Amount (\$\$)	4,678.24	800.00	3,878.24	82.90

INSPECTION

Date of Assignment: 09/02/2022

Date Inspected: 08/02/2022 Inspected At: Nineteen Autowerks Pte Ltd - Woodlands (HQ)
39 Woodlands Close, MEGA@Woodlands #01-24
Singapore 737856

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 May 2022)

Parts: 143 HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMN4044U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	988.50 FL	*500.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	211.20 FL	*- FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	138.40 FL	*- FL
4	1		*REAR BUMPER LOWER COVER	Not Necessary	319.00 FL	*- FL
5	1		*REAR BUMPER INNER SPONGE	Not Necessary	162.80 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Not Necessary	328.00 FL	*- FL
7	2		*REAR BUMPER BRACKET	Not Necessary	312.40 FL	*- FL
8	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
9	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
10	1		*REVERSE SENSOR	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,020.30	530.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	492.06	100.00
Total Parts (\$\$)	2,528.24	430.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	300.00
2	SPRAY PAINTING	New	800.00	200.00
3	REMOVE & REFIT REVERSE SENSOR	New	100.00	60.00
4	TO APPLY UNDERCOATING FOR RUST ROOFING	New	150.00	0.00
5	CHECK WIRING SYSTEM AFTER DISCONNECT & CONNECT	New	100.00	30.00
Gross Labour Cost (\$)			2,150.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >