



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 3950T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (WCP)	BUCKLED	190.00	190.00
1	LH FRONT BUMPER SIDE RETAINER (WCP)	DISTORTED	35.00	35.00
1	LH FRONT BUMPER FOGLAMP (WCP)	SERVICEABLE	135.00	-
1	LH FRONT BUMPER FOGLAMP COVER (WCP)	SERVICEABLE	55.00	-
10	FRONT BUMPER CLIPS @\$1.50 (WCP)	NECESSARY	15.00	15.00
1	LH HEADLAMP ASSY (WCP)	CRACKED	650.00	650.00
	COST PLUS 10%		108.00	89.00
			1,188.00	979.00
	<u>LABOUR</u>			
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.		400.00	250.00
	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.		50.00	20.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		450.00	280.00
	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	NOT NECESSARY	100.00	-
			1,000.00	550.00
	GRAND TOTAL		2,188.00	1,529.00
	RECOMMENDED COST OF REPAIRS			1,529.00
	LESS EXCESS			-500.00
	NETT LIABILITY			1,029.00

Report Ref No. CS/UOI22001173/Kvf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.