



Aspire 3

DDR4



Win

Fast

100401

LKK

K. Kim Hin AUTO PTE LTDCO. REG. NO: 199402370D
GST NO: M2-0123250-3**金興(興)汽車私人有限公司**160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sgYour Reference : DHOM110178172100
Accident Date : 26-Jan-2022

No. : 32199

Date : 07-Feb-2022

Our Ref : 021617 / MH

PAGE : 1

WONG YOKE EU (MDM)
C/O UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD
#28-01
SPRINGLEAF TOWER
Singapore 079909

NOT Authorized

Lily B

81529.00 Primary After Pairs

Part by Part

Ex 850dp 3 days

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6L (2014) SKQ3950T

- 1 pc front bumper
- 1 pc LH front bumper side retainer
- 1 pc LH front bumper foglamp
- 1 pc LH front bumper foglamp cover
- 10 pcs front bumper clips
- 1 pc LH headlamp assy

Bu	190.00	c	✓
DI	35.00	c	✓
Sm	135.00	c	✓
Sm	55.00	c	✓
cc	15.00	c	✓
cm	650.00	c	✓

@ S\$ 1.50

1,080.00

Add 10% :

108.00

1,188.00

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

400.00 250

To focus headlamps. To check front
wiring and lighting operation.

50.00 20

To putty and respray on affected
portions.

450.00 280

To conduct front wheel alignment
test.

100.00 X

Total : S\$ 2,188.00

Singapore Dollars Two Thousand One Hundred and
Eighty Eight Only

Note: Amount quoted above is subject to prevailing

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

port Format :

Interview (\$

Tech Invs (\$

F.P.S

Others