

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22001174/BQF3E2

Date: 05/04/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001405102		
Claimant Vehicle No :	SMP5766C	Insured Vehicle No :	SFG5039Z		
Date of Loss:	29/01/2022	Nature of Claim:	TP	Claim No:	269499

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP5766C	Engine No:	L13B3932848
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Chassis No:	GK33418358
Reg. Date:	01/10/2019 (Man. Year: 2019)	Odometer:	77663 km
Colour:	Grey		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 3 mm	Rear Left Side:	Yokohama 3 mm
Front Right Side:	Yokohama 3 mm	Rear Right Side:	Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,558.64	3,005.84	2,552.80	45.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,490.00	1,360.00	47.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,408.64	4,495.84	3,912.80	46.53
Approved Total (Overridden) (S\$)		3,600.00		
Nett Amount (S\$)	8,408.64	3,600.00	4,808.64	57.19

INSPECTION

Date of Assignment:	09/02/2022	FC AUTO GARAGE PTE LTD (HQ)
Date Inspected:	08/02/2022 Inspected At:	8 Kaki Bukit Ave 4 #04-03, Premier @ Kaki Bukit
Estimated Period of Repair:	5.0 days	Singapore 415875

Adjuster: Lim Teow Guan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Mar 2022)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP5766C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	879.20 FL	*779.20 FL
2	1		*TAILGATE WEATHERSTRIPE	Distorted	102.30 FL	*92.30 FL
3	1		*TAILGATE GARNISH	Broken	298.40 FL	*258.00 FL
4	1		*TAILGATE LOGO	Necessary	49.40 FL	*28.00 FL
5	1		*TAILGATE EMBLEM - FIT	Necessary	55.90 FL	*28.50 FL
6	1		*TAILGATE LOCK	Jammed	217.20 FL	*90.00 FL
7	1		*TAILGATE INNER TRIM BOARD	Broken	128.20 FL	*128.20 FL
8	1		*TAILGATE DAMPER LH	Not Damaged	113.20 FL	*- FL
9	1		*TAILGATE DAMPER RH	Not Damaged	113.20 FL	*- FL
10	2		*TAILGATE STOPPER	Not Necessary	25.80 FL	*- FL
11	1		*TAIL GATE INNER LAMP LH	Not Damaged	109.20 FL	*- FL
12	1		*TAILGATE INNER LAMP RH	Not Damaged	109.20 FL	*- FL
13	1		*REAR BUMPER	Dented	629.50 FL	*510.00 FL
14	1		*REAR BUMPER RETAINER LH	Necessary	38.70 FL	*25.70 FL
15	1		*REAR BUMPER RETAINER RH	Necessary	38.70 FL	*25.70 FL
16	1		*REAR BUMPER DIFFUSER	Not Damaged	88.40 FL	*- FL
17	1		*REAR BUMPER SIDE GARNISH (LH)	Not Damaged	56.10 FL	*- FL
18	1		*END PANEL	Dented	490.00 FL	*341.60 FL
19	1		*END PANEL TOP GARNISH	Broken	180.60 FL	*71.60 FL
20	1		*REAR FENDER (LH)	Repair	708.20 FL	*- FL
21	1		*REAR FENDER INNER SHIELD (LH)	Torn	113.70 FL	*99.00 FL
22	1		*SPARE TYRE COMPARTMENT BOARD	Not Damaged	280.70 FL	*- FL
23	1		*SPARE TYRE COMPARTMENT	Not Damaged	220.40 FL	*- FL
24	1		*REAR FENDER INNER TRIM	Broken	300.70 FL	*224.00 FL
25	1		*TAIL LAMP (LH)	Broken	394.20 FL	*290.00 FL
26	1		*TAIL LAMP RH	Broken	394.20 FL	*290.00 FL
27	1		*TAIL LAMP PANEL (LH)	Dented	125.50 FL	*125.50 FL
28	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*TAILGATE PROTECTOR STRIP	Necessary	80.00 FS	*30.00 FS
30	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
31	1		*REAR BUMPER REVERSE SENSOR	Short Circuit	280.00 FS	*100.00 FS
32	1		*REAR FENDER MUDGUARD LH	Broken	90.00 FS	*90.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,810.80	3,687.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,252.16	681.46
Total Parts (\$\$)	5,558.64	3,005.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS, INCLUSIVE OF REPLACEMENT PARTS	New	1,000.00	600.00
2	LABOUR TO SPRAY PAINT AFFECTED AREAS	New	1,200.00	600.00
3	TO RUST PROOF AFFECTED AREA	New	60.00	0.00
4	DISMANTLE AND TRANSFER TAILGATE FITTINGS AND MECHANISM TO NEW BOOT LID / FACILITATE REPAIR	New	100.00	80.00
5	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	60.00	0.00
6	DISCONNECT AND CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKET	New	60.00	30.00
7	REMOVE AND REFIT END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	80.00	0.00
8	REMOVE AND REFIT REVERSE SENSOR	New	60.00	60.00
9	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	150.00	120.00
10	TO REALIGN REAR EXHAUST SYSTEM	New	80.00	0.00
Gross Labour Cost (\$\$)			2,850.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >