

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22001178/BTF3N2**Date:** 07/04/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001960072
Claimant Vehicle No :	SKN9573A	Insured Vehicle No :	SLK854C
Date of Loss:	31/01/2022	Nature of Claim:	TP
		Claim No:	269513

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN9573A	Engine No:	B004J723N13B16A
Make & Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)	Chassis No:	WBA3A16070NS37611
Reg. Date:	01/08/2014 (Man. Year: 2014)	Odometer:	109819 km
Colour:	Brown		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	Maxxis 5 mm	Rear Right Side:	Maxxis 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,683.75	4,699.20	3,984.55	45.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	2,010.00	2,040.00	50.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,733.75	6,709.20	6,024.55	47.31
Approved Total (Overridden) (S\$)		4,050.00		
(S\$)	12,733.75	4,050.00	8,683.75	68.19
+ GST 7.00/7.00% (S\$)	891.36	283.50	607.86	68.19
Nett Amount (S\$)	13,625.11	4,333.50	9,291.61	68.19

INSPECTION

Date of Assignment:	09/02/2022	
Date Inspected:	21/02/2022 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

SPECIAL REMARKS

FOR MANDATE ONLY

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Apr 2022)
Parts:	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN9573A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR DOOR	Dented	1,341.00 FL	*1,341.00 FL
2	1		*RH REAR DOOR WEATHERSTRIP	Necessary	168.00 FL	*168.00 FL
3	1		*RH REAR DOOR LOCK	Not Damaged	387.00 FL	*- FL
4	1		*RH SIDE ROCKER PANEL GARNISH	Broken	477.00 FL	*477.00 FL
5	1		*RH REAR FENDER	Dented	1,587.00 FL	*1,295.80 FL
6	1		*REAR BUMPER	Broken	1,208.00 FL	*1,020.10 FL
7	4		*REAR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	28.00 FL	*28.00 FL
8	1		*RH REAR LOWER ARM	Not Damaged	311.00 FL	*- FL
9	1		*RH REAR KNUCKLE ARM	Not Damaged	1,080.00 FL	*- FL
10	1		*RH REAR SHOCK ABSORBER	Not Damaged	372.00 FL	*- FL
11	1		*RH REAR WHEEL BEARING	Jammed	304.00 FL	*304.00 FL
12	1		*RH REAR CONTROL ARM	Not Damaged	102.00 FL	*- FL
13	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
14	1		*REAR WINDSCREEN GLASS SPONGE SEAL	Necessary	50.00 FS	*30.00 FS
15	1		*RH REAR SPORT RIM (LOCAL REPAIR)	Cut	1,050.00 FS	*200.00 FS
16	1		*RH REAR TYRE	Not Necessary	380.00 FS	*- FS
17	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
18	1		*BRAKE FLUID (FOR BRAKE BLEEDING AFTER REMOVE UNDERCARRIAGE)	Not Necessary	60.00 FS	*- FS
19	1		*SET RH SIDE ROCKER PANEL GARNISH CLIPS	Necessary	7.00 FS	*7.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,052.00	4,930.90
- List Item Discount on L Items 5.00/5.00% (\$\$)	368.25	231.70
Total Parts (\$\$)	8,683.75	4,699.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,200.00	800.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	50.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	0.00
5	REMOVE AND REINSTALL RH REAR DOOR INNER MECHANISM TO NEW DOOR	New	150.00	80.00
6	REMOVE AND REINSTALL RH REAR FENDER INNER TRIMS,BOARDS,ROOF LINING,CARPET AND GARNISH TO ASSIST REPAIR	New	350.00	150.00
7	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	120.00
8	REMOVE AND REINSTALL REAR BUMPER REVERSE SENSOR TO ASSIST REPAIR	New	70.00	60.00
9	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	450.00	0.00
10	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
11	REMOVE AND REINSTALL FUEL TANK,PIPES,HOSES AND SENSORS TO ASSIST REPAIR	New	180.00	0.00
Gross Labour Cost (\$)			4,050.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >