

Company Reg No: 201929175W

Chassis number: WBA3A16070NS37611

	Labour and painting		Amount
--	---------------------	--	--------

17

1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	800.00	\$ 1,200.00	✓
2	Spray painting on affected areas and panels	800.00	\$ 1,200.00	✓
3	Check wiring and lighting system		\$ 50.00	} NNX
4	Apply rust coating chemical on affected areas and panels		\$ 80.00	
5	Remove and reinstall RH rear door inner mechanism to new door	80.00	\$ 150.00	✓
6	Remove and reinstall RH rear fender inner trims, boards, roof lining, carpet and garnish to assist repair	150.00	\$ 350.00	✓
7	Remove and reinstall rear windscreen glass to assist repair	120.00	\$ 220.00	✓
8	Remove and reinstall rear bumper reverse sensors to assist repair	60.00	\$ 70.00	✓
9	Remove and replace rear undercarriage parts to assist repair		\$ 450.00	NNX
10	Test drive and adjust wheel alignment system		\$ 100.00	NNX
11	Remove and reinstall fuel tank, pipes, hoses and sensors to assist repair		\$ 180.00	NNX
			2010.00	
	Total		\$ 4,050.00	

Survey & Resurvey

21/2/2022

1520 hrs

Touin Mr

Lump sum repair

Repair days 6

Spare Parts: \$ 6,996.75
Special Nett: \$ 1,687.00
Labour: \$ 4,050.00

Total Amount: \$ 12,733.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts 4401.26

SN 297.00

Labour 2010.00

6708.26

@ 20% 1341.65

5366.60

LS 5350/2

Touin Mr

10/3/2021