

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001179/AGA3Q2**Date:** 13/07/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100505630
Claimant Vehicle No :	SMV4518C	Insured Vehicle No :	SLM9992S
Date of Loss:	01/02/2022	Nature of Claim:	TP
		Claim No:	2263062923SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV4518C	Engine No:	L15B5582115
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11332076
Reg. Date:	30/09/2020 (Man. Year: 2020)	Odometer:	6420 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,610.16	3,695.52	11,914.64	76.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,970.00	1,310.00	4,660.00	78.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,580.16	5,005.52	16,574.64	76.80
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	21,580.16	4,000.00	17,580.16	81.46
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		4,236.45		
Global Sum Settlement (S\$)		4,200.00		

INSPECTION

Date of Assignment:	05/02/2022	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	05/02/2022 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Cracked	3,984.60 FL	*2,335.00 FL
2	1		*HEADLAMP LOWER BRACKET LH	Cracked	52.00 FL	*52.00 FL
3	1		*FRONT BUMPER	Deformed	878.50 FL	*878.50 FL
4	1		*FRONT BUMPER LOWER LIP	Not Necessary	355.00 FL	*- FL
5	1		*FRONT BUMPER FOGLAMP LH	Not Necessary	327.70 FL	*- FL
6	1		*FRONT BUMPER FOGLAMP COVER LH	Deformed	69.00 FL	*69.00 FL
7	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	150.00 FL	*- FL
8	1		*FRONT BUMPER SIDE RETAINER	N/S Damaged	46.00 FL	*23.00 FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	321.00 FL	*- FL
10	1		*FRONT WIPER PANEL GARNISH	Not Necessary	374.40 FL	*- FL
11	1		*FRONT RESORNATOR BOX	Cracked	210.40 FL	*210.40 FL
12	1		*BONNET	Not Necessary	1,168.00 FL	*- FL
13	1		*FRONT FENDER LH	Buckled	748.80 FL	*586.00 FL
14	1		*FRONT FENDER INNER GARNISH LH	Not Necessary	85.00 FL	*- FL
15	1		*FRONT FENDER ARCD GARNISH LH	Cut	195.00 FL	*195.00 FL
16	1		*FRONT FENDER INNER COWLING LH	Torn	170.50 FL	*170.50 FL
17	1		*FRONT WHEEL RIM RH	Not Necessary	1,450.00 FL	*- FL
18	1		*FRONT ABS SENSOR	Not Necessary	295.00 FL	*- FL
19	1		*FRONT CROSSMEMBER	Not Necessary	1,365.00 FL	*- FL
20	1		*FRONT STEERING RACK & PINION	Not Necessary	1,750.00 FL	*- FL
21	1		*FRONT SHOCK ABSORBER RH	Not Necessary	586.50 FL	*- FL
22	1		*FRONT LOWER ARM RH	Not Necessary	474.70 FL	*- FL
23	1		*FRONT KNUCKLE ARM RH	Not Necessary	461.70 FL	*- FL
24	1		*FRONT KNUCKLE ARM INNER BEARING RH	Not Necessary	262.00 FL	*- FL
25	1		*FRONT WHEEL HUP RH	Not Necessary	379.40 FL	*- FL
26	1		*FRONT LINKAGE RH	Not Necessary	65.00 FL	*- FL
27	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
28	1		*SET FRONT BUMPER LOWER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
29	1		*SET FRONT WIPER PANEL GARNISH CLIP	Not Necessary	30.00 FS	*- FS
30	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS
31	1		*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
32	1		*SET FRONT FENDER INNER GARNISH CLIP RH	Not Necessary	50.00 FS	*- FS
33	1		*SET FRONT FENDER ARCED GARNISH CLIP LH	Necessary	50.00 FS	*20.00 FS
34	1		*SET FRONT FENDER INNER COLWING CLIP RH	Necessary	50.00 FS	*30.00 FS
35	1		*SIDE SKIRT CLIP RH	Not Necessary	80.00 FS	*- FS
36	1		*SET WHEEL CAP	Not Necessary	150.00 FS	*- FS
37	1		*FRONT WHEEL TYRE RH	Not Necessary	450.00 FS	*- FS
38	1		*FRONT WHEEL RIM RH	Not Necessary	1,500.00 FS	*- FS
39	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,855.20	4,599.40
- List Item Discount on L Items 20.00/20.00% (\$)	3,245.04	903.88
Total Parts (\$)	15,610.16	3,695.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVING AND REPLACING PARTS	New	1,800.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	600.00
3	TUFF COAT	New	250.00	80.00
4	WIRING CHECK	New	120.00	30.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	0.00
7	REMOVE AND REFIX POWER STEERING RACK AND PINION	New	350.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	0.00
9	RESET ABS LIGHT	New	350.00	0.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,970.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >