

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN		Ref:	CS3/LPC22001187/Urs3e2		
	300 BEACH ROAD SINGAPORE 1995		Date:	23/02/2022		
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XE 9595E	Veh. Inspected	l	SLA 3707C	
	Policy No.	Z21VC05007687	Coverage (\$)		0.00	
	Claim No.	21/21/21/VC05/024953	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		08/02/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ CLA180 (A)	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	WDD1179422N243588	Colour		YELLOW	
	Odometer	120374 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/40 R18	PIRELLI		6 mm	
	L/H Front Tyre	225/40 R18	PIRELLI		6 mm	
	R/H Rear Tyre	225/40 R18	PIRELLI		6 mm	
	L/H Rear Tyre	225/40 R18	PIRELLI		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information					
	Accident Date	07/02/2022	Inspect Date /	Time	08/02/2022 (11:11 AM)	
	Survey held at	FASTECH AUTO PTE LTD				
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22001187/Urs3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser