



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 390T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DENTED	1,245.50	855.30
1	SET FRONT BUMPER CLIPS	NECESSARY	65.00	50.00
1	FRONT BUMPER SPONGE	NOT NECESSARY	117.60	-
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	171.80	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	752.00	-
1	FRONT BUMPER LOWER GRILLE	DEFORMED / TORN	685.00	685.00
1	FRONT BUMPER FOG LAMP COVER RH	SCRATCHED	197.60	166.10
1	FRONT AIRCON PIPE	NOT NECESSARY	357.00	-
1	FRONT GRILLE	SCRATCHED	845.00	645.20
1	FRONT GRILLE EMBLEM	NOT NECESSARY	250.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	780.00	-
1	FRONT FENDER COWLING (GARNISH) RH	NOT NECESSARY	466.00	-
1	FRONT HEAD LAMP RH	SCRATCHED / CRACKED	862.40	862.40
	LESS 10% DISCOUNT		-	-326.40
			6,794.90	2,937.60
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER LOWER GRILLE CLIPS (SN)	NOT NECESSARY	65.00	-
1	SETS FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	60.00	-
			125.00	-
<u>LABOUR</u>				
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		50.00	20.00
	TO REMOVE & REFIX AIR CON,RE-FILL AIR CON GAS & TEST FOR LEAKAGES.	NOT NECESSARY	250.00	-
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		800.00	300.00
	REMOVE AND REFIX FENDER TRIM,GARNISH & ETCS.	NOT NECESSARY	60.00	-
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		600.00	400.00

Report Ref No. CS/AGI22001188/Uvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.	NOT NECESSARY	80.00	-
			1,840.00	720.00
GRAND TOTAL			8,759.90	3,657.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS/AGI22001188/Uvf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.