

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22001189/EPA3Q2**Date:** 18/01/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SNC8808C **Insured Vehicle No :** SLQ774T

Date of Loss: 05/02/2022 Nature of Claim: TP Claim No: MFL2022D0000637

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC8808C**
 Make & Model: BMW 520I, 2.0 (A) Engine No: 12085627B48B20A
 Reg. Date: 26/06/2019 (Man. Year: 2019) Chassis No: WBAJA12070WW34954
 Colour: White Odometer: 75598 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35 R19 Rear Tyre Size: 275/35 R19
 Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
 Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,479.45	3,798.60	1,680.85	30.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,629.00	4,624.00	1,005.00	17.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,108.45	8,422.60	2,685.85	24.18
+ GST 7.00/7.00% (S\$)	777.59	589.58	188.01	24.18
Nett Amount (S\$)	11,886.04	9,012.18	2,873.86	24.18
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,419.63		

INSPECTION

Date of Assignment: 08/02/2022

Date Inspected: 25/02/2022 Inspected At:

 Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby Performance
 Centre
 Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2022)
Parts:	143	BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC8808C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*TAILGATE ALUMINIUM	Dented	1,818.60 FS	*1,818.60 FS
3	1		*REAR BUMPER CARRIER	Not Necessary	582.55 FS	*- FS
4	1		*REAR BUMPER BOTTOM REINFORCEMENT	Broken	75.95 FS	*75.95 FS
5	1		*REAR BUMPER CENTRE GUIDE	Not Necessary	177.25 FS	*- FS
6	1		*REAR BUMPER TRIM STRIP	Not Necessary	119.40 FS	*- FS
7	1		*REAR BUMPER PANEL PRIMED (PD)	Dented	1,603.00 FS	*1,603.00 FS
8	1		*LETTERING 520I	Necessary	65.60 FS	*65.60 FS
9	1		*PLAQUE 82MM	Necessary	72.85 FS	*72.85 FS
10	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
11	10		*EXPANDING RIVET D=8MM	Necessary	11.00 FS	*11.00 FS
12	1		*UNDERBODY PANELLING REAR	Not Necessary	48.95 FS	*- FS
13	2		*DECUPING RING PDC TORQUE CONVERTER	Not Necessary	10.30 FS	*- FS
14	2		*ULTRASONIC SENSOR MINERALWEISS (WA96)	Not Necessary	742.40 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,479.45	3,798.60
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER ,BOOT LID INCLUDING TO KNOCK OUT DENTED AREA	New	2,550.00	1,700.00
2	TO RESPRAY REAR BUMPER AND BOOT LID	New	2,076.00	1,972.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	504.00
6	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
Gross Labour Cost (S\$)			5,629.00	4,624.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >