

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001190/VQY3N2**Date:** 28/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00066672100		
<b>Claimant Vehicle No :</b>	SJZ7257A	<b>Insured Vehicle No :</b>	SMG2552U		
Date of Loss:	22/01/2022	Nature of Claim:	TP	Claim No:	SNM22D200583/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJZ7257A</b>		
Make & Model:	HONDA FIT, 1.3 G (A)	Engine No:	L13A4221993
Reg. Date:	22/12/2010 (Man. Year: 2009)	Chassis No:	GE61202468
Colour:	Black	Odometer:	215820 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,830.00	1,970.40	2,859.60	59.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,360.00	600.00	30.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,790.00</b>	<b>3,330.40</b>	<b>3,459.60</b>	<b>50.95</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,650.00</b>		
<b>(\$\$)</b>	6,790.00	2,650.00	4,140.00	60.97
<b>+ GST 7.00/7.00% (\$\$)</b>	475.30	185.50	289.80	60.97
<b>Nett Amount (\$\$)</b>	<b>7,265.30</b>	<b>2,835.50</b>	<b>4,429.80</b>	<b>60.97</b>

**INSPECTION**

Date of Assignment:	08/02/2022	
Date Inspected:	10/02/2022 Inspected At:	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT Singapore 417800
Estimated Period of Repair:	5.0 days	

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Mar 2022)
<b>Parts:</b>	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJZ7257A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Repair	900.00 FL	*- FL
2	1		*FRONT DOOR OUTER HANDLE RH	Repair	110.00 FL	*- FL
3	1		*FRONT DOOR SIDE MIRROR RH	Jammed	350.00 FL	*350.00 FL
4	1		*FRONT DOOR SIDE MIRROR REAR COVER RH	Missing	100.00 FL	*100.00 FL
5	1		*FRONT DOOR SIDE MIRROR SIGNAL LAMP RH	Serviceable	80.00 FL	*- FL
6	1		*ROCKER PANEL RH (NPA)	Serviceable	0.00 FL	*- FL
7	1		*FRONT DOOR GLASS REGULATOR RH	Serviceable	380.00 FL	*- FL
8	1		*FRONT DOOR GLASS MOTOR RH	Serviceable	550.00 FL	*- FL
9	1		*FRONT FENDER RH	Dented	550.00 FL	*430.00 FL
10	1		*FRONT BUMPER	Cut	600.00 FL	*503.00 FL
11	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	70.00 FL	*70.00 FL
12	1		*FRONT HEADLAMP RH	Scratched	780.00 FL	*570.00 FL
13	1		*FRONT FENDER INNER SHIELD RH	Distorted	230.00 FL	*90.00 FL
14	1		*FRONT WHEEL RIM RH	Scratched	850.00 FS	*280.00 FS
15	1		*FRONT TYRE RH	Serviceable	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,770.00</b>	<b>2,393.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	940.00	422.60
<b>Total Parts (S\$)</b>	<b>4,830.00</b>	<b>1,970.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RESET POWER WINDOW	New	120.00	0.00
2	TO TRANSFER DOOR	New	80.00	0.00
3	TO CONDUCT COMPUTER WHEEL ALIGNMENT	New	80.00	60.00
4	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS	New	30.00	20.00
5	TO DISMANTLE AND REFIT FRONT UNDERCARRIAGE	New	220.00	0.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	800.00	650.00
7	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	30.00	30.00
8	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDINGOF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	600.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,960.00</b>	<b>1,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >