

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001194/BQY3E2**Date:** 19/05/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00143462100

**Claimant Vehicle
No :** SLM7171H**Insured Vehicle
No :** GBL5873C

Date of Loss: 16/01/2022

Nature of Claim: TP

Claim
No: SNM22D200432/C02/TANKLDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLM7171H**

Make & Model: LEXUS RX200T, 2.0 LUXURY S/R (A)

Engine No: 8ARW490441

Reg. Date: 03/03/2017 (Man. Year: 2017)

Chassis No: JTJBAMCA302022917

Colour: White

Odometer: 60242 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R20

Rear Tyre Size: 235/55 R20

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	53,770.65	34,541.90	19,228.75	35.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,000.00	3,290.00	5,710.00	63.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	62,770.65	37,831.90	24,938.75	39.73
Approved Total (Overridden) (S\$)		28,400.00		
(S\$)	62,770.65	28,400.00	34,370.65	54.76
+ GST 8.00/8.00% (S\$)	5,021.65	2,272.00	2,749.65	54.76
Nett Amount (S\$)	67,792.30	30,672.00	37,120.30	54.76

INSPECTION

Date of Assignment: 18/05/2023

Date Inspected: 09/02/2022

Inspected At:

Bifrost Auto (HQ)

24 Defu Lane 12

Singapore 539131

Estimated Period of Repair: 14.0 days

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2023)
Parts:	M1-SUV	LEXUS RX200T 2.0 LUXURY S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM7171H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,435.20 FL	*1,983.90 FL
2	1		*BONNET RH HINGE	Bent	172.80 FL	*157.80 FL
3	1		*BONNET LH HINGE	Bent	172.80 FL	*157.80 FL
4	1		*BONNET LOCK	Jammed	574.60 FL	*165.00 FL
5	1		*FRONT WIPER GARNISH	Broken	703.10 FL	*597.00 FL
6	1		*FRONT WINDSCREEN GLASS RUBBER MOULDING	Necessary	231.50 FL	*231.50 FL
7	1		*FRONT BUMPER	Broken	1,132.10 FL	*812.50 FL
8	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	125.40 FL	*97.20 FL
9	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	125.40 FL	*97.20 FL
10	1		*FRONT BUMPER LH SIDE LIP	No such part	100.70 FL	*- FL
11	1		*FRONT BUMPER LH FOG LAMP	Short Circuit	516.70 FL	*324.50 FL
12	1		*FRONT BUMPER LH FOG LAMP COVER	Broken	75.40 FL	*75.40 FL
13	1		*FRONT BUMPER LH FOG LAMP COVER CHROME	Broken	125.30 FL	*125.30 FL
14	1		*FRONT BUMPER LH DISTANCE SENSOR	Not Damaged	481.90 FL	*- FL
15	1		*FRONT BUMPER CENTRE UPPER RUBBER SEAL	Necessary	55.80 FL	*55.80 FL
16	1		*FRONT GRILLE	Broken	1,328.90 FL	*984.10 FL
17	1		*FRONT GRILLE EMBLEM	Necessary	477.90 FL	*78.00 FL
18	1		*FRONT GRILLE CHROME MOULDING	Necessary	594.70 FL	*130.00 FL
19	1		*LH HEADLAMP ASSY	Broken	7,268.70 FL	*7,159.20 FL
20	1		*LH HEADLAMP CONTROL UNIT	Not Necessary	1,354.50 FL	*- FL
21	1		*LH FRONT FENDER	Distorted	1,414.10 FL	*776.70 FL
22	1		*LH FRONT FENDER ARCH MOULDING	Broken	245.90 FL	*162.50 FL
23	1		*LH FRONT FENDER SPLASH SHIELD	Broken	502.60 FL	*328.00 FL
24	1		*LH FRONT FENDER UPPER COVER	Broken	170.80 FL	*170.80 FL
25	1		*LH FRONT FENDER INNER EXTENSION OUTER PANEL	Dented	831.20 FL	*831.20 FL
26	1		*ENGINE LOWER COVER	Not Damaged	161.80 FL	*- FL
27	1		*LH FRONT CHROME SPORT RIM	Cut	3,450.60 FL	*1,854.60 FL
28	1		*LH FRONT SHOCK ABSORBER	Bent	790.80 FL	*631.60 FL
29	1		*LH FRONT DRIVE SHAFT	Not Damaged	1,916.80 FL	*- FL
30	1		*LH FRONT LOWER ARM	Bent	782.20 FL	*732.10 FL
31	1		*LH FRONT KNUCKLE ARM	Dented	1,043.60 FL	*835.80 FL
32	1		*LH FRONT WHEEL BEARING WITH HUB	Jammed	835.60 FL	*158.80 FL
33	1		*LH FRONT TIE ROD END	Bent	156.80 FL	*80.00 FL
34	1		*STEERING RACK AND PINION	Not Damaged	2,441.40 FL	*- FL
35	1		*LH FRONT DOOR	Dented	1,352.50 FL	*1,069.30 FL
36	1		*LH FRONT DOOR UPPER HINGE	Bent	137.60 FL	*84.05 FL
37	1		*LH FRONT DOOR LOWER HINGE	Bent	137.60 FL	*84.05 FL
38	1		*LH FRONT DOOR INNER TRIM BOARD	Broken	4,383.90 FL	*2,600.00 FL
39	1		*LH FRONT DOOR PROTECTOR	Necessary	548.80 FL	*225.10 FL
40	1		*LH FRONT DOOR LOCK	Not	701.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Necessary		
41	8		*LH FRONT DOOR OUTER FRAME CHROME RIVETS	Necessary	64.00 FL	*30.00 FL
42	1		*LH FRONT DOOR WEATHERSTRIP	Necessary	282.60 FL	*140.00 FL
43	1		*LH FRONT DOOR GLASS	Not Necessary	934.10 FL	*- FL
44	1		*LH SIDE MIRROR ASSY	Broken	2,504.90 FL	*2,361.00 FL
45	1		*LH SIDE MIRROR COVER	Cut	198.20 FL	*150.00 FL
46	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
47	1		*SET FRONT GRILLE CLIPS	Necessary	65.00 FS	*30.00 FS
48	1		*SET LH FRONT FENDER SPLASH SHIELD CLIPS	Necessary	70.00 FS	*30.00 FS
49	1		*LH FRONT FENDER INNER EXTENSION OUTER PANEL JOINT SEALANT	Not Necessary	70.00 FS	*- FS
50	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
51	1		*FRONT WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*20.00 FS
52	1		*SET LH FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	85.00 FS	*30.00 FS
53	1		*BRAKE FLUID	Necessary	70.00 FS	*70.00 FS
54	1		*LH FRONT TYRE	Cut	650.00 FS	*300.00 FS
55	1		*RH HEADLAMP ASSY	Broken	7,268.70 FL	*7,159.20 FL
56	1		*LH FRONT FENDER BRACKET	Broken	115.00 FL	*115.00 FL
57	1		*LH TAILLAMP ASSY	Not Necessary	1,783.20 FL	*- FL
58	1		*LH REAR FENDER	Dented	1,706.40 FL	*972.40 FL
59	1		*LH REAR FENDER ARCH MOULDING	Broken	155.00 FL	*155.00 FL
60	1		*REAR BUMPER	Broken	1,093.20 FL	*995.00 FL
61	1		*REAR BUMPER LH BRACKET	Broken	123.40 FL	*123.40 FL
62	1		*FRONT WINDSCREEN GLASS	Broken	1,563.20 FL	*1,563.20 FL
63	1		*FRONT WINDSCREEN GLASS RUBBER SEAL	Necessary	387.00 FL	*130.00 FL
64	1		*FRONT WINDSCREEN GLASS SEALANT	Not Necessary	70.00 FS	*- FS
65	1		*FRONT WINDSCREEN GLASS INNER SEAL	Not Necessary	50.00 FS	*- FS
66	1		*FRONT WINDSCREEN GLASS ERP BRACKET	Necessary	26.00 FS	*26.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	59,594.50	38,317.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	5,823.85	3,775.10
Total Parts (\$\$)	53,770.65	34,541.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	2,000.00	1,400.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS PEARL WHITE	New	1,600.00	1,200.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	120.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	150.00	0.00
5	REMOVE AND REINSTALL FRONT WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	120.00
6	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	400.00	250.00
7	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	60.00
8	REMOVE AND REPLACE LH FRONT DOOR INNER MECHANISM TO ASSIST REPAIR	New	200.00	80.00
9	RESET AND DIAGNOSE CONTROL UNIT AND FAULT CODES	New	450.00	120.00
10	LABOUR	New	1,600.00	0.00
11	SPRAY PAINTING BONNET	New	1,400.00	0.00
12	REMOVE AND REPLACE FRONT WINDSCREEN GLASS AND SEALANTS	New	280.00	0.00
13	REMOVE AND REPLACE REAR INNER TRIMS, GARNISH, ROOF LINING, SEATS AND CARPET TO ASSIST REPAIR	New	400.00	0.00
14	REMOVE AND REINSTALL REAR BUMPER REVERSE SENSOR	New	100.00	60.00
Gross Labour Cost (\$)			9,000.00	3,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >