



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 9259G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT RH DOOR (CONSISTENT)	DENTED	2,120.00	2,120.00
1	FRONT RH DOOR LOCK (CONSISTENT)	NOT NECESSARY	398.00	-
1	FRONT RH DOOR WEATHERSTRIPE (CONSISTENT)	NECESSARY	280.00	280.00
1	FRONT RH DOOR CHROME MOULDING (CONSISTENT)	CUT	93.00	93.00
1	FRONT RH DOOR OUTER HANDLE (CONSISTENT)	TO REPAIR SEE LABOUR	385.00	-
1	REAR RH DOOR (CONSISTENT)	DENTED	2,175.00	2,175.00
1	REAR RH DOOR LOCK (CONSISTENT)	NOT NECESSARY	390.00	-
1	REAR RH DOOR WEATHERSTRIPE (CONSISTENT)	NECESSARY	285.00	285.00
1	REAR RH DOOR CHROME MOULDING (CONSISTENT)	CUT	98.00	98.00
1	ROCKER PANEL SIDE SKIRTING (CONSISTENT)	TO REPAIR SEE LABOUR	692.00	-
1	REAR RH WHEEL RIM (CONSISTENT)	NOT NECESSARY	1,250.00	-
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,680.00	-
1	REAR BUMPER SIDE HOLDER RH (CONSISTENT)	NOT NECESSARY	78.00	-
	LESS 10% DISCOUNT		-	-505.10
			9,924.00	4,545.90
<u>SPECIAL NETT ITEMS</u>				
1	ROCKER PANEL SIDE SKIRTING CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR RH TYRE (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			400.00	-
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT RH DOOR OUTER HANDLE, ROCKER PANEL SIDE SKIRTING AND REAR BUMPER.		1,000.00	600.00
	SPRAY PAINTING.		1,200.00	1,000.00
	WIRING.		50.00	30.00
	TO TRANSFER FRONT AND REAR DOOR FITTINGS.		300.00	200.00
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-

Report Ref No. CS/ASM22001196/Avy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE REVERSE SENSOR.	NOT NECESSARY	120.00	-
			2,820.00	1,830.00
GRAND TOTAL			13,144.00	6,375.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,100.00

Report Ref No. CS/ASM22001196/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.