

## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

## **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info			
ALLIANZ INSURANCE SINGAPORE PTE LTD	Cust No/Name	/Cycle & Carriage.Fulco Motor De		
79 ROBINSON ROAD #09-01	Reg No/Reg Date			
SINGAPORE 068897	Date In/Mileage			
TEL:67143369	Chassis No	VR7EFYHZRMJ542597		
TEL:0/143309	Engine No	10Q4DR0030181		
Contact No	Make/Model	CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13		
	Colour/Trim	WPP / GY		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	10-10-10-10	NAME OF THE PERSON OF THE PERS
F0000051	Credit	24/06/2022/ 09:38	OD	303 / Renemer		25421		
		Description of Good	s / Service	S	Qty	Unit Price	Disc%	Amount
TO REMOVE M JJMZ3139 Z NOTES	E & REPLA E & RE-IN 50	ACE RADIATOR ASSY & I NSTALL AC CONDENSER / COOLANT		PORT PANEL P UP AC GAS & COOLANT	4.00	26.00	0.00	180.00
			st	ima	te	)		
Confirm & a	ccepted b	у			Parts Labour Standard N Specialist	t Job		104. 0. 0. 180.
Authorized	signatory	and company stamp			Others(Lub,etc) Sundry Total(w/o GST)			284.0

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

## **ESTIMATE**

	Owner Name & Vehicle Info			
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897	Cust No/Name	/Cycle & Carriage.Fulco Motor De		
	Reg No/Reg Date Date In/Mileage	17/01/2022/ 6319		
TEL:67143369	Engine No	VR7EFYHZRMJ542597 10Q4DR0030181		
Contact No	Make/Model Colour/Trim	CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13 WPP / GY		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
0000051	Credit	26/05/2022/ 09:39	OD	303 / Renemer		25421		
0000031	Credit	Description of Good	s / Services		Qty	Unit Price	Disc%	Amount
C1610817	780	LH STEERING	ROD BALL	SP WC	1.00	195.00	0.00	195.0 650.0
C9677914		LHF DRIVE S	HAFT /	Call	1.00	650.00	0.00	620.0
C9816824		RH HEADLIGH	T ASSEMBL	2.12	1.00	620.00	0.00	67.0
C9802978		LH DOOR HAN	DLE /	MAC	1.00	67.00	0.00	10.0
C9822171	580	LH DOOR ADH	ESIVE TAP	1 VIN	1.00	10.00 207.00	0.00	207.0
C9818018	380	OIGTS/W U I	DOOR ENTR	0	1.00	545.00	0.00	545.0
C9675747		RADIATOR AS LH WINDOW L	sy /	7 . DA	1.00	492.00	0.00	492.0
C9830335	880	LH WINDOW L	IFTER ELE /	/ VIDA	1.00	492.00	0.00	472.0
NOTES								
SUPPLEME	NTARY IT		-	-	_			
			$\sim 12$	ima	$\mathcal{L}_{\mathcal{L}}$			
			2111	11/2/19	<u> ነ</u> ነተ <i>(ር</i>	1)	- 1	
			$\mathcal{D}$	111111110	11110	7		
				nes Of 7/5/-	/			
			$\int_{\Omega}$	11 Oc/				
			$\leq \nu$	m g			- 1	
				/ /				
				1/4/-			- 1	
				$\mathcal{V}//\mathcal{S}/\mathcal{I}$	22			
				C				
					Parts			2,786
Confirm 2	ccented	IV			Parts			
Confirm & a	accepted i	··y			Labour			
Confirm & a	accepted i	уу				Menu		0
Confirm & a	accepted i	yy			Labour Standard			0
Confirm & a	accepted i	ny			Labour	t Job		0.
Confirm & a	accepted b	)y			Labour Standard Specialis	t Job		0. 0. 0.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.