



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 831H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT O/S FENDER (N)	BENT	555.20	555.20
1	FRONT O/S FENDER INNER SHIELD (N)	CRACKED	194.60	194.60
1	O/S HEADLAMP (N)	MTG BROKEN	629.30	629.30
1	O/S HEADLAMP LOWER GARNISH (N)	BUCKLED	368.50	368.50
1	O/S HEADLAMP LOWER BRACKET (N)	SERVICEABLE	102.80	-
1	FRONT BUMPER FASCIA (N)	BENT	655.20	655.20
1	FRONT O/S BUMPER SIDE RETAINER (N)	DISTORTED	25.00	25.00
1	FRONT GRILLE (N)	MTG CRACKED	436.50	436.50
1	FRONT O/S WHEEL HUB CAP (N)	DENTED / CUT	145.90	145.90
	LESS 10% DISCOUNT		-311.30	-301.02
			2,801.70	2,709.18
<b><u>SPECIAL NETT ITEMS</u></b>				
1	O/S FENDER BODY LETTERING (SN)	NECESSARY	250.00	130.00
			250.00	130.00
<b><u>LABOUR</u></b>				
	TO PUTTY AND SPRAY REPLACED PARTS.		400.00	300.00
	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS.		400.00	360.00
			800.00	660.00
<b>GRAND TOTAL</b>			<b>3,851.70</b>	<b>3,499.18</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,800.00</b>

Report Ref No. CS/AGI22001212/Ktf3n2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.