

ASS. REC. BY:

REF:

AG2 / 22 001212 / Kt

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

14/3 21:00 @ 28000 Cashed

red: 1051.70;27%

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

F. Invs

Others

TOTAL

Report Format :

ump Sum / I.B.I: (\$

Veh No:

CABG 8314 Yr Regn: 05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

NIS

NV200

c.c

1461

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

95735

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VSKYBAM 207.0144992

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

5/2/22

Rear

R/Bal.

9

mm

L/Bal.

9

mm

D.O.I.

10/2/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rm

The U/C / Chassis frame / Body Structure affected due to collision.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLQ3549H
Accident Date : 05-Feb-2022

No. : 06534

Date : 08-Feb-2022

Our Ref : 022026 (AUTO & GEN) / CHAN

PAGE : 1

JA LAN TIONG PTE LTD
69 QUALITY ROAD
Singapore 618822

*NOT WITHIN
11hr @ 2800h
Repair After Rain
4 days*

ESTIMATED COST OF REPAIR FOR NISSAN NV200 GBG831H

1 pc Front o/s fender
1 pc Front o/s fender inner shield
1 pc O/s headlamp
1 pc O/s headlamp lower garnish
1 pc O/s headlamp lower bracket
1 pc Front bumper fascia
1 pc Front o/s bumper side retainer
1 pc Front grille
1 pc Front o/s wheel hub cap

CM	555.20	n	✓
my Br	194.60	n	✓
Br	629.30	n	✓
Br	368.50	n	✓
Br	102.80	n	✓
Br	655.20	n	✓
my CM	25.00	n	✓
my CM	436.50	n	✓
my CM	145.90	n	✓

3,113.00

Less 10% : 311.30

1 pc O/s fender body lettering

Mr 2,801.70 *1305h*
250.00 sn

To putty and spray replaced parts

400.00 *300h*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

400.00 *360h*

Total : S\$ 3,851.70

Singapore Dollars Three Thousand Eight Hundred
and Fifty One and Cents Seventy Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: