

ASS. REC. BY:

REF: AG2 / 22 001212 / KH

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Alan's

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: CBG 831H Yr Regn: 05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: NIS NV200 c.c. 1461

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 95735 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKYBAM 207.0144992

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Yokohama

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 5/2/22 D.O.I. 10/2/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>14/3</u>	<u>21 Rep & 28000 Cost</u>
	<u>red: 1051.70;27%</u>

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:	
Transportation:	
S - RS - SI	
Expenses	
Others	
TOTAL	

- Add Fee:
- : Site Insp (\$)
 - : Interview (\$)
 - : Tech Invs (\$)
 - : Weekend (\$)

Report Format :

ump Sum / I.B.I: (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
 Tel: 6453 8686 (3 Lines) Fax: 6459 6550
 Company Reg. No.: 201113667N
 GST Reg. No.: 201113667N

Vehicle Insured : SLQ3549H
 Accident Date : 05-Feb-2022

No. : 06534
 Date : 08-Feb-2022

Our Ref : 022026 (AUTO & GEN) / CHAN

PAGE : 1

JA LAN TIONG PTE LTD
 69 QUALITY ROAD
 Singapore 618822

*NOT WITHAW
 11km @ 2800h
 Recovery After Pain
 4 days*

ESTIMATED COST OF REPAIR FOR NISSAN NV200 GBG831H

1 pc	Front o/s fender	Bu	555.20	n	✓
1 pc	Front o/s fender inner shield	CM	194.60	n	✓
1 pc	O/s headlamp	My Bro	629.30	n	✓
1 pc	O/s headlamp lower garnish	Bu	368.50	n	✓
1 pc	O/s headlamp lower bracket	Su	102.80	n	✓
1 pc	Front bumper fascia	Bu	655.20	n	✓
1 pc	Front o/s bumper side retainer	DIT	25.00	n	✓
1 pc	Front grille	My CM	436.50	n	✓
1 pc	Front o/s wheel hub cap	Pellwa	145.90	n	✓
			3,113.00		
		Less 10% :	311.30		

1 pc O/s fender body lettering

Me 2,801.70 *130sn*
 250.00 *sn?*

To putty and spray replaced parts

400.00 *3000*

To remove, cut-out damaged parts,
 panel beating, welding, align,
 refix and to renew above parts

400.00 *3600*

Total : S\$ 3,851.70

Singapore Dollars Three Thousand Eight Hundred
 and Fifty One and Cents Seventy Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: