



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 339Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, OUTER MIRROR, RH (DISC 25%)	MISSING	89.50	67.13
1	MIRROR ASSY, OUTER REAR VIEW, RH (DISC 10%)	BROKEN	1,373.50	1,236.15
1	PANEL SUB-ASSY, FRONT DOOR RH	NOT NECESSARY	1,249.60	-
1	STICKER DECAL STRIDES (DOOR)	NOT NECESSARY	60.00	-
1	PANEL SUB-ASSY, REAR DOOR, RH	NOT NECESSARY	1,243.90	-
1	PANEL SUB-ASSY, FENDER REAR RH	NOT NECESSARY	824.80	-
			4,841.30	1,303.28
LABOUR				
	PANEL BEATING & BODY WORK.		507.00	80.00
	SPRAY PAINT.		1,314.00	50.00
	TO REMOVE AND REFIX WING MIRROR.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TOWING CHARGE.	NOT NECESSARY	56.00	-
			2,237.00	150.00
GRAND TOTAL			7,078.30	1,453.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS/AIS22001213/Evf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.